ASS. REC. BY: | REF: CFI MSG M014371/ U9f3c Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

From (Person): Christine Wong of MSIG Date/Time: 14/8/19 @ 4.30pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 3863E Insured: SLT 3947B

at Workshop m/s Liu's Brother Tel: 67411730

of 1 Kaki Bukit Ave 6 # 01-01

Policy No: 29114756 Claim No: 598364

Sum Insured: Excess:

Make of Veh: D.O.A. 28/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 19.8.19 Person Contacted: Susan Vehicle IN / OUT

Date/Time	Action/Instruction
	Estimate ✓
	GBJ 3863E - x
	SLT 3947B - x
16/9/19	L/S @ 3000 4 day. Confirmed with Susan. ✓
	(Fed @ 2815.60, 48%)

MSIG

MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Liu's Bro

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	✓

Vehicle Details:

Vehicle Reg No	GBJ 3863E
Make	Nissan
Model	NV 350
Passenger capacity	02
Paint colour & code	Silver
Paint type	

Vehicle Extras:

In-built camera	Yes / No
Modification	Yes / No

Vehicle Data:

Odometer reading	12576 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Condition:	Seviceable Yes / No
Handbrake	
Footbrake	
Steering	
Body	
Paint	

Tyre Condition:

	Tread mm	Size	Condition
Front right	4	Dunlop 195 / R15	
Front left	4	"	
Rear left	4	"	
Rear right	4	"	

General Data:

Date of accident	28 - 06 - 19
Date of inspection	04 - 07 - 19
Date of assignment	03 - 07 - 19
Inspection location	Liu's brother

Painting Process:

Prepare off vehicle	
Painting off vehicle	
Neither (default)	

Cost Details:

	Repairer	Adjuster
Parts		
Supplementary		
Miscellaneous		
Body Labour		
Paint labour		
Paint material		
TOTAL		
Towing		
Excess		
Total less excess		
Estimated days for repair		

Body Panel Repair:

Panel repair calculator used
Yes / No

RECEIVED 18 SEP 2019

Remarks:

Lump / Global Sum

Reason(s) Margin Repair / Fast-line

Others:

Repair Authorised
Date:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019		14 Aug 2019 16:30 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**GRAB RENTALS PTE LTD**, Co. Reg. No.: 201617200G		
Main Claimant:	**GOLDBELL LEASING PTE LTD**, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	**GBJ3863E**	Date of Loss:	28/06/2019 07:00 - :59 [**2** Months and **24** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 598364	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	**SLT3947B**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)** Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Christina Wong** - 6643 1311]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 15/08/2019]		
Driver/Custodian (Insured):	TAI MUN HONG () , NRIC: S6921476B, Tel: +6594315523 Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: grab. Liab: dispute. TP agree on SJE - assign Autoprobe Consultants. Contact: Susan @ 6741 1730		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____

Date : _____

Policy No : _____

Claim No : _____

Insured Vehicle No : SLT3947B

TP Vehicle No : GBJ 3863E

Make & Model : Nissan NV350

Date of Accident : 28-06-19

Place of Survey : Liu's brother

Date of Survey : 04-07-19

Point of Impact / Damages :
Front Left

Recommended Reserve :

Repairer's Estimate : $ 5815.60

Interim Adjustment : $ 4647.30

Check Items : $ –



Proposed : Part by Part / Lump Sum Repair $3700/-

Excess : $ –

Estimate Repair Period : ~~95~~ days 4

Pre-accident Market Value (for total loss consideration) : $ 69900/-

COE / PARF to owner : $ 24589/-

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : $_____
(Authorised / Revert)

☑ TP Claim
(Without Prejudice)

Vehicle No. GBJ 3863E

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 04-07-19.

MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
Tel 6220 9644, Fax 6225 6371
www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

Attn: Christina Wong

Date: 05 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLT3947B		
TP Vehicle No	: GBJ3863E	Accident Date	: 28/06/2019
Make	: NISSAN NV350	Assignment Date	: 03/07/2019
Date of Inspection	: 04/07/2019	Est. Duration of Repair	: 5.00
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (KAKI BUKIT) (HQ) BLK 1 KAKI BT AVE 6 #01-01 AUTO BAY @ KAKI BT SINGAPORE 417883, KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages Front left portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	5,815.60
Revised Amount	:S$	4,647.30
Check Items (Estimated)	:S$	0.00
Total	:S$	
Lump Sum Repair	:S$	3,700.00

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	69900.00
COE / PARF Rebate	:S$	24589.00
Salvage Value	:S$	
Margin for Repair	:S$	

Remarks

(x) The vehicle is economical/~~not economical~~ for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No.:	GBJ3863E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25424945A
Chassis No.:	JN1MC2E26Z0009332
Maximum Power Output:	-
Open Market Value:	$25,062.00
Original Registration Date:	04 Apr 2019
First Registration Date:	04 Apr 2019
Transfer Count:	0
Actual ARF Paid:	$1,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	$25,233.00
COE Rebate Amount:	$24,080.00
Total Rebate Amount:	**$24,080.00**

The information contained herein is correct as at 18 Sep 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	GBJ3863E
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	NISSAN
Vehicle Model :	NV350 PANEL VAN 2.5 5MT 5DR
Chassis No. :	JN1MC2E26Z0009332
Propellant :	Diesel
Engine No. :	YD25424945A
Engine Capacity :	2488 cc
Maximum Power Output :	-
Maximum Laden Weight :	3300 kg
Unladen Weight :	1780 kg
Year Of Manufacture :	2017
Original Registration Date :	04 Apr 2019
Lifespan Expiry Date :	03 Apr 2039
COE Category :	C - Goods Vehicle & Bus
PQP Paid :	$25,233.00
COE Expiry Date :	03 Apr 2029
Road Tax Expiry Date :	03 Oct 2019
Inspection Due Date :	03 Apr 2020
Intended Transfer Date :	18 Sep 2019
CO2 Emission :	232.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	0.142000 (g/km)
HC Emission :	0.007500 (g/km)
NOx Emission :	0.072000 (g/km)
PM Emission :	0.000000 (mg/km)

The current road tax expiry is 03 Oct 2019. You may renew the road tax from 04 Jul 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 03 Oct 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 04 Oct 2019 to 03 Apr 2020)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			**25.00**

Amount Payable (From 04 Oct 2019 to 03 Oct 2020)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			**25.00**

Message

This vehicle has a road tax Over Payment of $56.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK Print

LIU'S BROTHER AUTO ENGINEERING WORKSHOP
No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: GBJ3863E190628

Estimate

Customer

Name: MSIG Insurance (Singapore) Pte Ltd
Address: Motor Claims Department
4 Shenton Way #21-01
SGX Centre 2 Singapore 068807

Date: 03-07-19
Vehicle No: GBJ3863E
Model/Make: Nissan NV350
Panel Van 2.5 5MT

Item No.	Descriptions Of Parts	Original Quotation / Estimation		Revised Quotation / Cost Of Repair
	Next item			
1	Front Bumper ~~cracked~~ Dist/Toin	$ 514.70	N	✓
2	Bumper Clips 1 set / necc	$ 48.00	~~N~~	✓ 30
3	Head Lamp ~~02~~ pcs (@ S$393.80 N) Left side NSSCR	$ ~~787.60~~ 394.80	N	IPC
4	Front Lh Bumper Bracket 01 ~~cracked~~ NN	$ 147.00	N	X
5	Fog Lamp Garnish X NN	$ 107.80	N	X
6	Wheel Half-Cab / ~~Gouged~~ gouged	$ 220.00	SN	1205.N
7	Step Garnish Outer ~~cracked~~ DC	$ 56.40	N	✓
8	Door / ~~Deformed~~ Bodyw/Sel	$ 1,015.50	N	✓
9	Door Weatherstrip / ~~Torn~~ NN	$ 88.00	N	✓
10	Door Lock X NN	$ 166.70	N	X
	Door Inner Trim Board ✓ ~~cracked~~ CNC	$ 481.70	N	✓
	Door Hinge 02 pcs (@ S$65.10 N) / ~~Bent~~ Bel	$ 122.20	N	✓
	To check all wiring & electrical component for proper function	$ ~~80.00~~	~~50~~	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs	$ ~~1,000.00~~	~~700~~	520
	To putty & spray painting & including touch up paint on accident affected	$ ~~800.00~~	600	✓
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	$ ~~80.00~~	50	✓
	To remove, replace and transfer door panel, fitting and mechanisms	$ ~~100.00~~	60	✓

102

Total Parts & Labour of estimate for damaged vehicle	$ 5,815.60
Total amount in Lump Sum Basis for repaired vehicle	

SDLS:

Liu's Brother Auto Engineering Workshop

M/s Liu's Brother Auto Engrg Wks

P - 2702.30
102
P - 2432.07
S.N - 120.00
L - 1250.00
3802.07
202
3041

~~05~~ days
04-07-19 @ 1000 hrs
Victor_Seng@sg.msig-asia.com
8774 7011
L/S After paint.

L/S $3000
4 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019		14 Aug 2019 16:30 Edit Adj Rpt	**S$3,000.00** Edit Estimates	**S$3,000.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	**GRAB RENTALS PTE LTD**, Co. Reg. No.: 201617200G		
Main Claimant:	**GOLDBELL LEASING PTE LTD**, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	**GBJ3863E**	Date of Loss:	28/06/2019 07:00 - :59 [**2** Months and **24** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 598364	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	**SLT3947B**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)** Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Christina Wong** - 6643 1311]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [**Imm.Advice** due 15/08/2019]		
Driver/Custodian (Insured):	TAI MUN HONG () , NRIC: S6921476B, Tel: +6594315523 Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: grab. Liab: dispute. TP agree on SJE - assign Autoprobe Consultants. Contact: Susan @ 6741 1730		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBJ3863E (598364)**
[SLT3947B]
TP
GOLDBELL LEASING PTE LTD
Jun 28 2019 7:00AM
[GRAB RENTALS PTE LTD]
Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/07/19 11:07	**Accident Statement** From:SC - Reg. No: SLT3947B, Claimant: GRAB RENTALS PTE LTD	i	Load HTM	
2	03/07/19 11:07	**Addendum Sheet** From:SC - Reg. No: SLT3947B, Claimant: GRAB RENTALS PTE LTD	i	Load JPG	☑
3	03/07/19 11:07	**Accident Statement Addm. #1** From:SC - Reg. No: SLT3947B, Claimant: GRAB RENTALS PTE LTD	i	Load HTM	
No	Finalized On	**MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)**		**Thumbnail**	**Print**
1	05/07/19 10:36	**Adjuster Immediate Advice**	i	Load HTM	

Photos/Images — 3 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
2	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
3	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
4	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
5	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
6	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
7	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
8	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
9	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
10	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
11	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
12	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
13	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
14	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
15	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
16	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
17	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
18	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
19	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
20	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
21	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
22	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
23	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
24	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
25	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
26	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
27	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
28	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
29	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
30	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
31	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
32	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
33	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
34	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
35	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
36	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
37	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
38	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
39	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
40	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
41	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
42	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
43	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
44	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
45	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
46	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
47	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
48	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
49	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑
50	05/07/19 00:05	**SURVEY PHOTO**	i	Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/07/19 11:07	**TP GBJ3863E E-REPORT** From:SC - Reg. No: SLT3947B, Claimant: GRAB RENTALS PTE LTD	i	Load PDF	
2	03/07/19 11:07	**PRI** From:SC - Reg. No: SLT3947B, Claimant: GRAB RENTALS PTE LTD	i	Load PDF	
3	03/07/19 12:43	**Agree on SJE**	i	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	05/07/19 11:16	**Preliminary Loss Advise**	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014371/UQF3E2
Date: 20/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756		
Claimant Vehicle No :	GBJ3863E	**Insured Vehicle No :**	SLT3947B		
Date of Loss:	28/06/2019	Nature of Claim:	TP	Claim No:	598364

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**GBJ3863E**		
Make & Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Engine No:	YD25424945A
Reg. Date:	04/04/2019 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0009332
Colour:	Silver	Odometer:	12576 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,755.60	2,557.47	1,198.13	31.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,250.00	810.00	39.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**5,815.60**	**3,807.47**	**2,008.13**	**34.53**
Approved Total (Overridden) (S$)		**3,000.00**		
(S$)	5,815.60	3,000.00	2,815.60	48.41
+ GST 7.00/7.00% (S$)	407.09	210.00	197.09	48.41
Nett Amount (S$)	**6,222.69**	**3,210.00**	**3,012.69**	**48.41**

INSPECTION

Date of Assignment:	14/08/2019		
Date Inspected:	04/07/2019	Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 19 Sep 2019)
Parts:	N/A	NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3863E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***FRONT BUMPER**	Distorted / Torn	514.70 F	*514.70 FN
2	1		***SET FRONT BUMPER CLIPS**	Necessary	48.00 F	*30.00 FN
3	1		***FRONT HEAD LAMP**	N/S Scratched	787.60 F	*399.80 FN
4	1		***FRONT LH BUMPER BRACKET**	Not Necessary	147.00 F	*- FN
5	1		***FRONT LH FOG LAMP GARNISH**	Not Necessary	107.80 F	*- FN
6	1		***FRONT LH WHEEL HALF-CAB**	Grazed	220.00 FS	*120.00 FS
7	1		***FRONT LH STEP GARNISH OUTER**	Deformed	56.40 F	*56.40 FN
8	1		***FRONT LH DOOR**	Badly Dented / Bent	1,015.50 F	*1,015.50 FN
9	1		***FRONT LH DOOR WEATHERSTRIP**	Twisted	88.00 F	*88.00 FN
10	1		***FRONT LH DOOR LOCK**	Not Necessary	166.70 F	*- FN
11	1		***FRONT LH DOOR INNER TRIM BOARD**	Cracked	481.70 F	*481.70 FN
12	2		***FRONT LH DOOR HINGE**	Bent	122.20 F	*122.20 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S$)	**3,755.60**	**2,828.30**
- Nett Item Discount on N Items 0.00/10.00% (S$)	0.00	270.83
Total Parts (S$)	**3,755.60**	**2,557.47**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION**	New	80.00	20.00
2	**LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS**	New	1,000.00	520.00
3	**TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED**	New	800.00	600.00
4	**TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA**	New	80.00	50.00
5	**TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS**	New	100.00	60.00
		Gross Labour Cost (S$)	**2,060.00**	**1,250.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >