...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	**S$437.82** Edit Estimates	**S$437.82** View Rpt		**Pending for Survey Report** Cancel Case

Main	Reference	Claim Details	Documents	Show All

CLAIM SUBFOLDER DETAILS	**[Created by adjuster]**
Insured:	**UNITED SCIENTIFIC EQUIPMENT PTE LTD**, Co. Reg. No.: A198702125K
Main Claimant:	**GRAB RENTALS PTE LTD**, Co. Reg. No.: 201617200G

Vehicle Reg. No.:	**SLN155X**	Date of Loss:	08/08/2019 19:00 - :59 [**27** Months and **19** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 2677876371SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	**GBF5607L**	Policy No. (Claimant):	A29114756MKF
		Excess:	

Repairer:	**Esteem Performance Pte Ltd (HQ)** Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **MdNoor, Norsiah**] Norsiah.MdNoor@aig.com
Claimant's Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... [**Final Rpt** due 28/08/2019]

ASSOCIATED MAIL RECEIVED   View All   Compose Case Mail

- AIG_SG_EXPRESS (06/08/2020): **Alert - Adj Mandate Approved (S$552.87) - SLN155X - Claim Handler: MdNoor, Norsi...**

ALL ASSOCIATED TASKS   View All   Search Tasks   Create New Task   Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

*SLN155X (2677876371SG)
[GBF5607L]
TP
GRAB RENTALS PTE LTD
Aug 8 2019 7:00PM
[UNITED SCIENTIFIC EQUIPMENT PTE LTD]
Esteem Performance Pte Ltd

| Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio | | **View** | View in Browser ⌄ |

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		**Thumbnail**	**Print**
1	(Draft)	**Third Party Express Settlement – Payment Breakdown**	ⓘ	Edit	

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		**Thumbnail**	**Print**
1	03/05/20 17:07	**Adjuster Immediate Advice**	ⓘ	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		**Thumbnail**	**Print**
1	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
2	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
3	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
4	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
5	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
6	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
7	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
8	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
9	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
10	03/05/20 17:20	**General View**	ⓘ	Load JPG	☑
11	03/05/20 17:21	**Reinspection Photo**	ⓘ	Load JPG	☑
12	03/05/20 17:21	**Reinspection Photo**	ⓘ	Load JPG	☑

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		**Thumbnail**	**Print**
1	19/08/19 15:19	**EMAIL FROM AIG DD 19082019**	ⓘ	Load PDF	
2	19/08/19 15:19	**TP EST & GIA REPORT**	ⓘ	Load PDF	
3	15/11/19 13:26	**EMAIL TO OI**	ⓘ	Load PDF	
4	03/05/20 16:59	**LOD, FINAL REPAIR BILL, RENTAL AGREEMENT, ATA & LTA SEARCH**	ⓘ	Load PDF	
5	03/05/20 17:15	**TP ESTIMATE- MARKED- FINAL**	ⓘ	Load PDF	
6	03/05/20 17:15	**FINALISED ESTIMATE**	ⓘ	Load PDF	
7	25/08/20 10:26	**Authorisation to Act**	ⓘ	Load PDF	
8	25/08/20 10:26	**LETTER TO OI**	ⓘ	Load PDF	
9	25/08/20 10:26	**LOD**	ⓘ	Load PDF	
10	25/08/20 10:26	**LTA SEARCH**	ⓘ	Load PDF	
11	25/08/20 10:26	**Release Voucher**	ⓘ	Load PDF	
12	25/08/20 10:26	**RENTAL AGREEMENT**	ⓘ	Load PDF	
13	25/08/20 10:26	**WORKSHOP INVOICE**	ⓘ	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		**Thumbnail**	**Print**
1	20/08/19 16:23	**OI GIA REPORT**	ⓘ	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR   **TEAM _____**

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	GBF5607L (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID CVT (A)
	SLN155X (TP veh)		
Date of Accident:	08/08/2019		

Global Sum Settlement	:	[ ] Yes	[X] No	
Repair Estimate	: $	5,152.61		
Final Repair Cost	: $	468.47		
Loss of Use	: $		days at $0.00 per day	
Rental (if any)	: $	76.95	1 days	
LTA / GIA Search Fee	: $	7.45		
Others:	: $			
	: $			
Final Settlement Sum	: $	552.87		

Is Third Party Workshop GIA Registered?	[ ] YES [X] NO (Kindly indicate below)
A) For **Non GIA Registered Workshop:**	Agreed Liability _____100_____(%)
B) For **GIA Registered Workshop:**	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: _____(%)	Assessed Liability (*):_____(%)
Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	_____
	_____

Payment Instruction: Payee's Breakdown		
1)	Esteem Performance Pte Ltd	: $ 552.87
2)		: $
3)		: $
4)		: $

NUR SHAQILAH BTE ABDOL WAHAB   25 Aug 2020
_____   _____
LKK Auto Consultants Pte Ltd   Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CC4/AIG19014417/KKA3S2
Date:	25/08/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLN155X	**Insured Vehicle No :**	GBF5607L
Date of Loss:	08/08/2019	Nature of Claim:	TP　　Claim No:　2677876371SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SLN155X**		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS039295
Reg. Date:	20/04/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU903556174
Colour:	Metallic Silver	Odometer:	299717 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,850.93	407.82	3,443.11	89.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	964.59	30.00	934.59	96.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**4,815.52**	**437.82**	**4,377.70**	**90.91**
+ GST 7.00/7.00% (S$)	337.09	30.65	306.44	90.91
Nett Amount (S$)	**5,152.61**	**468.47**	**4,684.14**	**90.91**
+ Car Rental (1.0 x S$76.95/day) (S$)		76.95		
+ Doc/Search Fee (S$)		7.45		
Nett Liability (S$)		**552.87**		

INSPECTION

Date of Assignment:	19/08/2019		
Date Inspected:	08/10/2019	Inspected At:	385 Sin Ming Drive Singapore 575718
			Repairer: Esteem Performance Pte Ltd
Estimated Period of Repair:	1.0 days		

Adjuster:	KENNETH KONG	**Manager:**	Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	497.50 FL	*- FL
2	1		*REAR COVER BUMPER	Dented / Cut	582.60 FL	*582.60 FL
3	1		*REAR BUMPER COVER	Serviceable	27.50 FL	*- FL
4	1		*LEFT RETAINER	Serviceable	112.70 FL	*- FL
5	1		*RIGHT RETAINER	Serviceable	112.70 FL	*- FL
6	1		*L/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
7	1		*R/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
8	1		*REAR BUMPER REINF	Repair	398.90 FL	*- FL
9	1		*BOOT / T-GATE MOULDING	Serviceable	782.50 FL	*- FL
10	1		*REAR MANUFACT BADGE	Not Necessary	61.70 FL	*- FL
11	1		*REAR SPOILER	Serviceable	1,567.83 FL	*- FL
12	1		*RR BUMPER CLIP	Not Necessary	40.00 FL	*- FL
13	1		*LH REAR BUMPER UNDER COVER	Serviceable	187.60 FL	*- FL
14	1		*RH REAR BUMPER UNDER COVER	Serviceable	187.60 FL	*- FL
15	1		*RR BUMPER UNDER COVER CLIP	Serviceable	14.00 FL	*- FL
16	1		*WORDING PRIUS	Not Necessary	51.90 FL	*- FL
17	1		*WORDING HYBRID	Not Necessary	55.47 FL	*- FL
18	1		*REAR NO PLATE REAR NO PLATE	Serviceable	45.00 FS	*- FS
19	1		*REVERSE SENSOR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
20	1		*R&R REVERSE SENSOR	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**5,344.90**	**582.60**
- List Item Discount on L Items 30.00/30.00% (S$)	1,493.97	174.78
Total Parts (S$)	**3,850.93**	**407.82**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**TOTAL OF LABOUR.**	New	475.00	30.00
2	**PAINT WORK: LABOUR COST.**	New	360.00	0.00
3	**PAINT WORK: MATERIAL COST.**	New	129.59	0.00
	Gross Labour Cost (S$)		**964.59**	**30.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >