CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1001E (Supplementary) DATE : 26.08.2019

MAKE : TEL : 6542 5119

MODEL : HYUNDAI i40 FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Duct broken			$ 134.60 ✓
	Air Duct Hose 4H			$ 351.00 ✗
	Horn Unit (LH/RH) Bt/Dm		$ 73.80	$ 147.60 ✓
	SUB TOTAL		282.20	$ 633.20
	LESS ~~20%~~ 25%			$ 126.64
	DISCOUNTED TOTAL		211.65	$ 506.56
	Wheel alignment			80.00 NM ~~60.00~~
	Dyan			
	& KK Auto			
			498 17.25	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.