15/5/2010

CC6/CTI19014841/Aha3n2

LKK: (SUN - 14/10)
IDAC:

INS. CASE OWNER:

ASSIGNMENT

Surveyor: ADRIAN DOI: 22/08/2019 Date / Time: 22/08/2019

Registered in Merimen: —

Pre-assign / CCU / FTE

Insured Vehicle No. : YN 3486S Claim No. : SNM19D2039333C02/6 (OCK/AT)

Name of Insured : SI Marine Engineering P/L Policy No. :

Insured Tel No. : HP: Make / Model :

Excess Sec II :S$ D.O.A : 31/07/2019 12:15 Place of Accident : ALONG PAYA LEBAR RD TURNING RIGHT

Is driver the owner? (NO) Nature of Accident : INTO PIE

If NO, Driver Name / Age : THIYAGARAJAN BHAGAHSING OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SLR 9702L → → →

INSRS:
WSP: PEOPLE'S
Tel : VEHICLE
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
	PA 8627U - NA/CTI19013422/r3; DOA:31/7/19 YN 3486S - CC6/AIG14012216/Asa3q2; DOA:29/6/14
05/11	- NO OI GIA REPORT IN YET OI GIA Report in.
05/11/19	- FILE REVIEWED. OLD REMK. ENDED TP. SEND LETTER & EMAIL TO OI TO NOTIFY TP CLAIM & ACD ISSUES.
08/11/19	- FINALISED - SEND PA TO OI. TYPE REPORT WHILE PENDING TP LOD - REPORT DONE - TP LOD IN BY EMAIL
16/12/19	- SEEK MANDATE APPROVAL TO OI - OI APPROVED MANDATE. SEND LOF OFFER. - TP ACCEPTED OFFER. - ALL DOCS IN ORDER.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	15/10/2019
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	05/11/19 - VIC

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:	✓	
Authorisation To Act:		
Release Voucher:	✓	
Final Repair Bill:	✓	
Car Rental Invoice:		
Towing Invoice		
LTA / GIA :	✓	
Medical Bill:		
PIR:		
Mandate/Reject Instruction:	✓	
LOD	✓	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: 08/11/19 Sent By: VIC

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: L/S S$ 3,450.00 (3 days) Reduction: 6.5 % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 16/12/19 Confirm with APPLE Email ✓ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia :

Repair Cost: (W/OGST) S$ 3,691.50 OLD REMK. ENDED TP

Loss of Rental (LOR): S$ — (days)

Loss of Use (LOU): S$ 180.00 ($60 x 3 days)

Loss of Income (LOI): S$ — ($ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S$ 7.45

Medical: S$ —

Disbursement: S$ — (e.g. Tow/ Independent)

Legal Cost S$ —

Total: S$ 3,878.95 **Global Sum S$:** —

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: @ 100.00

4) RA fee → $2.54

Email ☐ Call ☐

FINAL PAYMENT Date/Time: Confirm with:

Payee 1:	S$ 3,878.95	Name 1:	PEOPLE'S VEHICLE RECOVERY SERVICE
Payee 2: (Strike if N.A.)	S$ —	Name 2:	—
Payee 3: (Strike if N.A.)	S$ —	Name 3:	—

ASS'D REC. BY: | REF:

Adrian

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR9702L Yr Regn: 2008 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz C200 c.c 1796

Colour Grey. A/C: Insured / Std / NI / NA

Sp.Reading 139613 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2040412A150351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17.

R: 225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	22/08/19

Survey held at People.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Chian. COE Expiry : 29/02/28.
	Ho $3,450.00
	CR50: $6,340.00 (65%)
	MV :
	PV :
	Nett:

Date/Time, File Pass to?	Date/Time, File Return to?
1)	2)
3)	4)
5)	6)
Preli. Report:	
Final Report:	

Part Prices Check:

IN	OUT

Survey Fee: Date:

Basic & Add.

__ S + RS, __ SI

Photos

Others

TOTAL

LAK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 08.11.2019

Your ref: TBA
Our ref: CC6/CTI19014841/Aha3

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. **SLR 9702L**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.08.2019 at the premises of M/s PEOPLE'S VEHICLE RECOVERY SERVICE and have the following to report:-

Workshop Estimate Amount	: S$	9,790.00
Revised Estimate Amount	: S$	4,351.20
"Check" Items Amount	: S$	-
Market Value	: S$	-
LTA Reimbursement Value	: S$	-
Nett Value	: S$	-

Description of Damage:
The vehicle sustained damages at the Rear Portion

Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 3 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
Tel No. : 67433246 / 67438552 Fax No. : 67430013
E-Mail : peoplevehicle@gmail.com
Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

CHINA TAI PING INSURANCE (S) PTE LTD
105 CECIL STREET #19-00
THE OCTAGON (S) 069534

Vic

Attention : Motor Claim Department
Contact : 6389 6111 Fax No. : 6222 1033

Estimate : ES19024

Date : 22/08/2019
Vehicle Num. : SLR 9702 L
Make/Model : MERCEDES BENZ C200
Chassis/Eng# :
Accident Date : 30/07/2019
Claim No. : TT 354-19
Reference : YN 3486 S
Policy No. : CHINA DMPCSN3012631800
WDD2040412A150351

S/N	Quantity	Particular	Unit Price	Amount S$
		NETT ITEMS :		
1.	1	BUMPER REAR Del d		1,345.00
2.	1	BUMPER CENTRE MOUDLING REAR New		175.00
3.	2	BUMPER SIDE MOULDING REAR	110.00	220.00
4.	2	BUMPER SIDE RETAINER REAR New	75.00	150.00
5.	1	BUMPER REINFORCEMENT REAR * Bent.		650.00
6.	1	BOOTLID Repair		1,850.00
7.	1	BOOTLID INNER LOCK New		285.00
8.	1	BOOTLID LOGO New		85.00
9.	1	C 200 EMBLEM		75.00
10.	1	KOMPRESSOR EBMBLEM New		105.00
11.	1	BOOT HANDLE MOULDING New		195.00
12.	2	TAIL LAMP New	560.00	1,120.00
13.	1	END PANEL REAR Repair		1,205.00
14.	4	REVERSE SENSOR Dmgd 2 pieces.	185.00	~~740.00~~ 370.
		Nett Total S$:		8,200.00
		10.00% Discount S$:		820.00
				7,380.00
		LABOUR :		
		REMOVE & REPLACE ACCIDENT DAMAGED PARTS		~~1,400.00~~ 650

CONTINUE /...

Rear Bumper Centre Guide Cracked 185

Tailligh lower Bracket x02 Cracked 54x2=108

3468
3121.20

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
Tel No. : 67433246 / 67438552 Fax No. : 67430013
E-Mail : peoplevehicle@gmail.com
Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

CHINA TAI PING INSURANCE (S) PTE LTD
105 CECIL STREET #19-00
THE OCTAGON (S) 069534

Attention : Motor Claim Department
Contact : 6389 8111 Fax No. : 6222 1033

Estimate : ES19024

Date : 22/08/2019
Vehicle Num. : SLR 9702 L
Make/Model : MERCEDES BENZ C200
Chassis/Eng# :
Accident Date : 30/07/2019
Claim No. : TT 354-19
Reference : YN 3486 S
Policy No. : CHINA DMPCSN3012631800

S/N	Quantity	Particular		Unit Price	Amount S$
		SPRAY PAINTING ACCIDENT EFFECT PARTS	1230	~~850.00~~ 600	
		CHECK ALL LIGHTING AFTER REPAIR		~~60.00~~ 30	
		UNDERCOAT		100.00 X.	
		Labour Total S$:			2,410.00

SingDollars : Nine Thousand Seven Hundred Ninety Only

E. & O.E. Total S$: 9,790.00

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice.No Signature Required.

...s hence notify
...following:
...spray painting
...ed part(s) during resurvey
...subject to confirmation
...on a "Without Prejudice" basis
...ion(s) is allowed
• Supp...ary item(s) must be resurveyed and is subject to final approval from Insura...e Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling
H/S 22/08/19.

03 Days.

total: 4351.20
C/S: 3450.

Mei Kwan (LKKAuto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Tuesday, 10 September, 2019 9:50 AM
To: Mei Kwan (LKKAuto); Admin A; Wee Giap Enterprise; Vic (LKKAuto)
Cc: Ong Chin Kiat; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAuto); chantel3009 @hotmail.com; Chai Chui Ai; Lim Lee Choo
Subject: OUR REF: SNM19D203933-YN3486S-OCK - Direct Settlement - Accident Involving YN3486S (OI: SNM19D203933C02/6(ock) AND SLR9702L (TP : LKK REF - CC6/CTI19014841/Aha3) on 31/07/2019
Attachments: REPORT OF SLR9702L (EXTRACT).pdf; LIST OF AUTHORIZED WORKSHOPS.pdf

Categories: HMK

LKK REF - CC6/CTI19014841/Aha3
CTPIS REF – SNM19D203933C02/6(ock)

Policy NO: DMCVSN1915001900
Vehicle No: YN4386S
From 4 April 2019 to 4 November 2019

Dear Mei Kwan/Vic

We refer to your emails of 23 August 2019 and 10 September 2019 pertaining to the above matter.

Please note that Insured, **M/s SL Marine Engineering Pte Ltd has not and/or has yet and/or has refused to file accident report till date.**

Aside to M/s Wee Giap enterprise, please **assist to notify mutual client to instruct their driver namely Thiyagarajan Bhagathsing to file Accident Report IMMEDIATELY** at **M/s LKK Auto Consultants Pte Ltd OR any of China TaiPing Insurance (S) Pte Ltd Authorized Workshop (Reporting Centre)** to enable us to handle the incoming claim against their Motor Insurance Policy on their behalf.

Aside to Chin Kiat, please assist to keep track and repudiate liability, if necessary.

Meanwhile, please update the claims status in the system.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478
W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 10 September, 2019 8:32 AM
To: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow

We refer to the above matter.

We have inspected TP vehicle SLR 9702L at M/s People's Vehicle Recovery Service – Ubi on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.
Best Regards,

Mei Kwan | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/CTI19014841/Aha3

By Registered Mail
First Reminder

15 October 2019

Sl Marine Engineering Pte Ltd
12F Enterprise Road
Enterprise 10
SINGAPORE 627686

Dear Sirs/Madam,

ACCIDENT INVOLVING YN3486S AND SLR9702L ON 31.07.2019 ALONG/AT PAYA LEBAR ROAD TURNING TO PIE

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** dated 24/08/2019

To enable us to look into the matter immediately, please let us hear from you within **fourteen (14)** days from date of this letter (by 31/10/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

(Suvarna)

Singapore POST

Singapore Post Limited
(Reg. No. 199201624E)
10 Eunos Road 8
#06-30 Singapore Post Centre
Singapore 408600

Tel: 1605
Fax: 6842 5114
To check delivery status or to raise an enquiry on your registered article(s), please visit www.singpost.com

POSTING RECEIPT FOR REGISTERED ARTICLE(S)

NOTES:
a) Separate forms are to be used for Insured and Non-Insured Registered Article.
b) Please provide all information required and produce this receipt for all enquiries.
c) * Please tick where applicable. It shall be assumed no Advice of Receipt (AR) is required or delivery by air is requested if relevant * is left blank.
d) Please indicate the return address on the item(s) to ensure prompt return in event of non-delivery to the addressee(s).
e) Please post item(s) at the post office counter according to the sequence stated below.

1. Name & Address of Addressee
ESHAN LOGISTICS PTE LTD
190 WOODLANDS INDUSTRIAL PARK E5
#02-09
SINGAPORE 757512 (GBG 3784P)

AR*:( )Y( )N | By*:( ) AIR ( ) SUR | Insurance*:( )Y S$_____ ( )N | Contents:

2. Name & Address of Addressee
SI Marine Engineering Pte Ltd
12F Enterprise Road
Enterprise 10
Singapore 627686 (YN 34865)

AR*:( )Y( )N | By*:( ) AIR ( ) SUR | Insurance*:( )Y S$_____ ( )N | Contents:

For Official Use Only
(Item numbers are printed in order of posting at counter)

Sender's Agreement
I have read, understood and agreed to the terms and conditions of posting overleaf. I accept the maximum liability payable for Registered Mail Service and certify that all information provided by me is true and the item(s) does not contain any hazardous or prohibited item(s).

Name & Signature _____ Date _____

P116 09/2014

MPR-0311928800931B

Singapore POST

MacPherson Road
Singapore Post Limited
10 Eunos Road 8
Singapore Post Centre
Singapore 408600
GST Reg. No. : M2-0105651-9
Customer Service Hotline: 1605

Date/Time 15/10/2019 10:03

No.	Description	Amount(S$)
1	Accept Registered Article Item 1. Ref:RC282600335SG Ctry : SG Transaction No.:8135192880009 2. Ref:RC282600344SG Ctry : SG Transaction No.:8135192880010 3. Ref:RC282600358SG Ctry : SG Transaction No.:8135192880011 4. Ref:RC282600361SG Ctry : SG Transaction No.:8135192880012 5. Ref:RC282600375SG Ctry : SG Transaction No.:8135192880013	0.00
4	Sale of Postage Label (Domestic) Quantity: 1 Unit price: 2.54 Total GST: 0.17 Ref.: RC282600344SG Insurance: 0.00 Postage paid: 2.54 Transaction No.: 8135192880014	2.54
5	Sale of Postage Label (Domestic) Quantity: 1 Unit price: 2.54 Total GST: 0.17 Ref.: RC282600358SG Insurance: 0.00 Postage paid: 2.54 Transaction No.: 8135192880014	2.54
6	Sale of Postage Label (Domestic) Quantity: 1 Unit price: 2.54 Total GST: 0.17 Ref.: RC282600375SG Insurance: 0.00 Postage paid: 2.54 Transaction No.: 8135192880014	2.54
	Total GST	0.85
	Total Amount	12.70
	Cash	12.70

Enjoy up to 3% cashback on eligible online and retail spend with the Spree Credit Card.
No minimum spend required. T&Cs apply.
Sign up now at singpost.com/spreecard

Thank you for giving us the opportunity to serve you. Please visit www.singpost.com for detailed Terms and Conditions.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref : CC6/CTI19014841/Aha3n2

Date : 24-12-2019

Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	YN 3486S	**Veh. Inspected**	SLR 9702L
	Policy No.	DMCVSN1915001900	**Coverage ($)**	0.00
	Claim No.	SNM19D203933C02/6	**Excess ($)**	0.00
	Assign From		**Assign Date**	22/08/2019

2. Vehicle Particulars & Condition

	Make & Model	MERCEDES BENZ C 200	**c.c**	1796
	Engine No.	HIDDEN	**Year of Reg.**	2008
	Chassis No.	WDD2040412A150351	**Colour**	GREY
	Odometer	139613	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	31/07/2019	**Inspection Date**	22/08/2019
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9702L

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (N)	DEFORMED	1,345.00	1,345.00
1	BUMPER CENTRE MOULDING REAR (N)	NECESSARY	175.00	175.00
2	BUMPER SIDE MOULDING REAR @$110.00 (N)	NECESSARY	220.00	220.00
2	BUMPER SIDE RETAINER REAR @$75.00 (N)	NECESSARY	150.00	150.00
1	BUMPER REINFORCEMENT REAR (N)	BENT	650.00	650.00
1	BOOTLID (N)	TO REPAIR SEE LABOUR	1,850.00	-
1	BOOTLID INNER LOCK (N)	NOT NECESSARY	285.00	-
1	BOOTLID LOGO (N)	NECESSARY	85.00	85.00
1	C200 EMBLEM (N)	NECESSARY	75.00	75.00
1	KOMPRESSOR EMBLEM (N)	NECESSARY	105.00	105.00
1	BOOT HANDLE MOULDING (N)	NOT NECESSARY	195.00	-
2	TAIL LAMP @$560.00 (N)	NOT NECESSARY	1,120.00	-
1	END PANEL REAR (N)	TO REPAIR SEE LABOUR	1,205.00	-
4	REVERSE SENSOR @$185.00 (N)	DAMAGED (2 PCS ONLY)	740.00	370.00
1	REAR BUMPER CENTRE GUIDE (N)	CRACKED	185.00	185.00
2	TAILLAMP LOWER BRACKET @$54.00 (N)	CRACKED	108.00	108.00
	LESS 10% DISCOUNT		-849.30	-346.80
			7,643.70	3,121.20
	LABOUR			
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID AND END PANEL REAR.		1,400.00	600.00
	SPRAY PAINTING ACCIDENT EFFECT PARTS.		850.00	600.00
	CHECK ALL LIGHTING AFTER REPAIR.		60.00	30.00
	UNDERCOAT.	NOT NECESSARY	100.00	-
			2,410.00	1,230.00
	GRAND TOTAL		**10,053.70**	**4,351.20**

Report Ref No. CC6/CTI19014841/Aha3n2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**3,450.00**

Report Ref No. CC6/CTI19014841/Aha3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser