VOLKSWAGEN CENTRE SINGAPORE
17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Volkswagen ŠKODA Commercial Vehicles

Quotation

Non binding - Preview

Page 1/1

Ms.
QUEK
ZIMIN
216A COMPASSVALE DRIVE
#03-544
Singapore 541216

Document no.	
Document date	10-09-2019
Customer no.	5211040640
Customer GST-ID	
Dealer	39999
Job order number	2019001970/ 1
Job order date	10-09-2019
Service Advisor	PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SME2307Y	5T13NZ	24-09-2018	WVGZZZ1TZJW120903	Touran 1.4 CL GT110 TSID7F	212

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1	2,400.00	2,568.00

Quotation valid till 17-09-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	4,920.00	7%	397.60	5,680.00	6,077.60
Total	760.00	4,920.00		397.60	5,680.00	6,077.60

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010088
3 days
12/09/19 @1045
Resurvey after repair