23/03/2002

ASS. REC. BY: | REF: CS/FCI 1906165/ Ktf3 | Special Instruction: N2

(WS)

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Norina Chia Sun San of: FCI Date/Time: 12.9.19 12.26 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 7470E Insured: SHA 0956S

at Workshop m/s: HC Auto Tel: 94570678

of: 160 Sin Ming Drive #05-09

Policy No: Claim No: D1900589 3MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 9.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 13.9.19 (rep)

H.O.D. Endorsement:

Date/Time: 12.9.19 1.15p.m Person Contacted: Elaine Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 7470 E - ✓
	SHA 9565 - ✓
16/9 @ 10.58am	- Sent preli advise via email
7/11	1 Lm @ 215.61 email & confirm (Red: 4863.30, 68%)

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: Date: 13.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJF 7470E

at Workshop m/s HC AUTO

of 160 Sin ming Drive #05-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 11.00 a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: @ 26k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 6/23 Person Contacted: Vehicle: IN / OUT

Veh No: SJF 7470E Yr Regn: 06 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Mit Lancer EX c.c 1499

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 126559 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSRCY2A84 007308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: B.S 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	9/9/19	D.O.I.	13/9/19

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: $26,000
	LTA 13,675/-
	NV: 12325/-

RECEIVED 08 NOV 2019

Date/Time, File Pass to? 1) 8/11 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1+1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Rep Format : TP

Lump Sum / E.P.I.C : 2250

Survey Fee:	150
Transportation:	50
S + R S ... SI	50+50
Photos	24
Others	
TOTAL	324

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005893MFSH

Date: 16/09/2019

Our Ref: **CS/FCI19016165/Ktf3**

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJF 7470E
Please be informed that we had conducted the inspection of the abovementioned vehicle 13/09/2019 at the premises of M/s HC Auto have the following to report: -

Workshop Estimate Amount	: S$ 7,113.30
Revised Estimate Amount	: S$ 2,356.20
"Check" Items Amount	: S$ 595.70
Market Value	: S$
LTA Reimbursement Value	: S$
Nett Value	: S$

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth Kong
Automotive Assessor

MS FirstCapital

MS First Capital Insurance Limited Co.Reg.No. 195000106C GST Reg. No. M2-0001676-9
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date	11-09-2019	**Our Ref No.**	D19005893MFSH
Accident Date	09-09-2019	**Claim Type.**	Third Party
Insured Vehicle	SHA0956S	**Third Party Vehicle.**	SJF7470E
Survey Location	160 SIN MING DRIVE #05-09 SIN MING AUTO CITY		
Contact Person.	JOE CHEE		
Contact No.	0/ 94570678	**Fax No.**	0
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	**Fax No.**	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	H C AUTO PTE LTD	**Attention.**	NIL
Cc : TP Solicitor	VISION LAW LLC	**TP Solicitor Fax No.**	NA
Officer Incharge	MERINA CHIA SAN SAN		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 16 September 2019 10:58 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19005893MFSH/1
Attachments: PRELI ADVISED OF SJF 7470E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJF 7470E**
Number of days (estimated) : 3 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 12 September 2019 1:15 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005893MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	871Z
Vehicle Details	
Vehicle No.:	SJF7470E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	4A910083262
Chassis No.:	JMYSRCY2A8U007308
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	$16,591.00
Original Registration Date:	10 Jun 2008
First Registration Date:	10 Jun 2008
Transfer Count:	2
Actual ARF Paid:	$16,591.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	$19,107.00
COE Rebate Amount:	$13,675.00
Total Rebate Amount:	**$13,675.00**

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Nov 2019

OK

T/20190910/2082

Report No. T/20190910/2082

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No	1
Report Number	T/20190910/2082
Vide Report Number	T/20190910/7001
Date/Time of Report Made	10/09/2019 13:55
Place Report Lodged	Traffic Police
Type of Informant	Driver
Name of Informant	Lim Ziquan
ID Type / ID No.	NRIC NO / S9915056D
Home/Office	92205805
Mobile	92205805
Email	
Type of Accident	Non-Injury / Hit and Run
Drink Drive	No
Anyone conveyed by ambulance	No
Date/Time of Accident	09/09/2019 20:10
Accident Location	SEMBAWANG ROAD

SHA958S	Car	HYUNDAI	Ioniq	Yellow		2
SJF7470E	Car	MITSUBISHI	EX	White	Slightly Damaged	0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722
Tel : 6457 0678 Fax : 6457 8287
Co. and GST Reg. No. : 200820153N

Date : 12 / 09 / 2019

ESTIMATE COSTS OF REPAIR

Ms Soh Siew Lai
C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

Not Authorised
Liftup BZ250A
Resurvey After Paint
3 days

Dear Sir / Madam ,

Vehicle no. : SJF 7470 E - Mitsubishi Lancer 1.5 Mivec GLS
Accident date : 09 / 09 / 2019

	Quantity	Descriptions	Amount (S$)
1	1 pc	rear weather-strip	$ 195.00
2	1 pc	boot lid	$ 545.00
3	1 pc	boot lid inner lock	$ 60.00
4	1 pc	boot lid Mitsubishi logo	$ 45.00
5	1 pc	boot lid ' LANCER ' emblem	$ 26.00
6	1 pc	rear bumper fascia	$ 847.00
7	1 pc	rear bumper lower lip	$ 850.00
8	1 pc	rear bumper reinforcement	$ 273.00
9	2 pcs	rear bumper side bracket 1 @ 178.00	$ 356.00
10	2 pc	rear bumper side retainer 1 @ 43.00	$ 86.00
11	2 pc	rear bumper reflector 1 @ 168.00	$ 336.00
12	6 pcs	rear bumper clip 1 @ 3.50	$ 21.00
13	1 pc	rear end panel	$ 423.00
14	1 pc	rear end panel garnish	$ 174.00
			$ 4,237.00
		Less 10%	$ 423.70
			$ 3,813.30
15	1 pc	rear end panel seal	$ 250.00 sn
16	1 pc	rear no plate	$ 100.00 sn
17	1 set	rear reverse sensor	$ 350.00 sn
			$ 4,513.30
		Labour charges	$ 1,200.00
		To putty and spray painting	$ 1,000.00
		Re-seal anti rust	$ 120.00
		To check,replace,repair wiring	$ 180.00
		Remove and refix rear bumper reverse sensor	$ 100.00
			$ 7,113.30
		Plus : 7% GST	$ 497.93
		Grand-Total	$ 7,611.23

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS/FCI19016165/Ktf3n2

Date : 11-11-2019

Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	SHA 956S	**Veh. Inspected**	SJF 7470E
	Policy No.		**Coverage ($)**	0.00
	Claim No.	D19005893MFSH	**Excess ($)**	0.00
	Assign From	MERINA CHIA SAN SAN	**Assign Date**	12/09/2019

2. Vehicle Particulars & Condition

	Make & Model	MITSUBISHI LANCER EX (A)	**c.c**	1499
	Engine No.	HIDDEN	**Year of Reg.**	2008
	Chassis No.	JMYSRCY2A8U007308	**Colour**	WHITE
	Odometer	126559	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	09/09/2019	**Inspection Date**	13/09/2019
	Survey held at	HC AUTO & MOTORS SERVICE BLK 14 SIN MING ESTATE, #01-07/09, SINGAPORE 575658		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 7470E

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR WEATHER-STRIP	SERVICEABLE	195.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	545.00	-
1	BOOT LID INNER LOCK	TO REPAIR SEE LABOUR	60.00	-
1	BOOT LID MITSUBISHI LOGO	NOT NECESSARY	45.00	-
1	BOOT LID "LANCER" EMBLEM	NOT NECESSARY	26.00	-
1	REAR BUMPER FASCIA	BUCKLED	847.00	847.00
1	REAR BUMPER LOWER LIP	CRACKED	850.00	850.00
1	REAR BUMPER REINFORCEMENT	BENT	273.00	273.00
2	REAR BUMPER SIDE BRACKET @$178.00	SERVICEABLE	356.00	-
2	REAR BUMPER SIDE RETAINER @$43.00	SERVICEABLE	86.00	-
2	REAR BUMPER REFLECTOR @$168.00	SERVICEABLE	336.00	-
6	REAR BUMPER CLIP @$3.50	NECESSARY	21.00	21.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	423.00	-
1	REAR END PANEL GARNISH	SERVICEABLE	174.00	-
	LESS 10% DISCOUNT		-423.70	-199.10
			3,813.30	1,791.90
	SPECIAL NETT ITEMS			
1	REAR END PANEL SEAL (SN)	NOT NECESSARY	250.00	-
1	REAR NO PLATE (SN)	DENTED	100.00	45.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			700.00	245.00
	LABOUR			
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF BOOT LID,BOOT LID INNER LOCK AND REAR END PANEL.		1,200.00	360.00
	TO PUTTY AND SPRAY PAINTING.		1,000.00	400.00
	RE-SEAL ANTI RUST.	NOT NECESSARY	120.00	-
	TO CHECK,REPLACE,REPAIR WIRING.		180.00	15.00

Report Ref No. CS/FCI19016165/Ktf3n2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR.		100.00	50.00
			2,600.00	825.00
	GRAND TOTAL		**7,113.30**	**2,861.90**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**2,250.00**

Report Ref No. CS/FCI19016165/Ktf3n2

MARKET VALUE: $26,000.00 (EST)-LTA REIMBURSEMENT VALUE: $13,675.00=NETT VALUE: $12,325.00

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.