Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12503

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1124/2019/NS
Date	:	17-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SBQ 1771 M

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Tay Joo Li (Zheng Ruli)
Address	:	Blk 204 Serangoon Central #09-106 Singapore 550204
Telephone	:	HP +65 83161129
Type of Claim	:	Third Party Claims
Policy No.	:	1900007238
Vehicle No	:	**SMH 3308 Y**
Model Code	:	Audi A3 Cabriolet 1.4 TFS
Model / Year	:	Jan-19
Engine No	:	CZE 849494
Chassis No	:	WAUZZZ8V0K1015187
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Sep-19
Place of Accident	:	Upper Thomson Rd Towards Jln Todak

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 3308 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's RecommendatIon
1	To remove and transfer rear parking aid. Check function.	s/n	$ 280.00	
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.		$ 1,050.00	
3	To respray rear bumper.		$ 900.00	
4	To carry out diagnostic checks.	s/n	$ 192.00	
	SUB-TOTAL LABOUR CHARGES	**:**	**$ 2,422.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 3308 Y

S/N	Parts Description		Damage Parts & Prices S/NETT	REMARKS
1	REAR BUMPER		$ 1,793.00	
2	REAR BUMPER GUIDE SECTION - LH / RH	2	$ 30.00	
3	REAR BUMPER SPOILER		$ 216.00	
4	REAR LIGHT REFLECTOR - LH / RH	2	$ 76.00	
5	REAR PARKING AID SENSOR - INNER / OUTEI	2	$ 462.00	
6	REAR BUMPER SIDE REINFORCEMENT		$ 522.00	
7	SUNDRIES		$ 300.00	
	TOTAL SPARE PARTS CHARGES	:	**$ 3,399.00**	
	TOTAL LABOUR CHARGES	:	**$ 2,422.00**	
	GRAND TOTAL CHARGES	:	**$ 5,821.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	**:**
Surveyed Date	**:**
Authorised Date	**:**
Excess Cost	**:**
Liability	**:**
Remarks	**:**

Please Note **:** This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant