ASS. REC. BY: | REF: CS/FCI/9016477/Kq d3 n2 | Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CWS Jason Tea of FCI Date/Time: 5:30pm @ 17/9/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 3836B Insured: SHC 2038T

at Workshop m/s Cheng Hoe Motor Tel: 67556142

of Blk 1019 Yishun Ind. Park A # 01-574

Policy No: Claim No: D1900595 2MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 15/09/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement:

Date/Time: 11.06am @ 18/9/19 Person Contacted: Weiling Vehicle IN / OUT

Date/Time	Action/Instruction
	SMA 3836B - ✗
	SHC 2038T - CS/FCI/8005476/Atd 3.2 29.1413/2018
24/9/19 @	11.37am revised to Jason Tea by email.
19/2	@ 2512.00 Confirmed (Rad @ 340.60, 12%)

ASS. REC. BY: Kenneth

REF: PCZ1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chey Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 6741c

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA 3836B Yr Regn: 06 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mazda 3 c.c 1498

Colour M. Grey A/C: Insured / Std / NI / NA

Sp.Reading 8142 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8 J0224351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.	15/9/19	D.O.I.	23/9/19

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	File pass to

mon

19/2/2020

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech Invs ($)

☐ Weekend ($)

Report Format : TP

Lump Sum / I.B.I: ($ 751)

Survey Fee	110
Transportation	50
S + RS SI	50
Fuel/Oil	19
Others	
TOTAL	229

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005952MFSH

Date: 24 September 2019

Our Ref: CS/FCI19016477/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 3836B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/09/2019 at the premises of M/s CHENG HOE MOTOR. and have the following to report:-

Workshop Estimate Amount	: S$ 2,852.60 .
Revised Estimate Amount	: S$ 2,366.40 .
"Check" Items Amount	: S$ 291.20 .
Market Value	: S$ - .
LTA Reimbursement Value	: S$ - .
Nett Value	: S$ - .

Description of Damage:
The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MS FirstCapital

MS First Capital Insurance Limited (Co Reg No: 199000108E GST Reg No: M2-0002476-9)
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date	16-09-2019	**Our Ref No.**	D19005952MFSH
Accident Date	15-09-2019	**Claim Type.**	Third Party
Insured Vehicle	SHC2038T	**Third Party Vehicle.**	SMA3836B
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374		
Contact Person.	JUNE		
Contact No.	67556142/ 0	**Fax No.**	67557719
Survey Type	DIRECT SETTLEMENT		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	**Fax No.**	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	**Attention.**	NIL
Cc : TP Solicitor	NA	**TP Solicitor Fax No.**	NA
Officer Incharge	JASON TEA CHEE KIAT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 24 September 2019 11:27 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005952MFSH/1
Attachments: CSFCI19013566Kqf3.pdf

Dear Jason.

Enclosed herewith preliminary advice of SMA 3836B.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 18 September 2019 11:12 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005952MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 17 September 2019 5:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005952MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	131Z
Vehicle Details	
Vehicle No.:	SMA3836B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT LED EU6
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	P520516026
Chassis No.:	JM6BN22A8J0224351
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	$17,971.00
Original Registration Date:	05 Jun 2018
First Registration Date:	05 Jun 2018
Transfer Count:	0
Actual ARF Paid:	$17,971.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2028
PARF Rebate Amount:	$13,478.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	$38,700.00
COE Rebate Amount:	$33,129.00
Total Rebate Amount:	**$46,607.00**

The information contained herein is correct as at 16 Sep 2019

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
WS Ref: TP/FC/AMK
Claim Type: Third Party
Accident Date: 15/09/2019
TP Veh Reg No: SHC2038T

Not Authorised
Reserve B4 paint
4 days

Estimate No: **ES1992056/AMK**
Date: 23 Sep 2019
Policy No: 1800088229
Veh Reg No: **SMA3836B**
Make/Model: MAZDA 3 1.5L
Chassis No: JM6BN22A8J0224351
Engine No: P520516026
Reg. Date: 05/06/2018

Estimate Repair Cost to Vehicle No :SMA3836B

	Description	U/Price	Quantity	List Price	Amount
				S$	S$
	List Price				
1	REAR BUMPER	997.00	1 PC	997.00	—
2	REAR BUMPER TOW HOOK COVER	18.00	1 PC	18.00	—
3	REAR BUMPER REINFORCEMENT	565.00	1 PC	565.00	—
4	REAR BUMPER INNER CENTRE PDC SENSOR	182.00	2 PC	364.00	2+182
5	REAR BUMPER CLIP	5.00	5 PC	25.00	—
6	REAR BOOT LOGO	79.00	1 PC	79.00	—
7	REAR BOOT EMBLEM 'SKYACTIV'	67.00	1 PC	67.00	—
8	REAR BOOT EMBLEM 'MAZDA 3'	57.00	1 PC	57.00	—
				2,172.00	
			Less 20%	434.40	1,737.60
	Special Net				
9	REAR NUMBER PLATE	35.00	1 PC	35.00	X
				35.00	35.00
	Labour				
10	REMOVE & REFIX REAR BUMPER,REINFORCEMENTS & PARKING SENSORS,KNOCKING & REPAIR REAR END PANEL & REALIGN REAR BOOT THE SAME	400.00	1 LA	400.00	320
11	PUTTY & RESPRAY REAR BUMPER,REINFORCEMENTS,PARKING SENSORS,REAR END PANEL,REAR BOOT & ALL AFFECTED AREAS	600.00	1 LA	600.00	540
12	REMOVE & REFIX PARKING SENSORS,CHECK & RESET THE SAME	80.00	1 LA	80.00	60
				1,080.00	1,080.00
				Total	S$ 2,852.60
				Add GST @ 7%	199.68
				Total Amount Payable	S$ 3,052.28

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS/FCI19016477/Kqd3n2

Date : 20-02-2020

Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	SHC 2038T	**Veh. Inspected**	SMA 3836B
	Policy No.		**Coverage ($)**	0.00
	Claim No.	D19005952MFSH	**Excess ($)**	0.00
	Assign From	JASON TEA	**Assign Date**	17/09/2019

2. Vehicle Particulars & Condition

	Make & Model	MAZDA 3 (A)	**c.c**	1496
	Engine No.	HIDDEN	**Year of Reg.**	2018
	Chassis No.	JM6BN22A8J0224351	**Colour**	METALLIC GREY
	Odometer	8142	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	205/60 R16	BRIDGESTONE	9 mm
	L/H Front Tyre	205/60 R16	BRIDGESTONE	9 mm
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	15/09/2019	**Inspection Date**	23/09/2019
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 3836B

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	997.00	997.00
1	REAR BUMPER TOW HOOK COVER	MISSING	18.00	18.00
1	REAR BUMPER REINFORCEMENT	BENT	565.00	565.00
2	REAR BUMPER INNER CENTRE PDC SENSOR @$182.00	SHORTED (1 PC ONLY)	364.00	182.00
5	REAR BUMPER CLIP @$5.00	NECESSARY	25.00	25.00
1	REAR BOOT LOGO	NECESSARY	79.00	79.00
1	REAR BOOT EMBLEM "SKYACTIV"	NECESSARY	67.00	67.00
1	REAR BOOT EMBLEM "MAZDA 3"	NECESSARY	57.00	57.00
	LESS 20% DISCOUNT		-434.40	-398.00
			1,737.60	1,592.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	35.00	-
			35.00	-
	LABOUR			
	REMOVE & REFIX REAR BUMPER,REINFORCEMENTS & PARKING SENSORS,KNOCKING & REPAIR REAR END PANEL & REALIGN REAR BOOT THE SAME.		400.00	320.00
	PUTTY & RESPRAY REAR BUMPER REINFORCEMENTS,PARKING SENSORS,REAR END PANEL,REAR BOOT & ALL AFFECTED AREAS.		600.00	540.00
	REMOVE & REFIX PARKING SENSORS,CHECK & RESET THE SAME.		80.00	60.00
			1,080.00	920.00
	GRAND TOTAL		**2,852.60**	**2,512.00**

	RECOMMENDED COST OF REPAIRS			**2,512.00**

Report Ref No. CS/FCI19016477/Kqd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.