Vehicle Repair Estimate

Date : 20-Sep-2019
Vehicle Num : SGZ6991E
Make/Model : Golf Mk7 1.4TSI
Chassis No : WVWZZZAUZDW105852

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper	1	$ de 910.00	$ 910.00
2	Impact beam	1	$ ovc ? X 390.00	$ 390.00
3	Attachment strip bumper	1	$ new 70.00	$ 70.00
4	Tail light (Right)	1	$ outer 205.00	$ 205.00
5	Rear lock mechanism with micro switch	1	$ ovc? X 535.00	$ 535.00
6	Trunk Lid	1	$ bt 1,330.00	$ 1,330.00
7	Golf lettering	1	$ new 60.00	$ 60.00
8	TSI bluemotion		new 60.00	60.00
9				
10				
11				
12				
13				
14				
15				
16				
17				
	TOTAL PARTS			$ 3,500.00
			less 10%	
	TOTAL AMOUNT			$ 3,500.00
	MISCELLANEOUS ITEM			
	Sundries		$ 20 new 80.00	$ 80.00
	Number plate with casing		$ bt 35.00	$ 35.00
	LABOUR			
1	For the removal, transfer and installation of various associated components from rear bumper,trunk lid, windscreen, parking aid, harness, wiring, lock mechanism		$ 400. 650.00	$ 650.00
1	Surface preparation and paint for trunk lid and bumper		$ 450. 800.00	$ 800.00
3	To perform complete diagnosis of the vehicle		$ ✓ 90.00	$ 90.00
	Taughin 97495749.			
	WP' 25/9/19 P445			
	4-5 days			
	taughin @ [illegible]			
	lump sum after 10%			
	Resurvey before paint before			
	TOTAL			$ 5,155.00
	GST 7%			$ 360.85
	GRAND TOTAL			$ 5,515.85

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

L/o $2,700.00 5 DAYS

VAG

Vehicle Repair Estimate

Date : 20-Sep-2019

Vehicle Num : SGZ6991E

Make/Model : Golf Mk7 1.4TSI

Chassis No : WVWZZZAUZDW105852

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper	1	$ 910.00	$ 910.00
2	Impact beam	1	$ 390.00	
3	Attachment strip bumper	1	$ 70.00	$ 70.00
4	Tail light (Right)	1	$ 205.00	$ 205.00
5	Rear lock mechanism with micro switch	1	$ 535.00	
6	Trunk Lid	1	$ 1,330.00	$ 1,330.00
7	Golf lettering	1	$ 60.00	$ 60.00
8	TSI bluemotion	1	$ 60.00	$ 60.00
9				
10				
11				
12				
13				
14				
15				
16				
17				
	TOTAL PARTS			$ 2,635.00
			10% -	237 1.50
	TOTAL AMOUNT			$ 2,635.00
	Sundries		$ 80.00	$ 20.00
	Number plate with casing		$ 35.00	$ 35.00
	LABOUR			55
1	For the removal, transfer and installation of various associated components from rear bumper,trunk lid, windscreen, parking aid, harness, wiring, lock mechanism		$ 650.00	$ 400.00
1	Surface preparation and paint for trunk lid and bumper		$ 800.00	$ 450.00
3	To perform complete diagnosis of the vehicle		$ 90.00	$ 90.00
				940
	TOTAL			$ 3,630.00
	GST 7%			$ 254.10
				$ 3,884.10

3366.50

20% - 4 S$ 2700

5 days.

26/11