KCN

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D   GST REG:200707743D

23-Sep-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8535 R

Qty	Description		Amount
1 pc	Rear bumper		$ 696.00
1 pc	Rear bumper lower cover		$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ $29.00		$ 58.00
1 pc	Rear bumper inner sponge		$ 114.00
1 pc	Rear bumper reinforcement		$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ $53.00		$ 106.00
1 pc	Rear bumper n/s reflector		$ 46.00
2 pcs	Rear bumper reinforcement lower bracket @ $18.00		$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ $18.00		$ 36.00
			$ 1,905.00
		Less 10%	$ 190.50
			$ 1,714.50

S/NETT

Qty	Description		Amount
1 set	Rear bumper clips		$ 48.00
1 set	Reverse sensor		$ 280.00 — 200
	Rear Bumper Rubber Mat — nvc $50 —		
	Sundry		$ 50.00
	To dismantle / replace reverse sensor to new bumper and reset to the same		$ 120.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		$ 180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		200 $ 800.00
	To putty and spray painting on rear bumper, end panel		180 $ 400.00
	To apply rustproofing on the repaired and replaced panels.		$ 80.00
			$ 3,672.50

3,722.50#

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.