ASS. REC. BY: Merimen

REF: CC3/AIG M017421 / Af362

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100331009

Claims No. 8700726178G

Sum Insured: Excess: $1400

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Yes. Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKJ 1271U Yr Regn: 2013, Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A8 cc 2955

Colour: ~~Black~~ Blue A/C: Insured / Std / Nil / NA

Sp.Reading: 139829 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: WAU2224H2CN027562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R19. R: 255/45R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	03/10/19.

Survey held at: Premium

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD AIG.
	SKJ 1271U - CC3/AIG M017421 / Af362 D.O.A. 26/10/2019
	4/10 - 9:45 mandate request via merimen
MV : 120K	7/10 @ 12:33 - mandate approved by victor koh
PV : 86K	7/10 @ 2:05pm inform premium authorise repair
Nett. 34K	excess $1400/-
	Part by Part $25,878.30 (Red: 32014.18 : 55%)

Date/Time, File Pass to? 2/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : OD

Lump Sum / I.B.J: $ 25,878.30

Survey Fee:	200
Transportation:	
S + RS S	
Photos	
Other:	11
TOTAL	211

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	822M
Vehicle Details	
Vehicle No.:	SKJ1271U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QUATTRO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	CGW036566
Chassis No.:	WAUZZZ4H2CN027562
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	$83,970.00
Original Registration Date:	21 Feb 2013
First Registration Date:	21 Feb 2013
Transfer Count:	0
Actual ARF Paid:	$83,970.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2023
PARF Rebate Amount:	$54,580.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	$92,667.00
COE Rebate Amount:	$31,330.00
Total Rebate Amount:	**$85,910.00**

The information contained herein is correct as at 04 Oct 2019

OK

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 7 October 2019 2:05 PM
To: claims@premiumauto.com.sg; Admin-D (LKKAuto); Admin A; SUR
Subject: RE: OD CLAIM FOR SKJ 1271 U ON 2/10/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKJ 1271U (Excess $1,400/-). Not exceeding $34,000/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, 7 October 2019 10:43 AM
To: claims@premiumauto.com.sg; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SKJ 1271 U ON 2/10/2019

Dear Sir,

Still waiting approval

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 7 October 2019 10:37 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	03 Oct 2019 09:48	**Clm Veh Model Changed**		[] Merimen Administrator
2	03 Oct 2019 09:48	**Clm Created**	Reg No: SKJ1271U. Policy No: 2100331009-06. Acct Date: 2019/10/02. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119130789	[I] Merimen Administrator
3	03 Oct 2019 14:17	**Clm Registration Modified**	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	03 Oct 2019 14:17	**Adj Clm Retrieved**	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	03 Oct 2019 14:17	**Adj Co Assigned**	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	03 Oct 2019 14:17	**Adj Next Rpt Changed**	Next Rpt:Final Rpt.Due Date:2019/10/14	[A] LEE SU THING
7	03 Oct 2019 14:17	**Adj Mandate Set**	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	03 Oct 2019 14:17	**Clm Registration Modified**	Rep:1137->200611.	[A] LEE SU THING
9	03 Oct 2019 14:17	**Clm Veh Model Changed**	(203386) AUDI A8L 3.1 FSI (D3) (A).	[A] LEE SU THING
10	03 Oct 2019 14:17	**Adj Adjuster Assigned**	[None] -> ADRIAN LING	[A] LEE SU THING
11	04 Oct 2019 08:53	**Adj Rpt Initiated**		[A] DENISE TAY KWEE CHENG
12	04 Oct 2019 08:53	**Insured Phone No Updated**	[None] -> [+6598192091]	[A] DENISE TAY KWEE CHENG
13	04 Oct 2019 08:53	**Clm Dtl Modified**	JPJ Reg. Date: -> 2013/02/21.	[A] DENISE TAY KWEE CHENG
14	04 Oct 2019 08:53	**Clm Details Notified**		[A] DENISE TAY KWEE CHENG
15	04 Oct 2019 09:32	**Adj Im. Advice Submitted**	Next Rpt:Final Rpt.Due Date:2019/10/14	[A] DENISE TAY KWEE CHENG
16	04 Oct 2019 09:45	**Adj Mandate Request**	Cur.Req:32726.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
17	04 Oct 2019 15:21	**Clm Registration Modified**	Init.Est.:->5,000 - 6,000. Excess: -> 1400.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mithoo Singh, Aashweenjeet Kaur
18	07 Oct 2019 08:44	**Label Added**	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	07 Oct 2019 12:33	**Adj Next Rpt Changed**	Next Rpt:Final Rpt.Due Date:2019/10/14. Mandate Remarks: Re-inspection and upload damage photos of RH front fender required. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	07 Oct 2019 12:33	**Adj Mandate Set**	Approved:23533.00:Re-inspection and upload damage photos of RH front fender required. Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From **Date To** **Audit Type** None Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2302052	04 Oct 2019 08:53:32	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKJ1271U		11.77

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/10/2019 09:35
Date Of Accident	02/10/2019 15:15
Exact Location Of Accident	YISHUN AVE 9 TOWARDS AVE 6
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKJ1271U
Insured/Policyholder	
Name Of Registered Owner	ALL BIG FROZEN FOOD PTE LTD
Co Reg No	199105822M
Email Address	VINCENT@ALLBIG.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-66942300
Vehicle Particulars	
Manufacturer	AUDI
Model	A8L D4 3.0 TFSI QU 4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	2100331009-06
Cover Note Number	
Driver	
Name of Driver	WEE MENG TECK
NRIC No	S1561616D
Date Of Birth	24/10/1962
Occupation	INDOOR
Date Of Driving Pass	17/10/1983
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98192091
Fax Number	
Contact Number	
EMail Address	VINCENT@ALLBIG.COM.SG

Address	58 LENTOR CRESCENT
Postcode	786723
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I WAS TRAVELLING ON AVE 9 YISHUN TOWARDS AVE 6 AND AFTER THE JUNCTION OF AVE 9 AND STREET 21 ABOUT 30 METER AHEAD, THE CAR SMH 8708 T STOP SUDDENLY TO TURN RIGHT INTO THE ESSO PETROL STATION AND I COULDN'T STOP IN TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH8708T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on Ave 9 Yishun towards Ave 6 and after the junction of Ave 9 and Street 21 about 30 meter ahead, the car SMH 8708T stop suddenly to turn right into the Esso petrol station and I couldn't stop in time.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Oct 2019

Preliminary Advice

Vehicle No	: SKJ1271U	Accident Date	: 02/10/2019
Make	: AUDI A8L	Policy No.	: 2100331009-06
Assignment Date	: 03/10/2019	Excess	: S$0.00
Date of Inspection	: 03/10/2019	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	57,337.00
Revised Amount	:S$	23,533.00
Check Items (Estimated)	:S$	9,193.00
Total	:S$	32,726.00
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	120,000.00
COE / PARF Rebate	:S$	85,910.00
Salvage Value	:S$	
Margin for Repair	:S$	34,090.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

>Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	822M
Vehicle Details	
Vehicle No.:	SKJ1271U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QUATTRO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	CGW036566
Chassis No.:	WAUZZZ4H2CN027562
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	$83,970.00
Original Registration Date:	21 Feb 2013
First Registration Date:	21 Feb 2013
Transfer Count:	0
Actual ARF Paid:	$83,970.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2023
PARF Rebate Amount:	$54,580.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	$92,667.00
COE Rebate Amount:	$31,330.00
Total Rebate Amount:	**$85,910.00**

The information contained herein is correct as at 04 Oct 2019

OK

>Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	822M
Vehicle Details	
Vehicle No.:	SKJ1271U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QUATTRO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	CGW036566
Chassis No.:	WAUZZZ4H2CN027562
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	$83,970.00
Original Registration Date:	21 Feb 2013
First Registration Date:	21 Feb 2013
Transfer Count:	0
Actual ARF Paid:	$83,970.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2023
PARF Rebate Amount:	$54,580.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	$92,667.00
COE Rebate Amount:	$31,357.00
Total Rebate Amount:	**$85,937.00**

The information contained herein is correct as at 03 Oct 2019

OK

UOB We're revving up our celebrations for our first-year milestone

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!
Post an Ad | Advertiser Login | Ways of Selling

Classic Promo!Best Deal!Fast Selling!Hurry Down Now!
Flexible Loan. Trade In Are Welcome. 100% Deposit Refund For Unapproved Loan.
Classic Credit StarAd

* Free VICOM evaluation
* Free grooming and 6 months maintenance
* In-house workshop ensures quality service
* Member of SVTA and hire purchase association
* 100% deposit refund for unapproved loan
YONG LEE SENG MOTOR PTE LTD

Browse by Category | Save Search | Print | Sort by Date Posted | 20 results/page

11 vehicles | Search audi a8 | Advanced Search | Search | View All

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	audi a8		Any	Any	Any	Any	Any	Any	Available

Audi A8 Diesel 3.0A 50 TDI Quattro | $298,000 | N.A | N.A. | 2,967 cc | 270 km | Luxury | Available

Original Registration Date: 31-Oct-2018 Imported Used Vehicle. Comes with new 10-yr COE.
Fuel Type: Diesel (Euro 5 Engine and Above)
Vesuvius Grey Unit In Impeccable Condition! Grey Metallic Paintwork Matched With Black Leather Interior Seats And Wood Trimmings! Flexible Loan Available! Call Now To Enquire More Or To Arrange A Viewing!

Envy Motors Pte Ltd

Posted: 14-Sep-2019 Tags: Audi A8, audi a8, Audi, A8, a8, Used Audi

Audi A8 4.2A FSI Quattro | $74,000 | $25,420 /yr | 08-Nov-2010 | 4,163 cc | 188,000 km | Luxury | Available

This Car Is Like New Just Changed Tyres Few Weeks Ago, Servicing Done This Week And New Battery And Break Pad Fixed Few Days Ago, You Have Nothing To Worry About For The Next One Year.

Posted: 14-Sep-2019 Tags: 2015 Audi A8, 2010 audi a8, Audi A8, audi a8, Audi, A8, a8, Used Audi

Audi A8L 4.2A FSI Quattro | $79,800 | $24,220 /yr | 28-Dec-2010 | 4,163 cc | 65,000 km | Luxury | Available

6 Months Warranty, Excellent Condition, Low Mileage, Fully Maintain By Premium, Servicing Just Done, Accident Free, Loan Available, Trade In Welcome.

Posted: 20-Sep-2019 Tags: 2015 Audi A8L, 2010 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audi A8L 6.3A FSI W12 Quattro | $149,800 | $33,900 /yr | 08-Jul-2011 | 6,299 cc | 47,100 km | Luxury | Available

Please Note That This Is An Owner Consignment Vehicle, Viewing Strictly By Appointment Only. Top Of The Range Agent's Unit Audi A8L With W12 Engine. Loan/Trade In Available, Call To Scrutinize.

Posted: 05-Sep-2019 Tags: 2011 Audi A8L, 2011 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

JBL MS-8 Digital Processor

Cash & Carry Automatic Equalizer for Great Sound from Any Car Audio System UOB Credit Card 12month 0% Installment Plan

More info about this product

Audi A8L 4.2A FSI Quattro | $109,800 | $26,190 /yr | 20-Dec-2011 | 4,163 cc | 88,000 km | Luxury | Available

High Spec Ultra Luxurious A8 Long Wheelbase, Classy Wood And Leather Finishing, Nappa/Alcantara Leather Lining, Accident Free, Well Kept In Original Beautiful White Paint, Brown Leather Interior, Audi MMI, Rear Entertainment, Call For Viewing Appointment

Posted: 20-Aug-2019 Tags: 2011 Audi A8L, 2011 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audi A8L 3.0A TFSI Quattro | $122,800 | $25,140 /yr | 20-Dec-2012 | 2,995 cc | 98,000 km | Luxury | Available

Accident-Free. Kept In Pristine Condition. Trade-In And Loan Available. Please Call For An Appointment.

Posted: 22-Sep-2019 Tags: 2012 Audi A8L, 2012 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audi A8L 3.0A TFSI Quattro | $156,000 | $22,010 /yr | 30-May-2014 | 2,995 cc | 72,000 km | Luxury | Available

Almost New Condition. Accident Free. Tip Top Condition.

Posted: 10-Aug-2019 Tags: 2014 Audi A8L, 2014 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

SHORTLISTED | HISTORY

Compare [3]

Audi A8L 3.0A TFSI Quattro | $246,000 | $25,050 /yr | 16-Jun-2017 | 2,995 cc | - | Luxury | Available

1 Owner, Fully Serviced By Audi, 5 Years Unlimited Mileage Agent Warranty. Classy Black On Beige Interiors, Paintwork /leather Care 7 Year AAS Warranty. Evaluation Welcomed, Trade-In Available, Call Now To View! Viewing By Appointment.

360 VR Cars

Posted: 10-Sep-2019 Tags: 2017 Audi A8L, 2017 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audi A8L Mild Hybrid 3.0A TFSI Quattro | $369,999 | $34,410 /yr | 30-Nov-2018 | 2,995 cc | 16,000 km | Luxury | Available

Fuel Type: Petrol-Electric

Latest Audi Flagship Model! Twin Roof. OLED! One Audi Management Owner! 5 Years Audi Agent Warranty Till Nov 2023! Unlimited Mileage! Fully Audi Agent Servicing Since Day One! Lowest Bank Interest Rate 2.28%! Showroom Condition! Flexible Financial Available,...

PREMIUM AD

Premium Automobiles

Posted: 21-Sep-2019 Tags: 2018 Audi A8L, 2018 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audi A8L Mild Hybrid 3.0A TFSI Quattro | $376,999 | $34,400 /yr | 30-Nov-2018 | 2,995 cc | 6,000 km | Luxury | Available

Fuel Type: Petrol-Electric

Latest Generation Audi A8L With Mild Hybrid Technology! Audi Management Unit! 5 Years Audi Agent Warranty Till Nov 2023! Unlimited Mileage! Fully Audi Agent Servicing Since Day One! 100% Loan Approval! Bank Interest Rate 2.28%. Showroom Condition! Superb Tip T...

PREMIUM AD

Premium Automobiles

Posted: 13-Sep-2019 Tags: 2018 Audi A8L, 2018 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Audio Upgrade for Any Budget

Enhance your in-car entertainment with a headunit upgrade. Choose from 400+ units. Prices from just $170!

Find out more!

Audi A8L Mild Hybrid 3.0A TFSI Quattro | $374,999 | $34,460 /yr | 30-Nov-2018 | 2,995 cc | 17,880 km | Luxury | Available

Fuel Type: Petrol-Electric

Stunning Vesuvius Grey Metallic With Acoustic Glass, OLED! One Audi Management Owner! 5 Years Audi Agent Warranty Till Nov 2023! Fully Audi Agent Servicing Since Day One! Lowest Bank Interest Rate 2.28%! Showroom Condition! Superb Tip Top Condition! High Trad...

PREMIUM AD

Premium Automobiles

Posted: 05-Sep-2019 Tags: 2018 Audi A8L, 2018 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used audi a8l, audi a8l Singapore, used audi a8l Singapore, used audi a8l, used vehicles Singapore or even buy used audi a8l Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare [3]

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14599

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1185/2019/NS
Date	:	3-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	All Big Frozen Food Pte Ltd
Address	:	1 Senoko Ave Singapore 758297
Telephone	:	HP +65 98192091
Type of Claim	:	Own Damage Claim
Policy No.	:	2100331009-06
Vehicle No	:	**SKJ 1271 U**
Model Code	:	A8 D4 3.0 TFSI QU
Model / Year	:	Feb-13
Engine No	:	CGW 036566
Chassis No	:	WAUZZZ4H2CN027562
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Oct-19
Place of Accident	:	Yishun Ave 9 Towards Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKJ 1271 U

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendation
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	$	480.00	
2	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	$	1,400.00	? 1400
3	To dismantle and renew front bumper, rhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		$	7,000.00	3.5×600 = 2100 (Without lock carrier). 6×600 = 3600 (With lock carrier)
4	To respray front bumper, bonnet, rhs front fender and hinges.		$	4,000.00 1800	600×3 = 1800
5	To carry out diagnostic checks.	S/N	$	192.00	
	TOTAL LABOUR CHARGES	:		**$13,072.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
1	FRONT BUMPER Distorted.		$	3,051.00 ✓	2440.80
2	FRONT BUMPER CLOSING ELEMENT } Not Nec		$	238.00 ✗	
3	FRONT BUMPER SPOILER		$	271.00 ✗.	
4	FRONT BUMPER WHEEL SPOILER - RH OUTER } Not Nec		$	40.00 ✗	
5	FRONT BUMPER WHEEL SPOILER - RH INNER		$	32.00 ✗.	
6	FRONT BUMPER FOAM FILLER PIECE Cracked		$	✓116.00 ?	92.40
7	FRONT BUMPER CARRIER Bent		$	✓987.00 ?	789.60
8	FRONT BUMPER COVER Damaged		$	✓59.00 ?	47.04
9	FRONT BUMPER COVER Damaged.		$	✓116.00 ?	92.40
10	FRONT BUMPER GUIDE PIECE - RH ~~Not Nec~~ Damaged.		$	✓48.00 ✗	37.68
11	FRONT BUMPER RETAINING BRACKET - LH / RH Not Nec	2	$	28.00 ✗.	
12	FRONT BUMPER TRIM BRACKET - LH / RH New	2	$	✓32.00 ?	12.72
13	SIGNAL HORN BRACKET Not Nec		$	43.00 ? ✗	
14	SIGNAL HORN - LOW TONE Not Nec		$	262.00 ? ✗	
15	SIGNAL HORN - HIGH TONE Not Nec		$	168.00 ? ✗	
16	FRONT PARKING AID SENSOR Not Nec	3	$	629.00 ? ✗	
17	FRONT FENDER - RH Buckled.		$	✓1,681.00 ✓	1344.80
18	FRONT FENDER ATTACHMENT PARTS Not Nec		$	260.00 ?	
19	FRONT FENDER REAR BRACKET - RH Not Nec		$	26.00 ✗.	
20	FRONT FENDER BRACE Bent.		$	✓775.00 ?	620.00
	SUB TOTAL SPARE PARTS CHARGES	:	**$**	**8,862.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
21	FRONT FENDER FRONT BRACKET - RH Bent.		$	23.00 ?	18
22	FRONT FENDER CONNECTING PIECE Bent.		$	221.00 ?	176.80
23	WHEEL HOUSING LINER - RH FRONT ? Not New		$	276.00 X	
24	WHEEL HOUSING LINER - RH REAR		$	206.00 X.	
25	BONNET Distorted.		$	6,055.00	4844
26	BONNET ATTACHMENT PARTS Not Nec		$	240.00 ?	
27	BONNET CATCH HOOK Not New		$	142.00 X.	
28	BONNET LID HINGE - LH / RH Not New	2	$	494.00 X.	
29	BONNET GAS FILLED STRUT Not New	2	$	217.00 X	
30	BONNET LOCK BAR Not Nec	2	$	218.00 ?	
31	BONNET SEAL New		$	53.00	41.92
32	BONNET FLAP GASKET Not Nec		$	152.00 ?	
33	BONNET HOUSING - LH / RH Not New	2	$	84.00 X.	
34	BONNET LID LOCK Not Nec	2	$	420.00 X.	
35	MICRO SWITCH - FRONT Not New	2	$	133.00 X.	
36	BONNET COVER New	2	$	7.00 X	
37	CAUTION SIGN STICKER ? New	NEC	$	13.00	9.76
38	AIRCON STICKER	NEC	$	18.00	14.00
39	FRONT BUMPER GRILLE - LH / RH RH Dmgd	2	$	~~766.00~~	383 . 306
40	FRONT BUMPER END CAP - RH ~~Not Nec~~ Dmgd		$	62.00 X.	48.88
	SUB TOTAL SPARE PARTS CHARGES	:	**$**	**9,800.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
41	FRONT BUMPER LICENSE PLATE HOLDER Cracked		$	418.00	334
42	RADIATOR GRILLE } Cracked.		$	1,751.00	1400.80
43	QUATTRO INSCRIPTION		$	87.00	69.28
44	RADIATOR GRILLE STRIKER PLATE - UPPER ~~Not Nec~~ Cracked.		$	117.00 ?	93.60
45	RADIATOR GRILLE COVER CAP Not Nec		$	126.00 ?	
46	RADIATOR GRILLE COVER Not New		$	55.00 ?	
47	RADIATOR GRILLE REINFORCEMENT - LH / RH Bnd	2	$	88.00 ?	70.22
48	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT INNER Not New	2	$	88.00 ?	
49	RADIATOR GRILLE SECURING PLATE Not new		$	75.00 ?	
50	REAR DIGITAL CAMERA Damged.		$	902.00 ?	721.20
51	FRONT HEADLAMP BRACKET RH Dmgd.	4	$	104.00 ?	41.60
52	HEADLIGHT - LH / RH RH cracked.	1 ~~2~~	$	~~7,376.00~~	3688. 2950.40
53	GAS DISCHARGE LAMP } New		$	398.00	
54	GAS DISCHARGE LAMP CONTROL UNIT		$	1,051.00	
55	HEADLIGHT VENT HOSE - RH		$	17.00	
56	HEADLIGHT LIFT CYLINDER - LH / RH RH cracked	1 ~~2~~	$	~~432.00~~	216 172.40
57	HEADLIGHT WASHER HOSE Not new		$	98.00	
58	COOLANT RADIATOR LOCK CARRIER Cracked.		$	1,031.00 ?	824.80
59	FRONT CONSOLE CATCH HOOK - CENTRE Not new	2	$	222.00 ?	
60	A/C CONDENSER Not Nec.		$	876.00	
	SUB TOTAL SPARE PARTS CHARGES	:		**$ 15,312.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remark
61	PRESSURE SENDER		$	175.00	
62	HIGH PRESSURE PRESSURE RELIEF VALVE		$	48.00	
63	A/C CONDENSER ADAPTER		$	91.00	
64	RADIATOR - REAR CENTRE	Not Nec	$	1,246.00	
65	RADIATOR RUBBER BUSH - UPPER / CENTRE / LOWER		6 $	54.00	
66	ADDITIONAL RADIATOR - FRONT CENTRE		$	1,044.00	
67	READY MIX COOLANT Not Nec		4 $	84.00	67.20
68	TWIN FAN RING		$	400.00	
69	RADIATOR FAN - LH / RH	Not Nec	2 $	5,316.00	
70	RADIATOR AIR GUIDE - LH / RH	RH Damaged	2 $	82.00	32.24
71	RADIATOR AIR GUIDE	Not Nec	$	37.00	
72	RADIATOR SEALING STRIP - LOWER CENTRE	Not Nec	$	21.00	
73	AIR FILTER		$	486.00	
74	INTAKE MANIFOLD	Not Nec	$	455.00	
75	AIR FILTER RETAINER		$	28.00	
76	INTAKE AIR DUCT Dented		$	47.00 ?	37.36
77	INTAKE DUCT Not Nec		$	62.00 ?	
78	FLANGE Not Nec		$	38.00 ?	
79	AIR INLET DUCT COVER Damaged.		$	24.00 ?	19.04
80	BONNET ANTI THEFT GUARD COVER - RH Not Nec		$	13.00 ?	
81	FRONT NO PLATE Bent	S/N	$	40.00	40
82	SUNDRIES Not Nec.		$	500.00 ?	161.70
	TOTAL SPARE PARTS CHARGES		:	**$ 44,265.00**	
	TOTAL LABOUR CHARGES			**$ 13,072.00**	
	GRAND TOTAL			**$ 57,337.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

93287.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Adrian Ling.
Surveyed Date	:	03/10/19.
Authorised Date	:	
Excess Cost	:	
Liability	:	Not Authorised, 07 Days. (Without lock Carrier)
Remarks	:	10 Days. (With Lock Carrier)

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/1185/2019/NS
Date	16-Oct-19
Service Advisor	Glory Tan
Pages	1 of 1
Regn No	SKJ 1271 U
Model No	A8 D4 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	Retaining bracket for lock carrier RHS Cm	$ 16.00	12.32
2	Adapter cable loom camera Cm	$ 384.00	309.70
3	Coupling element for headlight RHS Cm	$ 12.00	
4	Bracket for radiator grille nu	$ 9.00	6.30
5	Locking clips for radiator nu	$ 36.00	28.80
6	Securing element for wheel housing liner nu	$ 99.00	79.00

TOTAL **$ 556.00**

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remarks
1	FRONT BUMPER Distorted.	$	3,051.00 ✓	3051
2	FRONT BUMPER CLOSING ELEMENT ? Not Nec	$	238.00 ✗	
3	FRONT BUMPER SPOILER	$	271.00 ✗.	
4	FRONT BUMPER WHEEL SPOILER - RH OUTER ? Not Nec	$	40.00 ✗	
5	FRONT BUMPER WHEEL SPOILER - RH INNER	$	32.00 ✗.	
6	FRONT BUMPER FOAM FILLER PIECE ? CM ✓	$	116.00 ?	(116)
7	FRONT BUMPER CARRIER ? CM ✓	$	987.00 ?	(987)
8	FRONT BUMPER COVER ? CM ✓	$	59.00 ?	(59)
9	FRONT BUMPER COVER ? CM ✓	$	116.00 ?	(116)
10	FRONT BUMPER GUIDE PIECE - RH Not Nec CM ✓	$	48.00 ✗	
11	FRONT BUMPER RETAINING BRACKET - LH / RH Not Nec	2 $	28.00 ✗.	
12	FRONT BUMPER TRIM BRACKET - LH / RH ? CM ✓	2 $	32.00 ?	(32)
13	SIGNAL HORN BRACKET ?	$	43.00 ?	(43)
14	SIGNAL HORN - LOW TONE ?	$	262.00 ?	(262)
15	SIGNAL HORN - HIGH TONE ?	$	168.00 ?	(168)
16	FRONT PARKING AID SENSOR ?	3 $	629.00 ?	(629)
17	FRONT FENDER - RH Buckled.	$	1,681.00 ✓	1681
18	FRONT FENDER ATTACHMENT PARTS ?	$	260.00 ?	(260)
19	FRONT FENDER REAR BRACKET - RH Not Nec	$	26.00 ✗.	
20	FRONT FENDER BRACE ? bf ✓	$	775.00 ?	(775)
	SUB TOTAL SPARE PARTS CHARGES	: $	8,862.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
21	FRONT FENDER FRONT BRACKET - RH ? bt		$	23.00 ?	(13)
22	FRONT FENDER CONNECTING PIECE ? ~~8~~ bt		$	221.00 ?	(221)
23	WHEEL HOUSING LINER - RH FRONT } Not new		$	276.00 X	
24	WHEEL HOUSING LINER - RH REAR		$	206.00 X.	
25	BONNET Distorted.		$	6,055.00 ✓	6055
26	BONNET ATTACHMENT PARTS ?		$	240.00 ?	(240)
27	BONNET CATCH HOOK Not new		$	142.00 X.	
28	BONNET LID HINGE - LH / RH Not new	2	$	494.00 X.	
29	BONNET GAS FILLED STRUT Not new	2	$	217.00 X	
30	BONNET LOCK BAR ?	2	$	218.00 ?	(218)
31	BONNET SEAL New		$	53.00 ✓	53
32	BONNET FLAP GASKET ?		$	152.00 ?	(152)
33	BONNET HOUSING - LH / RH Not new	2	$	84.00 X.	
34	BONNET LID LOCK Not new	2	$	420.00 X.	
35	MICRO SWITCH - FRONT Not new	2	$	133.00 X.	
36	BONNET COVER New	2	$	7.00 ✓	7
37	CAUTION SIGN STICKER } New	NEC	$	13.00 ✓	13
38	AIRCON STICKER	NEC	$	18.00 ✓	18
39	FRONT BUMPER GRILLE - LH / RH RH Dmgd	2	$	~~766.00~~ 383.	383
40	FRONT BUMPER END CAP - RH Not new		$	62.00 X.	
	SUB TOTAL SPARE PARTS CHARGES	:	$	9,800.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remarks
41	FRONT BUMPER LICENSE PLATE HOLDER Cancelled		S 418.00 ✓	418
42	RADIATOR GRILLE } Cancelled.		S 1,751.00 ✓	1751
43	QUATTRO INSCRIPTION		S 87.00 ✓	87.
44	RADIATOR GRILLE STRIKER PLATE - UPPER ? Can ✓		S 117.00 ?	(117)
45	RADIATOR GRILLE COVER CAP ?		S 126.00 ?	(126)
46	RADIATOR GRILLE COVER ?		S 55.00 ?	(55)
47	RADIATOR GRILLE REINFORCEMENT LH RH ? Can ✓	2	S 88.00 ?	(88)
48	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT INNER ?	2	S 88.00 ?	(88)
49	RADIATOR GRILLE SECURING PLATE ?		S 75.00 ?	(75)
50	REAR DIGITAL CAMERA ? Can ✓		S 902.00 ?	(902)
51	FRONT HEADLAMP BRACKET ?	4	S 104.00 ?	(104)
52	HEADLIGHT - LH / RH RH Cancelled.	2	S ~~7,376.00~~ 3688.	3688
53	GAS DISCHARGE LAMP ?		S 398.00 ✗	
54	GAS DISCHARGE LAMP CONTROL UNIT } New		S 1,051.00 ✗	
55	HEADLIGHT VENT HOSE - RH		S 17.00 ✗	
56	HEADLIGHT LIFT CYLINDER - LH / RH RH cancelled	2	S ~~432.00~~ 216	216
57	HEADLIGHT WASHER HOSE Not new		S 98.00 ✗.	
58	COOLANT RADIATOR LOCK CARRIER ? Can ✓		S 1,031.00 ?	(1031)
59	FRONT CONSOLE CATCH HOOK - CENTRE ?	2	S 222.00 ?	(222)
60	A/C CONDENSER Not Nec.		S 876.00 ✗	
	SUB TOTAL SPARE PARTS CHARGES	:	$ 15,312.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKI 1271 U

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remark
61	PRESSURE SENDER		$ 175.00	
62	HIGH PRESSURE PRESSURE RELIEF VALVE		$ 48.00	
63	A/C CONDENSER ADAPTER		$ 91.00	
64	RADIATOR - REAR CENTRE		$ 1,246.00	
65	RADIATOR RUBBER BUSH - UPPER / CENTRE / LOWER		6 $ 54.00	
66	ADDITIONAL RADIATOR - FRONT CENTRE		$ 1,044.00	
67	READY MIX COOLANT		4 $ 84.00	
68	TWIN FAN RING		$ 400.00	
69	RADIATOR FAN - LH / RH		2 $ 5,316.00	
70	RADIATOR AIR GUIDE - LH / RH		2 $ 82.00	
71	RADIATOR AIR GUIDE		$ 37.00	
72	RADIATOR SEALING STRIP - LOWER CENTRE		$ 21.00	
73	AIR FILTER		$ 486.00	
74	INTAKE MANIFOLD		$ 455.00	
75	AIR FILTER RETAINER		$ 28.00	
76	INTAKE AIR DUCT ?		$ 47.00 ?	(47)
77	INTAKE DUCT ?		$ 62.00 ?	(62)
78	FLANGE ?		$ 38.00 ?	(38)
79	AIR INLET DUCT COVER		$ 24.00 ?	(24)
80	BONNET ANTI THEFT GUARD COVER - RH ?		$ 13.00 ?	(13)
81	AW FRONT NO PLATE		S/N $ 40.00	40.00
82	SUNDRIES ?		$ 500.00 ?	
	TOTAL SPARE PARTS CHARGES		: $ 44,265.00	
	TOTAL LABOUR CHARGES		$ 13,072.00	
	GRAND TOTAL		$ 57,337.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14599

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1185/2019/NS
Date	:	3-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
We took 19 days exclude 3 Sunday
jb - 18 Nov 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	All Big Frozen Food Pte Ltd
Address	:	1 Senoko Ave Singapore 758297
Telephone	:	HP +65 98192091
Type of Claim	:	Own Damage Claim
Policy No.	:	2100331009-06
Vehicle No	:	**SKJ 1271 U**
Model Code	:	A8 D4 3.0 TFSI QU
Model / Year	:	Feb-13
Engine No	:	CGW 036566
Chassis No	:	WAUZZZ4H2CN027562
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Oct-19
Place of Accident	:	Yishun Ave 9 Towards Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKJ 1271 U

S/n	Nature of Jobs			Estimated Charges		*Surveyor's Recommendation*
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	$	480.00	$	*480.00*
2	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	$	1,400.00	$	*1,400.00*
3	To dismantle and renew front bumper, rhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		$	7,000.00	$	*3,600.00*
4	To respray front bumper, bonnet, rhs front fender and hinges.		$	4,000.00	$	*1,800.00*
5	To carry out diagnostic checks.	S/N	$	192.00	$	*192.00*
	TOTAL LABOUR CHARGES	:		**$13,072.00**		*$7,472.00*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remarks
1	FRONT BUMPER		$ 3,051.00	$ 2,440.80
2	FRONT BUMPER CLOSING ELEMENT		$ 238.00	
3	FRONT BUMPER SPOILER		$ 271.00	
4	FRONT BUMPER WHEEL SPOILER - RH OUTER		$ 40.00	
5	FRONT BUMPER WHEEL SPOILER - RH INNER		$ 32.00	
6	FRONT BUMPER FOAM FILLER PIECE		$ 116.00	$ 92.40
7	FRONT BUMPER CARRIER		$ 987.00	$ 789.60
8	FRONT BUMPER COVER		$ 59.00	$ 47.04
9	FRONT BUMPER COVER		$ 116.00	$ 92.40
10	FRONT BUMPER GUIDE PIECE - RH		$ 48.00	$ 37.68
11	FRONT BUMPER RETAINING BRACKET - LH / RH	2	$ 28.00	
12	FRONT BUMPER TRIM BRACKET - LH / RH	2	$ 32.00	$ 12.72
13	SIGNAL HORN BRACKET		$ 43.00	
14	SIGNAL HORN - LOW TONE		$ 262.00	
15	SIGNAL HORN - HIGH TONE		$ 168.00	
16	FRONT PARKING AID SENSOR	3	$ 629.00	
17	FRONT FENDER - RH		$ 1,681.00	$ 1,344.80
18	FRONT FENDER ATTACHMENT PARTS		$ 260.00	
19	FRONT FENDER REAR BRACKET - RH		$ 26.00	
20	FRONT FENDER BRACE		$ 775.00	$ 620.00
	SUB TOTAL SPARE PARTS CHARGES	:	**$ 8,862.00**	**$ 5,477.44**

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remarks
		c/f			$	5,477.44
21	FRONT FENDER FRONT BRACKET - RH		$	23.00	$	18.00
22	FRONT FENDER CONNECTING PIECE		$	221.00	$	176.80
23	WHEEL HOUSING LINER - RH FRONT		$	276.00		
24	WHEEL HOUSING LINER - RH REAR		$	206.00		
25	BONNET		$	6,055.00	$	4,844.00
26	BONNET ATTACHMENT PARTS		$	240.00		
27	BONNET CATCH HOOK		$	142.00		
28	BONNET LID HINGE - LH / RH	2	$	494.00		
29	BONNET GAS FILLED STRUT	2	$	217.00		
30	BONNET LOCK BAR	2	$	218.00		
31	BONNET SEAL		$	53.00	$	41.92
32	BONNET FLAP GASKET		$	152.00		
33	BONNET HOUSING - LH / RH	2	$	84.00		
34	BONNET LID LOCK	2	$	420.00		
35	MICRO SWITCH - FRONT	2	$	133.00		
36	BONNET COVER	2	$	7.00		
37	CAUTION SIGN STICKER	NEC	$	13.00	$	9.76
38	AIRCON STICKER	NEC	$	18.00	$	14.00
39	FRONT BUMPER GRILLE - LH / RH	2	$	766.00	$	306.00
40	FRONT BUMPER END CAP - RH		$	62.00	$	48.88
	SUB TOTAL SPARE PARTS CHARGES	:	**$**	**9,800.00**	$	10,936.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remarks
	c/f				$	*10,936.80*
41	FRONT BUMPER LICENSE PLATE HOLDER		$	418.00	$	*334.00*
42	RADIATOR GRILLE		$	1,751.00	$	*1,400.80*
43	QUATTRO INSCRIPTION		$	87.00	$	*69.28*
44	RADIATOR GRILLE STRIKER PLATE - UPPER		$	117.00	$	*93.60*
45	RADIATOR GRILLE COVER CAP		$	126.00		
46	RADIATOR GRILLE COVER		$	55.00		
47	RADIATOR GRILLE REINFORCEMENT - LH / RH	2	$	88.00	$	*70.24*
48	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT INNER	2	$	88.00		
49	RADIATOR GRILLE SECURING PLATE		$	75.00		
50	REAR DIGITAL CAMERA		$	902.00	$	*721.20*
51	FRONT HEADLAMP BRACKET	4	$	104.00	$	*41.60*
52	HEADLIGHT - LH / RH	2	$	7,376.00	$	*2,950.40*
53	GAS DISCHARGE LAMP		$	398.00		
54	GAS DISCHARGE LAMP CONTROL UNIT		$	1,051.00		
55	HEADLIGHT VENT HOSE - RH		$	17.00		
56	HEADLIGHT LIFT CYLINDER - LH / RH	2	$	432.00	$	*172.40*
57	HEADLIGHT WASHER HOSE		$	98.00		
58	COOLANT RADIATOR LOCK CARRIER		$	1,031.00	$	*824.80*
59	FRONT CONSOLE CATCH HOOK - CENTRE	2	$	222.00		
60	A/C CONDENSER		$	876.00		
	SUB TOTAL SPARE PARTS CHARGES	:	**$**	**15,312.00**	$	*17,615.12*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1271 U

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remark
		c/f			$	17,615.12
61	PRESSURE SENDER		$	175.00		
62	HIGH PRESSURE PRESSURE RELIEF VALVE		$	48.00		
63	A/C CONDENSER ADAPTER		$	91.00		
64	RADIATOR - REAR CENTRE		$	1,246.00		
65	RADIATOR RUBBER BUSH - UPPER / CENTRE / LOWER	6	$	54.00		
66	ADDITIONAL RADIATOR - FRONT CENTRE		$	1,044.00		
67	READY MIX COOLANT	4	$	84.00	$	67.20
68	TWIN FAN RING		$	400.00		
69	RADIATOR FAN - LH / RH	2	$	5,316.00		
70	RADIATOR AIR GUIDE - LH / RH	2	$	82.00	$	32.24
71	RADIATOR AIR GUIDE		$	37.00		
72	RADIATOR SEALING STRIP - LOWER CENTRE		$	21.00		
73	AIR FILTER		$	486.00		
74	INTAKE MANIFOLD		$	455.00		
75	AIR FILTER RETAINER		$	28.00		
76	INTAKE AIR DUCT		$	47.00	$	37.36
77	INTAKE DUCT		$	62.00		
78	FLANGE		$	38.00		
79	AIR INLET DUCT COVER		$	24.00	$	19.04
80	BONNET ANTI THEFT GUARD COVER - RH		$	13.00		
81	FRONT NO PLATE	S/N	$	40.00	$	40.00
83	*Added parts - see attached*		$	556.00	$	434.16
84	SUNDRIES		$	500.00	$	161.70
	TOTAL SPARE PARTS CHARGES	:	**$**	**44,821.00**	$	18,406.82
	TOTAL LABOUR CHARGES		**$**	**13,072.00**	$	7,472.00
	GRAND TOTAL		**$**	**57,893.00**	$	25,878.82

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 **Attn: Mr. Adrian Ling - Motor Claims Dept** **Tel: 6841 0055 - Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/1185/2019/NS 16-Oct-19 Glory Tan 1 of 1 SKJ 1271 U A8 D4 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	Retaining bracket for lock carrier RHS	$ 16.00	$ 12.32
2	Adapter cable loom camera	$ 384.00	$ 307.20
3	Coupling element for headlight RHS	$ 12.00	
4	Bracket for radiator grille	$ 9.00	$ 6.80
5	Locking clips for radiator	$ 36.00	$ 28.80
6	Securing element for wheel housing liner	$ 99.00	$ 79.04
Labour			
1	To renew cable loom, calibrate camera	FOC	
	TOTAL	**$ 556.00**	**$ 434.16**

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKJ 1271 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1185/2019/NH

17th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Dear Sir,

RE: INSURANCE CLAIM FOR SKJ 1271 U, Audi A8L D4 3.0 TFSI QU.

With reference to the above-mentioned vehicle, no. **SKJ 1271 U,** claimant, **All Big Frozen Food Pte Ltd,** please find the related document per attached.

1. A copy of the Original invoice no. 85014843 – S$ 26,192.32.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKJ 1271 U

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014843
Date : 14/02/2020
Order : SKJ1271U
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SKJ1271U (V 17698) Regn Date: 21/02/2013 Mileage: 129527 WIP No.: 14599

Model: A8L D4 3.0 TFSI QU 4H80VA (YOM Chassis: WAUZZZ4H2CN027562 Engine: CGW 036566 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details		Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.		40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability		-1400.00	1.00	-1,400.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL AIRCON CONDENSER,RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS		1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED		3600.00	1.00	3,600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND RHS FRONT FENDER		1800.00	1.00	1,800.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK		192.00	1.00	192.00
X	A4H0807065E GRU	COVER(LAST)	Less 020%	1.00	3051.00	2,440.80
X	A4H0807694C	(SK)FOAM INSER BORRO	Less 020%	1.00	115.50	92.40
X	A4H0807109B	(SK)BRACKET AP	Less 020%	1.00	987.00	789.60
X	A4H0807217A 01C	(SK)COVER BORROW	Less 020%	1.00	58.80	47.04
X	A4H0807081	COVER AP	Less 020%	1.00	115.50	92.40
X	A4H0821106B	(SK)FENDER	Less 020%	1.00	1681.00	1,344.80
X	A4H0810864B	007497/(V)(SK)BRACKE	Less 020%	1.00	22.50	18.00
X	A4H0821260C	007497/(V)(SK)CONN P	Less 020%	1.00	221.00	176.80

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159936
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 16:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014843
Date : 14/02/2020
Order : SKJ1271U
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SKJ1271U (V 17698) Regn Date: 21/02/2013 Mileage: 129527 WIP No.: 14599

Model: A8L D4 3.0 TFSI QU 4H8OVA (YOM Chassis: WAUZZZ4H2CN027562 Engine: CGW 036566 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details		Qty	Unit Price	Amount
X	A4H0823029E	HOOD(LAST)	Less 020%	1.00	6055.00	4,844.00
X	A4H0823739C	(A)(SK)SEAL 9/10/19	Less 020%	1.00	52.40	41.92
X	A4H0823188	COVER	Less 020%	2.00	3.20	5.12
X	A8K0010520A	STICKER	Less 020%	1.00	12.20	9.76
X	A4H0010515P	STICKER(LAST)	Less 020%	1.00	17.50	14.00
X	A4H0807680M T94	(A)(SK)GRILLE 9/10/1	Less 020%	1.00	382.50	306.00
X	A4H0807152	(SK)COVER BORROW AP	Less 020%	1.00	61.10	48.88
X	A4H0807285Q T94	007477/(V)(GER)BRACK	Less 020%	1.00	417.50	334.00
X	A4H0853651H T94	GRILLE(LAST)	Less 020%	1.00	1751.00	1,400.80
X	A4H0853736 2ZZ	NAME PLATE(LAST)	Less 020%	1.00	86.60	69.28
X	A4H0853692	(A)(SK)PLATE 16/10/1	Less 020%	1.00	117.00	93.60
X	A4H0853479	(A)(SK)REINFORCE 16/	Less 020%	1.00	43.90	35.12
X	A4H0853480	(A)(SK)REINFORCE 16/	Less 020%	1.00	43.90	35.12
X	A7P6980551C	007497/(V)(SK)CAMERA	Less 020%	1.00	901.50	721.20
X	A4E0941455	(A)(SK)BRACKET AP 17	Less 020%	2.00	26.00	41.60
X	A4H0941030AC	(A)(SK)HEADLAMP 9/10	Less 020%	1.00	3688.00	2,950.40
X	A4H0955102D	CYLINDER	Less 020%	1.00	215.50	172.40
X	A4H0805594E	CARRIER(LAST) AP	Less 020%	1.00	1031.00	824.80
X	AG A13040M2	COOLANT AP	Less 020%	4.00	21.00	67.20
X	A4H0121284E	007497/(V)(SK)AIR DU	Less 020%	1.00	40.30	32.24
X	A4H0129628AB	(A)(SK)AIR DUCT 16/1	Less 020%	1.00	46.70	37.36
X	A4H0129666C	(A)(SK)COVER 16/10/1	Less 020%	1.00	23.80	19.04
X	A4H0853993A	BRACKET AP	Less 020%	1.00	8.50	6.80
X	A7L5018897A	CLIP AP	Less 020%	10.00	3.60	28.80
X	A8E0821989A	FASTENING AP	Less 020%	2.00	49.40	79.04
X	A4H0941454	PLATE AP	Less 020%	1.00	19.50	15.60
X	A4H0121081AB	TUBE AP	Less 020%	1.00	46.70	37.36
X	A4H0807136C	007497/(V)(SK)HOLDER	Less 020%	1.00	15.90	12.72
X	AN 91095301	007497/(V)(SK)BOLT A	Less 020%	1.00	1.70	1.36
X	AN 91195601	007497/(V)(SK)BOLT A	Less 020%	1.00	5.00	4.00
X	A4H0971192B	007497/(V)(SK)HARNES	Less 020%	1.00	384.00	307.20
X	A4H0807283	GUIDE AP	Less 020%	1.00	47.10	37.68
X	A4H0805638	BRACKET	Less 020%	1.00	15.40	12.32
X	A4E0805831	NUT	Less 020%	1.00	5.00	4.00

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 16:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014843
Date : 14/02/2020
Order : SKJ1271U
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SKJ1271U (V 17698) Regn Date: 21/02/2013 Mileage: 129527 WIP No.: 14599

Model: A8L D4 3.0 TFSI QU 4H80VA (YOM Chassis: WAUZZZ4H2CN027562 Engine: CGW 036566 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details		Qty	Unit Price	Amount
X	A4E0805949	BANJO BOLT	Less 020%	1.00	8.30	6.64
X	A4H0807284	GUIDE	Less 020%	1.00	47.10	37.68
X	A4H0821136F	SUPPORT	Less 020%	1.00	775.00	620.00
X	A4F0601165N	WHEEL CAP	Less 020%	1.00	62.40	49.92

Parts	18,366.80
Labour	0.00
Sublet	7,512.00
Menus	0.00
Lubricant	0.00

Sub-Total	24,478.80
7% GST	1,713.52
Grand Total	26,192.32

PREMIUM AUTOMOBILES PTE LTD

14/2

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKJ 1271 U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1185/2019/KK
30 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model	:	Audi A8L D4 3.0 TFSI QU
Vehicle Chassis No.	:	WAUZZZ4H2CN027562
Vehicle Regn No.	:	**SKJ 1271 U**
Vehicle Mileage	:	139850 KM
Vehicle Owner	:	All Big Frozen Food Pte Ltd
Certificate No	:	2100331009-06
Own Damage Excess	:	S$ 1,498.00 (Inclusive 7% GST)
Accident Date	:	02/10/2019
Place	:	Yishun Ave 9 Towards Ave 6
Repair Cost	:	$ 26,192.32
WIP No.	:	14599
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

ALL BIG FROZEN FOOD PTE LTD

Owner / Insured Signature : _____

Time : _____

Date : 31/10

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019		03 Oct 2019 14:17 Edit Adj Rpt	**S$25,878.80** Edit Estimates	**S$25,878.80** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by Insurer]**

Insured:	**ALL BIG FROZEN FOOD PTE LTD**, Co. Reg. No.: 199105822M, Tel: +6598192091		
Vehicle Reg. No.:	**SKJ1271U**	Date of Loss:	02/10/2019 00:00 - :59 [**79** Months and **11** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 8700726175SG	Policy/Cover Note No.:	2100331009 (Comprehensive)
		Excess:	S$1,400.00
Repairer:	**Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Khoo, Kay-Eng** - 6419 1026] Kay-Eng.Khoo@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 14/10/2019]		
Driver/Custodian:	WEE MENG TECK (56 / Male) , NRIC: S1561616D, Tel: +6598192091 Email: VINCENT@ALLBIG.COM.SG		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (05/12/2019): **Alert - Adj Mandate Approved (S$25878.82) - SKJ1271U - Claim Handler: Khoo, Kay-...**
- AIG_SG (21/10/2019): **Alert - Adj Mandate Approved (S$24089.00) - SKJ1271U - Claim Handler: Khoo, Kay-...**
- AIG_SG (07/10/2019): **Alert - Adj Mandate Approved (S$23533.00) - SKJ1271U - Claim Handler: Mithoo Sin...**
- AIG_SG (04/10/2019): **SKJ1271U / OD / 02/10/2019 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SKJ1271U (8700726175SG)**
OD
Oct 2 2019 12:00AM
[ALL BIG FROZEN FOOD PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/10/19 09:32	**Adjuster Immediate Advice**		Load HTM	
2	21/10/19 10:49	**Adjuster Immediate Advice**		Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/10/19 09:33	**General View**		Load JPG	☑
2	04/10/19 09:33	**General View**		Load JPG	☑
3	04/10/19 09:33	**General View**		Load JPG	☑
4	04/10/19 09:33	**General View**		Load JPG	☑
5	04/10/19 09:33	**General View**		Load JPG	☑
6	04/10/19 09:33	**General View**		Load JPG	☑
7	04/10/19 09:33	**General View**		Load JPG	☑
8	04/10/19 09:33	**General View**		Load JPG	☑
9	04/10/19 09:33	**General View**		Load JPG	☑
10	04/10/19 09:33	**General View**		Load JPG	☑
11	04/10/19 09:33	**General View**		Load JPG	☑
12	04/10/19 09:33	**General View**		Load JPG	☑
13	04/10/19 09:33	**General View**		Load JPG	☑
14	04/10/19 09:33	**General View**		Load JPG	☑
15	04/10/19 09:33	**General View**		Load JPG	☑
16	04/10/19 09:33	**General View**		Load JPG	☑
17	04/10/19 09:33	**General View**		Load JPG	☑
18	04/10/19 09:33	**General View**		Load JPG	☑
19	04/10/19 09:33	**General View**		Load JPG	☑
20	04/10/19 09:33	**General View**		Load JPG	☑
21	04/10/19 09:33	**General View**		Load JPG	☑
22	04/10/19 09:33	**General View**		Load JPG	☑
23	04/10/19 09:33	**General View**		Load JPG	☑
24	04/10/19 09:33	**General View**		Load JPG	☑
25	04/10/19 09:33	**General View**		Load JPG	☑
26	04/10/19 09:33	**General View**		Load JPG	☑
27	04/10/19 09:33	**General View**		Load JPG	☑
28	04/10/19 09:33	**General View**		Load JPG	☑
29	04/10/19 09:33	**General View**		Load JPG	☑
30	04/10/19 09:33	**General View**		Load JPG	☑
31	04/10/19 09:33	**General View**		Load JPG	☑
32	04/10/19 09:33	**General View**		Load JPG	☑
33	04/10/19 09:33	**General View**		Load JPG	☑
34	04/10/19 09:33	**General View**		Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
35	21/10/19 10:50	Reinspection Photo	1	Load JPG	☑
36	21/10/19 10:50	Reinspection Photo	1	Load JPG	☑
37	21/10/19 10:50	Reinspection Photo	1	Load JPG	☑
38	21/10/19 10:50	Reinspection Photo	1	Load JPG	☑
39	21/10/19 10:50	Reinspection Photo	1	Load JPG	☑
40	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
41	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
42	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
43	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
44	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
45	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
46	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
47	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
48	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
49	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
50	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
51	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
52	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
53	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
54	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
55	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
56	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
57	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
58	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
59	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
60	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
61	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
62	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
63	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
64	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
65	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
66	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
67	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
68	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
69	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
70	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
71	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
72	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
73	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
74	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
75	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
76	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
77	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
78	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
79	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
80	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑
81	21/10/19 10:51	Reinspection Photo	1	Load JPG	☑

Documentation			1 per page		☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/10/19 15:46	Driver's Driving License		Load PDF	

Assessment Reports			1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	03/10/19 15:46	Singapore Accident Statement		Load PDF	
3	04/10/19 09:43	estimate		Load PDF	
4	04/10/19 14:14	Certificate of Insurance		Load PDF	
5	21/10/19 10:45	SUPPLEMANTARY		Load PDF	
6	21/02/20 16:17	Workshop Invoice		Load PDF	
7	21/02/20 16:17	Discharge Voucher		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	06/12/19 18:44	Accident Statement		Load HTM	
2	06/12/19 18:45	Accident Statement		Load HTM	
3	06/12/19 18:47	Accident Statement		Load HTM	
4	06/12/19 18:48	Accident Statement		Load HTM	

Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/10/19 09:45	Accident Photo		Load JPG	☑
2	03/10/19 09:45	Accident Photo		Load JPG	☑
3	03/10/19 09:45	Accident Photo		Load JPG	☑
4	03/10/19 09:45	Accident Photo		Load JPG	☑
5	03/10/19 09:45	Accident Photo		Load JPG	☑
6	03/10/19 09:45	Accident Photo		Load JPG	☑
7	03/10/19 09:45	Accident Photo		Load JPG	☑
8	03/10/19 09:45	Accident Photo		Load JPG	☑
9	03/10/19 09:45	Accident Photo		Load JPG	☑
10	03/10/19 09:45	Accident Photo		Load JPG	☑
11	03/10/19 09:45	Accident Photo		Load JPG	☑
12	03/10/19 09:45	Accident Photo		Load JPG	☑
13	03/10/19 09:45	Accident Photo		Load JPG	☑
14	03/10/19 09:45	Accident Photo		Load JPG	☑
15	03/10/19 09:45	Accident Photo		Load JPG	☑
16	03/10/19 09:45	Accident Photo		Load JPG	☑
17	03/10/19 09:45	Accident Photo		Load JPG	☑
18	03/10/19 09:45	Accident Photo		Load JPG	☑
19	03/10/19 09:45	Accident Photo		Load JPG	☑
20	03/10/19 09:45	Accident Photo		Load JPG	☑
21	03/10/19 09:45	Accident Photo		Load JPG	☑
22	03/10/19 09:45	Accident Photo		Load JPG	☑
23	03/10/19 09:45	Accident Photo		Load JPG	☑
24	03/10/19 09:45	Accident Photo		Load JPG	☑
25	03/10/19 09:45	Accident Photo		Load JPG	☑

Documentation			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/10/19 09:47	Sketch Plan		Load JPG	☑
2	03/10/19 09:47	Sketch Plan #2		Load JPG	☑

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017421/ATF3E2
Date: 21/02/2020

REFERENCE

Insured/Claimant:	ALL BIG FROZEN FOOD PTE LTD	Policy No:	2100331009		
Date of Loss:	02/10/2019	Nature of Claim:	OD	Claim No:	8700726175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SKJ1271U**		
Make & Model:	AUDI A8L, 3.1 FSI (D3) (A)	Engine No:	CGW036566
Reg. Date:	21/02/2013 (Man. Year: 2012)	Chassis No:	WAUZZZ4H2CN027562
Colour:	Blue	Odometer:	139829 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S$120,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,711.16	18,406.80	26,304.36	58.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,072.00	7,472.00	5,600.00	42.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**57,783.16**	**25,878.80**	**31,904.36**	**55.21**
- Excess (S$)	1,400.00	1,400.00	0.00	0.00
(S$)	56,383.16	24,478.80	31,904.36	56.58
+ GST 7.00/7.00% (S$)	3,946.82	1,713.52	2,233.30	56.58
Nett Amount (S$)	**60,329.98**	**26,192.32**	**34,137.66**	**56.58**

INSPECTION

Date of Assignment:	03/10/2019		
Date Inspected:	03/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,051.00 FS	*2,440.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	238.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Not Necessary	271.00 FS	*- FS
4	1		*FRONT BUMPER WHEEL SPOILER - RH OUTER	Not Necessary	40.00 FS	*- FS
5	1		*FRONT BUMPER WHEEL SPOILER - RH INNER	Not Necessary	32.00 FS	*- FS
6	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	116.00 FS	*92.40 FS
7	1		*FRONT BUMPER CARRIER	Bent	987.00 FS	*789.60 FS
8	1		*FRONT BUMPER COVER	Damaged	59.00 FS	*47.04 FS
9	1		*FRONT BUMPER COVER	Damaged	116.00 FS	*92.40 FS
10	1		*FRONT BUMPER GUIDE PIECE - RH	Damaged	48.00 FS	*37.68 FS
11	2		*FRONT BUMPER RETAINING BRACKET - LH / RH	Not Necessary	28.00 FS	*- FS
12	2		*FRONT BUMPER TRIM BRACKET - LH / RH	Necessary	32.00 FS	*12.72 FS
13	1		*SIGNAL HORN BRACKET	Not Necessary	43.00 FS	*- FS
14	1		*SIGNAL HORN - LOW TONE	Not Necessary	262.00 FS	*- FS
15	1		*SIGNAL HORN - HIGH TONE	Not Necessary	168.00 FS	*- FS
16	3		*FRONT PARKING AID SENSOR	Not Necessary	629.00 FS	*- FS
17	1		*FRONT FENDER - RH	Buckled	1,681.00 FS	*1,344.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	260.00 FS	*- FS
19	1		*FRONT FENDER REAR BRACKET - RH	Not Necessary	26.00 FS	*- FS
20	1		*FRONT FENDER BRACE	Bent	775.00 FS	*620.00 FS
21	1		*FRONT FENDER FRONT BRACKET - RH	Bent	23.00 FS	*18.00 FS
22	1		*FRONT FENDER CONNECTING PIECE	Bent	221.00 FS	*176.80 FS
23	1		*WHEEL HOUSING LINER - RH FRONT	Not Necessary	276.00 FS	*- FS
24	1		*WHEEL HOUSING LINER - RH REAR	Not Necessary	206.00 FS	*- FS
25	1		*BONNET	Distorted	6,055.00 FS	*4,844.00 FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	240.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	142.00 FS	*- FS
28	2		*BONNET LID HINGE - LH / RH	Not Necessary	494.00 FS	*- FS
29	2		*BONNET GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
30	2		*BONNET LOCK BAR	Not Necessary	218.00 FS	*- FS
31	1		*BONNET SEAL	Necessary	53.00 FS	*41.92 FS
32	1		*BONNET FLAP GASKET	Not Necessary	152.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	2		*BONNET HOUSING - LH / RH	Not Necessary	84.00 FS	*- FS
34	2		*BONNET LID LOCK	Not Necessary	420.00 FS	*- FS
35	2		*MICRO SWITCH - FRONT	Not Necessary	133.00 FS	*- FS
36	2		*BONNET COVER	Not Necessary	7.00 FS	*- FS
37	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
38	1		*AIRCON STICKER	Necessary	18.00 FS	*14.00 FS
39	1		*FRONT BUMPER GRILLE - LH / RH	O/S Damaged	766.00 FS	*306.00 FS
40	1		*FRONT BUMPER END CAP - RH	Damaged	62.00 FS	*48.88 FS
41	1		*FRONT BUMPER LICENSE PLATE HOLDER	Cracked	418.00 FS	*334.00 FS
42	1		*RADIATOR GRILLE	Cracked	1,751.00 FS	*1,400.80 FS
43	1		*QUATTRO INSCRIPTION	Cracked	87.00 FS	*69.28 FS
44	1		*RADIATOR GRILLE STRIKER PLATE - UPPER	Cracked	117.00 FS	*93.60 FS
45	1		*RADIATOR GRILLE COVER CAP	Not Necessary	126.00 FS	*- FS
46	1		*RADIATOR GRILLE COVER	Not Necessary	55.00 FS	*- FS
47	2		*RADIATOR GRILLE REINFORCEMENT - LH / RH	Damaged	88.00 FS	*70.22 FS
48	2		*RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT INNER	Not Necessary	88.00 FS	*- FS
49	1		*RADIATOR GRILLE SECURING PLATE	Not Necessary	75.00 FS	*- FS
50	1		*REAR DIGITAL CAMERA	Damaged	902.00 FS	*721.20 FS
51	1		*FRONT HEADLAMP BRACKET (4PCS)	O/S Damaged	104.00 FS	*41.60 FS
52	1		*HEADLIGHT - LH / RH	O/S Cracked	7,376.00 FS	*2,950.40 FS
53	1		*GAS DISCHARGE LAMP	Not Necessary	398.00 FS	*- FS
54	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,051.00 FS	*- FS
55	1		*HEADLIGHT VENT HOSE - RH	Not Necessary	17.00 FS	*- FS
56	1		*HEADLIGHT LIFT CYLINDER - LH / RH	O/S Cracked	432.00 FS	*172.40 FS
57	1		*HEADLIGHT WASHER HOSE	Not Necessary	98.00 FS	*- FS
58	1		*COOLANT RADIATOR LOCK CARRIER	Cracked	1,031.00 FS	*824.80 FS
59	2		*FRONT CONSOLE CATCH HOOK - CENTRE	Not Necessary	222.00 FS	*- FS
60	1		*A/C CONDENSER	Not Necessary	876.00 FS	*- FS
61	1		*PRESSURE SENDER	Not Necessary	175.00 FS	*- FS
62	1		*HIGH PRESSURE RELIEF VALVE	Not Necessary	48.00 FS	*- FS
63	1		*A/C CONDENSER ADAPTER	Not Necessary	91.00 FS	*- FS
64	1		*RADIATOR - REAR CENTRE	Not Necessary	1,246.00 FS	*- FS
65	6		*RADIATOR RUBBER BUSH - UPPER / CENTRE / LOWER	Not Necessary	54.00 FS	*- FS
66	1		*ADDITIONAL RADIATOR - FRONT CENTRE	Not Necessary	1,044.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
67	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
68	1		*TWIN FAN RING	Not Necessary	400.00 FS	*- FS
69	2		*RADIATOR FAN - LH / RH	Not Necessary	5,316.00 FS	*- FS
70	1		*RADIATOR AIR GUIDE - LH / RH	O/S Damaged	82.00 FS	*32.24 FS
71	1		*RADIATOR AIR GUIDE	Not Necessary	37.00 FS	*- FS
72	1		*RADIATOR SEALING STRIP - LOWER CENTRE	Not Necessary	21.00 FS	*- FS
73	1		*AIR FILTER	Not Necessary	486.00 FS	*- FS
74	1		*INTAKE MANIFOLD	Not Necessary	455.00 FS	*- FS
75	1		*AIR FILTER RETAINER	Not Necessary	28.00 FS	*- FS
76	1		*INTAKE AIR DUCT	Deformed	47.00 FS	*37.36 FS
77	1		*INTAKE DUCT	Not Necessary	62.00 FS	*- FS
78	1		*FLANGE	Not Necessary	38.00 FS	*- FS
79	1		*AIR INLET DUCT COVER	Damaged	24.00 FS	*19.04 FS
80	1		*BONNET ANTI THEFT GUARD COVER - RH	Not Necessary	13.00 FS	*- FS
81	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
82	1		*SUNDRIES	Necessary	500.00 FS	*161.70 FS
83	1		*RETAINING BRACKET FOR LOCK CARRIER RHS	Cracked	12.32 FS	*12.32 FS
84	1		*ADAPTER CABLE LOOM CAMERA	Cracked	307.20 FS	*307.20 FS
85	1		*COUPLING ELEMENT FOR HEADLIGHT RHS	Not Necessary	12.00 FS	*- FS
86	1		*BRACKET FOR RADIATOR GRILLE	Necessary	6.80 FS	*6.80 FS
87	1		*LOCKING CLIPS FOR RADIATOR	Necessary	28.80 FS	*28.80 FS
88	1		*SECURING ELEMENT FOR WHEEL HOUSING LINER	Necessary	79.04 FS	*79.04 FS
				Total Parts (S$)	**44,711.16**	**18,406.80**

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	3,600.00
4	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND HINGES	New	4,000.00	1,800.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
		Gross Labour Cost (S$)	**13,072.00**	**7,472.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >