LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref :	CC4/ASM19017720/Upa3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG		Date :	09-07-2020
		Code :	ASM

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	XB 9368K	Veh. Inspected	SMM 7435K
	Policy No.	GA447784/1	Coverage ($)	0.00
	Claim No.	S9M022UN	Excess ($)	0.00
	Assign From	RICHARD ANG	Assign Date	08/10/2019

2.	Vehicle Particulars & Condition			
	Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053ZEE106174718	Colour	WHITE
	Odometer	138501	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.

5.	General Information		
	Accident Date	05/10/2019	Inspection Date 08/10/2019
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586	

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair
	ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**