Surveyor H. ANIN | REF: III

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Focus Auto pte Ltd

of 1 Kaki Bukit Ave 6 #02-48/50

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

cecelia case

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3-4 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: YP 3469 G Yr Regn: 4/08/2016.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: mit Fuso FK62FM22RDEB c.c 7545

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 78256km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FK62FMA30111.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl : NII / S/Rim / STD A/Rim or

Tyre Size: F: 245/70/R 19.5

R: 245/70/R 19.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm FALKEN	R/Bal.	6 mm FALKEN x2
L/Bal.	6 mm FALKEN	L/Bal.	6 mm FALKEN x2
D.O.A.	7/10/19	D.O.I.	15/10/19

Survey held at Focus Auto

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* YP 3469 G have Estimate case. NON completed File
	MV – 166000
	PV – 17920
	NV – 148000

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

(S + RS. – SI)

(Photos)

(Others)

(..)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)