ASS. REC. BY: | REF: CS/CTI/9018813/AS d3s2 | Special Instruction:

Surveyor: Adhan

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 23/10/19 @ 2.30pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDA 3535B Insured: WC 6593C

at Workshop m/s Cycle & Carriage Fulco Tel: 91792566

of 330 Ubi Road 3

Policy No: Claim No: SNM19D205012

Sum Insured: Excess:

Make of Veh: D.O.A. 22/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 4.27pm @ 23/10/19 Person Contacted: MCKS Vehicle IN / OUT

Date/Time	Action/Instruction Estimate ✓
	SDA 3535B - CS/CTI/8014639/Uhb3XX DOA: 10/8/2018
	WC 6593C - CS/CTI/9013029/Rly7362 DOA: 28/6/2019

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From: Date: 25/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDA 3535B

at Workshop m/s Cycle & Carriage Fulco

of 330 Ubi Road 3

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10.30am (waiting) Marsher

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS 1up

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SDA3535B Yr Regn: 2019 / Oct.

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Mit Attrage c.c 1193

Colour Red. A/C: **Insured / Std / NI / NA**

Sp.Reading 2691 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: MMBSTA13AKH 003396

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 185/55R15.

R: 185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	06	mm	R/Bal.	06	mm
L/Bal.	06	mm	L/Bal.	06	mm
D.O.A.			D.O.I.	25/10/19	

Survey held at Cycle and Carriage (Ubi)

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Rees o/s.

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	TP China.
	Adrian Confirmed P/P $ 4,055.39 @ 5 days with Marsher. ($ 9,184.61 Red - 69%)

RECEIVED 11 DEC 2019

Date/Time, File Pass to? 11/12/19

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

__S + RS __SF

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B. : ($ 4,055.39 p/p)

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 23 October 2019 2:30 PM
To: Mars Ler; assignments
Cc: Chris Bulaclac; Renemer Bagang
Subject: RE: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C

WITHOUT PREJUDICE

Dear Mars,

We refer to your email dated 23.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mars Ler [mailto:mars.ler@ccfulco.com.sg]
Sent: Wednesday, October 23, 2019 2:24 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>
Subject: RE: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C

Dear Kah Leong ,

Please kindly arrange **LKK-Marcus Chua** for conduct Pre-survey .

Thank you,

Best regards

Mars Ler

Senior Advisor - Motor Claims
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

From: Tan Kah Leong [mailto:KahLeong.Tan@sg.cntaiping.com]
Sent: Wednesday, 23 October 2019 2:11 PM
To: Mars Ler
Subject: RE: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C

Without Prejudice

Dear Mars,

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, October 23, 2019 2:02 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; mars.ler@ccfulco.com.sg
Subject: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C

Dear Kah Leong,

Please conduct PRS for SDA3535B.

Note : officer In charge – Kah Leong.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mars Ler [mailto:mars.ler@ccfulco.com.sg]
Sent: Tuesday, 22 October, 2019 7:42 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>
Subject: Re:Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C

Dear Motor Claims ,

Our client is looking to make a claim against your insurer for property damage caused to her vehicle.

Please confirm if your insurance company is prepared to engage in a direct settlement for property damage only.

This settlement excludes out client's right to recover further loss arising from rental of alternative / replacement vehicle.

As our client requires the use of a vehicle during this period that her vehicle is in our workshop, our client has will rented a vehicle and will be looking towards your company to make good her loss/rental cost.

Please confirm that you understand that any direct settlement reached for the cost of repairs to our client's vehicle does not prejudice her rights to recover any other damages he has suffered.

Please arrange for Pre-survey (Advance notice required 1 day ,vehicle with customer)

Thank you,

Best regards

Mars Ler
Senior Advisor - Motor Claims
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 11 December 2019 12:16 pm
To: 'Mars Ler (mars.ler@ccfulco.com.sg)'
Cc: 'Chris Bulaclac'; 'Renemer Bagang'; SUR
Subject: RE: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C Before Paint & Finalization

Dear Mars,

Confirmed final fig $ 4,055.39 @ 5 days of repairs.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Saturday, 16 November 2019 11:19 am
To: 'Mars Ler (mars.ler@ccfulco.com.sg)' <mars.ler@ccfulco.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Chris Bulaclac' <chris.bulaclac@ccfulco.com.sg>; 'Renemer Bagang' <renemer.bagang@ccfulco.com.sg>
Subject: FW: OUR REF: SNM19D205012-WC6593C-TKL-Accident On 22/10/2019 Involving Our Insured SDA3535B And Your Insured WC6593C Before Paint & Finalization

Dear Shirely,

Kindly assist. CS/CTI19018813/Asd3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/10/2019 18:32
Date Of Accident	22/10/2019 08:45
Exact Location Of Accident	EAST COAST PARK SERVICE RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDA3535B
Insured/Policyholder	
Name Of Registered Owner	TEOH CHENG LEONG FABIAN
NRIC No	S7046749F
Email Address	FABIANTEOH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96953909
Alternative Phone No	OTHERS-96953909
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900161044
Cover Note Number	
Driver	
Name of Driver	TEOH CHENG LEONG FABIAN
NRIC No	S7046749F
Date Of Birth	28/12/1970
Occupation	OUTDOOR
Date Of Driving Pass	22/11/1993
Driving Experience	25 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96953909
Fax Number	
Contact Number	OTHERS-96953909
EMail Address	FABIANTEOH@HOTMAIL.COM

Address	BLK 285 TAMPINES STREET 22 #06-217 SINGAPORE
Postcode	520285
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

ON 22/10/2019@ABOUT 0844HRS,I WAS TRAVELLING ALONG EAST COAST PARK SERVICE ROAD NEAR ECP COVE TOWARDS CITY.ONE CONCRETE MIXER WC6593C,TURNED RIGHT FROM SLIP ROAD.THE SAID MIXER CUT THROUGH A DOUBLE WHITE LINE AND COLLIDED INTO THE RIGHT REAR OF MY VEHICLE SDA3535B.THE RAIN HAS STOPPED BUT THE ROAD WAS WET.ALSO DISCOVERED THAT THE CONCRETE MIXER LEFT WINDOWS WERE COVERED BY CURTAIN.THE DRIVER OF THE CONCRETE MIXER IS CHINNATHAMBI MANOHARAN,LICENSE NO.F8047724N.SDA3535B RIGHT REAR BODY DENTED,BUMPER DENTED AND REAR RIGHT TAILLIGHTS,ETC WERE DAMAGE.THE CONCRETE MIXER SEEMS TO HAVE NO DAMAGE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6593C
Vehicle Make/Model/Colour	ISUZU CONCRETE MIXER TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHINNATHAMBI MANOHARON
NRIC/Passport Number	F8047724N
Contact Number	84517872
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time: 22/10/19. 1045 hrs	(If driver is not the policyholder)	Name:
	Date & Time:	NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/10/19 @ about 0844 hrs, I was travelling along East Coast Park Service Road near ECP Cove towards City. One concrete mixer, WC 6593 C, turned right from slip road. The said mixer cut through a double white line and collided into the right rear of my vehicle SDA3535B. The rain has stopped but the road was wet. Also discovered that the concrete mixer left windows were covered by curtain. The driver of the concrete mixer is Chinnathambi Manoharan, Licence No. F8047722 N. SDA3535B right rear body dented, bumper dented and rear right tail lights were damage. The concrete mixer seems to have no damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 22/10/19. 1045 hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SERVICE

AIG

CERTIFICATE OF INSURANCE

RIDE SHARE PRIVATE VEHICLE

Name of Policyholder : Teoh Cheng Leong Fabian
Period of Insurance : 08 Oct 2019 To 07 Oct 2020
Engine No. : 3A92UJB1499
Chassis No. : MMBSTA13AKH003396

Vehicle No. : SDA3535B
Policy No. : 1900161044
Endorsement No. :
Issued Date : 09 Oct 2019

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Sum Insured : Market Value
First Year of Registration : 2019
Driver Restriction : NA
Off Peak Car : No
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

When the Vehicle is used for the carriage of passenger for hire or reward, such authorised driver must be named under the Policy and registered with an intermediary which facilitates the carriage of passengers for hire or reward.

You have to pay an additional sum of $3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use for social, domestic, pleasure purposes and business purposes of any person to whom the Vehicle is hired.
Use for the carriage of passengers for hire or reward by any person to whom the Vehicle is hired.
This Policy does not cover
1) use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing;
2) use whilst drawing a trailer except the towing (other than for reward) of anyone disabled using a mechanically propelled vehicle; and
3) use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - $0 Own Damage - $1800 Theft - $0 Flood Cover - $1800

Section 2
Property Damage - $2000

Windscreen : $100

Named Driver and Excess (where applicable)

Teoh Cheng Leong Fabian - $1800 (Own Damage) $2000 (Property Damage), $1800 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

If the vehicle is used for the carriage of passenger for hire or reward, such driver must be named under the Policy and registered with an intermediary which facilitates the carriage of passengers for hire or reward. Should you decide to include any other driver, please contact us. (Company reserves the right to accept/reject the inclusion of any Named Drivers)

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV o the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500722050

C&C FULCO-CORPORATE
22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617 ANSP-MOTOR
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE
Chin E

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-174474
Date of Request: 22/10/2019 Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 22/10/2019
Enquiry By Mars Ler Yeong Cherng
TP Vehicle No. WC6593C
Accident Date 22/10/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
WC6593C	China Taiping Insurance (Singapore) Pte. Ltd.	07/03/2019-06/03/2020	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-174474
Date of Request: 22/10/2019
Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 22/10/2019
Enquiry By Mars Ler Yeong Cherng
TP Vehicle No. WC6593C
Accident Date 22/10/2019

DESCRIPTION	AMOUNT (S$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
[X] GIRO [ ] Cash [ ] Cheque

CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MITSUBISHI MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. **Contact No** 63896111	**Cust No/Name**	KCV12209/Mr Teoh Cheng Leong Fabian
	Reg No/Reg Date	SDA3535B / 08/10/2019
	Date In/Mileage	22/10/2019/ 0
	Chassis No	MMBSTA13AKH003396
	Engine No	3A92UJB1499
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	22/10/2019/ 19:38	DS	218 / MarsLer	35142

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S	MIPNT88088 ZERTONA PAINT PROTECTION				234.39 ~~550.00~~
S	MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S	MIPNT88088 TO CHECK LIGHITNG AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				82 ~~100.00~~
S	MIPNT88088 TO REPLACE REAR WINDSCREEN GLASS				300.00
M	SUNDRY SEALANT KIT ON REAR WINDSCREEN GLASS				100.00
S	MIPNT88088 TO INSTALL RIKE COOL SOLAR FILM ON REAR WINDSCREEN GLASS				220.00
S	MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING & CAPERTING & ROOF LINING TO GIVE WAY FACILATATE ACCESS RENEWEL RHR QTR OTR PNL				300 ~~1200.00~~
S	MIPNT88088 TO REPLACE REAR BUMPER,ETC -CUT AND RE-WELD REAR END PANEL AND RHR OTR QTR PANEL STRAIGHTEN,REFORM,ALIGN ON RHR ACCIDENT AFFECTED AREAS				1200 ~~4800.00~~
S	MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				300.00
S	MIPNT88088 REVERSE SENSOR SET				280.00
S	MIPNT98088 SPRAY PAINTING ON RR & RHR ACCIDENT AFFECTED AREAS				840 ~~2100.00~~
P	JJ6410C750 FACE, RR BUMPER Del'd	1.00	748.00	0.00	748.00
P	JJ6410C433 LH BRACKET, RR BUMPE New	1.00	28.00	0.00	28.00
P	JJ6410C434 RH BRACKET, RR BUMPE New	1.00	28.00	0.00	28.00
P	JJMU001623 CLIP,RR BUMPER New	10.00	4.00	0.00	40.00
M	JJ5370B566 MUD GUARD,RR RH New	1.00	36.00	0.00	36.00
M	JJ5281A631 PANEL,RR END Repair	1.00	425.00	0.00	425.00
M	JJ5301F968 PANEL,QTR,OTR RH Repair	1.00	763.00	0.00	763.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MITSUBISHI MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. **Contact No** 63896111	**Cust No/Name**	KCV12209/Mr Teoh Cheng Leong Fabian
	Reg No/Reg Date	SDA3535B / 08/10/2019
	Date In/Mileage	22/10/2019/ 0
	Chassis No	MMBSTA13AKH003396
	Engine No	3A92UJB1499
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	22/10/2019/ 19:38	DS	218 / MarsLer	35142

	Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	JJ5301F976	RH TAILLAMP PANEL	1.00	60.00	0.00	+ 60.00
M	JJ6131A233	GLASS,RR WINDOW	1.00	544.00	0.00	> 544.00
M	JJMR462285	STOPPER,WINDSHIELD G	2.00	3.00	0.00	+ 6.00
M	JJ6102A405	SPACER,RR WINDOW	3.00	9.00	0.00	+ 27.00
P	JJ8330A852	RH RR LAMP ASSY, COM	1.00	335.00	0.00	— 335.00
Z	NOTES					

ACCIDENT ON 22/10/2019 ALONG EAST COAST PARK SERVICE RD
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # WC6593C TP INS : CHINA TAIPING

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim
P/P 25/10/19.
05 Days

Confirm & accepted by

Parts	3,040.00
Labour	0.00
Standard Menu	0.00
Specialist Job	10,100.00
Others(Lub,etc)	0.00
Sundry	100.00
Total(w/o GST)	13,240.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MITSUBISHI MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	KCV12209/Mr Teoh Cheng Leong Fabian
	Reg No/Reg Date	SDA3535B / 08/10/2019
	Date In/Mileage	04/11/2019/ 4771
	Chassis No	MMBSTA13AKH003396
	Engine No	3A92UJB1499
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	14/11/2019/ 10:11	DS	218 / MarsLer	35142

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S	MIPNT88088 ZERTONA PAINT PROTECTION				234.39
S	MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S	MIPNT88088 TO CHECK LIGHITNG AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S	MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING & CAPERTING TO GIVE WAY ACCESS REPAIR ON RHR OTR QTR PNL				300.00
S	MIPNT88088 TO REPLACE REAR BUMPER,ETC -REPAIR REAR END PANEL AND RHR OTR QTR PANEL STRAIGHTEN,REFORM,ALIGN ON RHR ACCIDENT AFFECTED AREAS				1200.00
S	MIPNT98088 SPRAY PAINTING ON RR & RHR ACCIDENT AFFECTED AREAS				840.00
X	JJ6410C750 FACE, RR BUMPER	1.00	748.00	0.00	748.00
X	JJ6410C434 RH BRACKET, RR BUMPE	1.00	28.00	0.00	28.00
X	JJMU001623 CLIP,RR BUMPER	10.00	4.00	0.00	40.00
X	JJ8330A852 RH RR LAMP ASSY, COM	1.00	335.00	0.00	335.00
Z	NOTES ACCIDENT ON 22/10/2019 ALONG EAST COAST PARK SERVICE RD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR (R/A-22564) TP # WC6593C TP INS : CHINA TAIPING				

Estimate

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	1,151.00
Labour	0.00
Standard Menu	0.00
Specialist Job	2,904.39
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	4,055.39

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2019		25 Oct 2019 17:05 Edit Adj Rpt	**S$4,055.39** Edit Estimates	**S$4,055.39** View Rpt		**Pending for Survey Report** Cancel Case

Main | **Reference** | **Claim Details** | **Documents** | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	-, Co. Reg. No.: -		
Main Claimant:	**TEOH CHENG LEONG FABIAN**, ID: S7046749F		
Vehicle Reg. No.:	**SDA3535B**	Date of Loss:	22/10/2019 08:00 - :59 [**13** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / SNM19D205012C02	Policy/Cover Note No.:	DMCVSN19106219000
Vehicle Reg. No. (Insured):	**WC6593C**	Policy No. (Claimant):	1900161044
		Excess:	S$1,500.00
Repairer:	**Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)** 330 Ubi Road 3, 408650 Ubi - Tel: 67461000		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Tan Kah Leong** - 63896193]		
Claimant's Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 06/11/2019]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SDA3535B (SNM19D205012C02)**
[WC6593C]
TP
TEOH CHENG LEONG FABIAN
Oct 22 2019 8:00AM
[-]
Cycle & Carriage Fulco Motor Dealer Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Video — 1 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 18:48	**Video - Accident** [Linked Accident Report Documents]	i	Load MP4	
2	22/10/19 18:48	**Video - Accident** [Linked Accident Report Documents]	i	Load MP4	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/19 16:13	**General View**	i	Load JPG	✓
2	28/11/19 16:13	**General View**	i	Load JPG	✓
3	28/11/19 16:13	**General View**	i	Load JPG	✓
4	28/11/19 16:13	**General View**	i	Load JPG	✓
5	28/11/19 16:13	**General View**	i	Load JPG	✓
6	28/11/19 16:13	**General View**	i	Load JPG	✓
7	28/11/19 16:13	**General View**	i	Load JPG	✓
8	28/11/19 16:13	**General View**	i	Load JPG	✓
9	28/11/19 16:13	**General View**	i	Load JPG	✓
10	28/11/19 16:13	**General View**	i	Load JPG	✓
11	28/11/19 16:13	**General View**	i	Load JPG	✓
12	28/11/19 16:13	**General View**	i	Load JPG	✓
13	28/11/19 16:13	**General View**	i	Load JPG	✓
14	28/11/19 16:13	**Reinspection Photo**	i	Load JPG	✓
15	28/11/19 16:13	**Reinspection Photo**	i	Load JPG	✓
16	28/11/19 16:13	**Reinspection Photo**	i	Load JPG	✓
17	28/11/19 16:13	**Reinspection Photo**	i	Load JPG	✓

Linked Accident Report Documents

View: View in Browser

Video — 1 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 18:48	**Video - Accident**	i	Load MP4	
2	22/10/19 18:48	**Video - Accident**	i	Load MP4	

Assessment Reports — 1 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
1	06/12/19 19:11	**Accident Statement**	i	Load HTM	
2	06/12/19 19:12	**Accident Statement**	i	Load HTM	
3	06/12/19 19:13	**Accident Statement**	i	Load HTM	
4	06/12/19 19:14	**Accident Statement**	i	Load HTM	

Photos/Images — 3 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 18:55	**Accident Photo**	i	Load JPG	✓
2	22/10/19 18:55	**Accident Photo**	i	Load JPG	✓

Video 1 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
3	22/10/19 18:55	**Accident Photo**		Load JPG	
4	22/10/19 18:55	**Accident Photo**		Load JPG	
5	22/10/19 18:55	**Accident Photo**		Load JPG	
6	22/10/19 18:55	**Accident Photo**		Load JPG	
7	22/10/19 18:55	**Accident Photo**		Load JPG	
8	22/10/19 18:55	**Accident Photo**		Load JPG	
9	22/10/19 18:56	**Accident Photo**		Load JPG	
10	22/10/19 18:56	**Accident Photo**		Load JPG	

Documentation 1 per page

No	Finalized On	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 18:53	**Sketch Plan**		Load JPG	
2	22/10/19 18:53	**Sketch Plan #2**		Load JPG	
3	22/10/19 18:56	**Identification Card**		Load JPG	
4	22/10/19 18:56	**Driving License**		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19018813/ASD3S2
Date: 07/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19106219000		
Claimant Vehicle No :	SDA3535B	**Insured Vehicle No :**	WC6593C		
Date of Loss:	22/10/2019	Nature of Claim:	TP	Claim No:	SNM19D205012C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SDA3535B**		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UJB1499
Reg. Date:	09/10/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH003396
Colour:	Red	Odometer:	2691 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,320.00	1,151.00	2,169.00	65.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,920.00	2,904.39	7,015.61	70.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**13,240.00**	**4,055.39**	**9,184.61**	**69.37**

INSPECTION

Date of Assignment:	25/10/2019		
Date Inspected:	25/10/2019	Inspected At:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING **Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 07 Jan 2020)
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA3535B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***FACE, RR BUMPER**	Deformed	748.00 FS	*748.00 FS
2	1		***LH BRACKET, RR BUMPE**	Not Necessary	28.00 FS	*- FS
3	1		***RH BRACKET, RR BUMPE**	Necessary	28.00 FS	*28.00 FS
4	10		***CLIP, RR BUMPER**	Necessary	40.00 FS	*40.00 FS
5	1		***MUD GUARD, RR RH**	Not Necessary	36.00 FS	*- FS
6	1		***PANEL, RR END**	Repair	425.00 FS	*- FS
7	1		***PANEL, QTR, OTR RH**	Repair	763.00 FS	*- FS
8	1		***RH TAILLAMP PANEL**	Repair	60.00 FS	*- FS
9	1		***GLASS, RR WINDOW**	Not Necessary	544.00 FS	*- FS
10	2		***STOPPER, WINDSHIELD G**	Not Necessary	6.00 FS	*- FS
11	3		***SPACER, RR WINDOW**	Not Necessary	27.00 FS	*- FS
12	1		***RH RR LAMP ASSY, COM**	Cracked	335.00 FS	*335.00 FS
13	1		***SET REVERSE SENSOR**	Not Necessary	280.00 FS	*- FS
				Total Parts (S$)	**3,320.00**	**1,151.00**

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**ZERTONA PAINT PROTECTION.**	New	550.00	234.39
2	**DIAGNOSTIC / SCANNING.**	New	250.00	250.00
3	**TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.**	New	100.00	80.00
4	**TO REPLACE REAR WINDSCREEN GLASS.**	New	300.00	0.00
5	**SEALANT KIT ON REAR WINDSCREEN GLASS.**	New	100.00	0.00
6	**TO INSTALL RIKE COOL SOLAR FILM ON REAR WINDSCREEN GLASS.**	New	220.00	0.00
7	**TO REMOVE AND RE-INSTALL TRIMMING & CARPETING & ROOF LINING TO GIVE WAY FACILITATE ACCESS RENEWAL RHR QTR OTR PNL.**	New	1,200.00	300.00
8	**TO REPLACE REAR BUMPER, ETC - CUT AND RE-WELD REAR END PANEL AND RHR OTR QTR PANEL STRAIGHTEN, REFORM, ALIGN ON RHR ACCIDENT AFFECTED AREAS.**	New	4,800.00	1,200.00
9	**TO APPLY SEALANT KIT ON NEW PANEL.**	New	300.00	0.00
10	**SPRAY PAINTING ON RR & RHR ACCIDENT AFFECTED AREAS.**	New	2,100.00	840.00
		Gross Labour Cost (S$)	**9,920.00**	**2,904.39**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >