Vehicle Repair Estimate

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-123, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date : 5-Nov-2019
Vehicle Num : SBU6921T
Make/Model : BMW 520i
Chassis No : WBAXG12090C961494

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear bumper repair	1	$ 1,600.00	$ 1,600.00
2	Mount rear right ?	1	$ 190.00	$ 190.00
3				
4				
5				
6				
7			Rabu	
8			Hp 9001 0068	
9				
10			3 days	
11				
			06/11/19 @14:00	
			Resy after repair	
	TOTAL PARTS			$ 1,790.00
	TOTAL AMOUNT			$ 1,790.00
	MISCELLANEOUS ITEM			
1				
2				
	LABOUR			
1	To remove/refit/panel beat of rear bumper,rear quarter panel		$ 800.00	$ 200 ~~800.00~~
2	To perform surface repair, bodywork restoration and spray paint of rear bumper,rear quarter panel		$ 650.00	$ 500 ~~650.00~~
3	To diagnose and clearing of fault codes after repair		$ 90.00	$ X 90.00
	TOTAL			$ 3,330.00
	GST 7%			$ 233.10
	GRAND TOTAL			$ 3,563.10

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: