LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SKH 7988 G
MAKE : SUZUKI
MODEL : SX4 SEDAN 1.6
YEAR : 2009
CHASSIS NO : JSAGYC21S00320010

DATE : 7-Nov-19
DATE OF ACCIDENT : 5-Nov-19
THIRD PARTY REF SJV 6289 K
THIRD PARTY REF CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				$ 675.25
1 pc	rear bumper bean				$ 227.50
1 pc	rear end panel				$ 319.50
10 pcs	rear bumper clips		$ 3.00		$ 30.00
					$ 1,252.25
	Less 15%				$ 187.84
					$ 1,064.41
	To putty & spray paint.				$ 500.00
	labour charges.				$ 600.00
TG/VL	TOTAL				$ 2,164.41

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd