ASS. REC. BY: Taufik | REF: AIG

SJE @ Taufik

ASSIGNMENT

From: | Date: 15/11/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB3111Y

at Workshop m/s Feida Bus

of No-6 Surgui Kadut way

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: look for Faika

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted: Vehicle: IN / OUT

Veh No: CB3111Y Yr Regn: 2013 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Sunlong SLK6110 c.c 8849.

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 388329 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LJM1HCGEXBA502470

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: ~~11R22.5~~ 11R 27.5

R: 14(7)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/6 mm
D.O.A.		D.O.I.	15/11/19 @ 5pm

Survey held at Faika Bus

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s & Frt p/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	64670956.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weel end ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:	
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	