LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SGN 5708 C
MAKE : TOYOTA
MODEL : VIOS 1.5E A
YEAR : 2006
CHASSIS NO : MR053HY4204210577

DATE : 30-Nov-19
DATE OF ACCIDENT : 29-Nov-19
THIRD PARTY REF SKV 4091 P
THIRD PARTY REF AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				$ 262.90
2 pcs	rear bumper retainer		$ 35.60		$ 71.20
1 pc	rear bumper end panel				$ 751.02
1 pc	rear end panel garnish				$ 98.60
1 pc	rear boot VIOS emblem				$ 54.40
1 pc	rear boot emblem				$ 58.40
					$ 1,296.52
	Less 25%				$ 324.13
					$ 972.39
1 pc	rear bumper sensor	S.NETT			$ 200.00
1 pc	rear bumper company logo	S.NETT			$ 280.00
	To putty & spray paint.				$ 600.00
	To check rear wiring & water leakage				$ 30.00
	To anti- rust.				$ 30.00
	Labour charges.				$ 550.00
TG/VL	TOTAL				$ 2,662.39
TG/VL	TOTAL				$ -

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd