ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorised

Exp 9

2/12/19 | 3 h.

4 December 2019

REG NO. : SLF 1634 R
MAKE/MODEL : HONDA JAZZ

2/3 ~~$~~ 2200
Thughe Allowance

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE JHM 6K58

QTY	DESCRIPTION			AMT(S$)	
	LIST ITEMS				
1	Front headlamp - R/H	788.20	$	933.80	
1	Front headlamp lower bracket		$	65.20	
1	Front grille		$	267.50	
1	Front grille chrome moulding		$	188.30	
1	Front grille logo		$	85.40	
1	Front grille outer garnish		$	117.30	
1	Front bumper	594.70	$	660.90	
1	Front bumper clip (1 set)	35.00	$	50.00	
1	Front bumper fog lamp		$	155.80	
1	Front bumper fog lamp cover	84.20	$	96.00	
1	Front bumper reinforcement		$	250.80	
2	Front bumper side retainers	28.20	$	131.20	120
1	Front fender -R/H		$	571.50	
1	Front fender inner shield		$	121.60	
1	Front wheel hub		$	195.50	
1	Front wheel bearing		$	145.00	
1	Front shock absorber		$	380.50	
1	Front knuckle arm		$	385.00	
1	Front knuckle arm bearing		$	135.00	
1	Front lower arm		$	346.50	
1	Front tie rod		$	125.00	
			$	5,407.80	
		Less 20%	$	1,081.56	1650.1
			$	4,326.24	1320.08

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before the spray painting
- To resurvey [illegible] resurvey
- [illegible] Without Knowledge" basis

Acknowledged by Repairer
Signature:
Date:

	SPECIAL NETT ITEMS			
1	Front bumper lower spoiler	$	650.00	
1	Front fender inner shield clip (1 set)	$	50.00	
1	Front tyre	$	350.00	
1	Front sport rim	$	800.00	400
		$	1,850.00	

S/N	LABOUR CHARGES			
1	To check wiring and reset headlamps focusing.	$	80.00	20
2	To remove and refit front undercarriage.	$	350.00	
3	To conduct wheel alignment.	$	150.00	60
4	To apply undercoating.	$	100.00	
5	Panel beating.	$	1,400.00	350
6	To re-spray painting on the affected areas.	$	1,200.00	600
		$	3,280.00	

GRAND TOTAL : $ 9,456.24 2780.08

202

2200.06