ASS. REC. BY: H. ANN | REF: Asm (AXA)

ASSIGNMENT

From: | Date: 13.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 7707Z

at Workshop m/s Revolution Automotive

of 8 Kaki Bukit Ave 4 #01-49 Premier

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Before go call Lucas 81316518

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp''

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLK 7707Z | Yr Regn: 30/04/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes E200 AVG | c.c 1991

Colour Gray | A/C: Insured / Std / NI / NA

Sp.Reading 35094 km | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130422A399375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45/R18

R: 245/45/R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm (mic)	R/Bal.	5 mm (mic)
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	7/12/19	D.O.I.	13/12/19

Survey held at Resolution Automotive.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SLK 7707Z
	LDO Sime Lv
	Extend work
	MV - 169000
	PV - 85249
	NV - 83700

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.E.I: ( )

Survey Fee:	
Transportation:	
__S + RS.__SI	
Photos	
Others	
TOTAL	