EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643
Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
Email Address: em1autopteltd@gmail.com
COMPANY / GST REG. NO. : 201316380R

Vehicle Number :	**PA 4750Y**	**Date :**	**19.11.2019**
Vehicle Model :	**MIT.ROSA BUS**	**Chassis :**	**BE639JD00105**
Accident Date :	**10.12.2019**	**TP Ins.**	**FIRST CAP**
Original Reg Date :	**16.06.2004 (30.04.2024)**		

ESTIMATE

1	1 pc	Rear Bumper	Rx	2,600.00	N
2	1 pc	Rear Side Panel RH	bt	3,560.00	N
3	1 pc	Rear Side Panel Air Grille RH (Small)	bt	350.00	N
4	1 pc	Rear Mudflap RH	de	120.00	N
5	1 pc	Rear Mudflap Inner Shield RH	de	175.00	N
				6,805.00	
			Less 10 %	680.50	
			$	6,124.50	

Special Nett

1	1 pc	Rear Side Panel Sticker EXCURSION BUS		× 40.00	
2	5 pcs	Rear Side Glass Inner Seal	50.00	250.00	150.
3	5 pcs	Rear Side Panel Glass Sealant	60.00	300.00	250.
4	1 pc	Rear Tyre		380.00	X

Labour charge

Panel Beating	1000.	1,800.00
Spray painting - 3 Tones	1200.	1,800.00
Anti rust	60.	150.00
Remove and install carpet and seat.	280.	580.00
Remove and install side panel glass	350	400.00
To perform computerize wheel alignment.	X	90.00
		11,914.50
	Less 20 %	2,382.90
	Lump sum $	**9,531.60**

Tanghin 97495449
WP'
20/12/19 @ 3.5.
lumpsum
Resuming after repair
7 days
SUR [illegible]

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: