profi automotive

Address: 10 Kaki Buki Road 2 #01-03/05 First East CentreS417868 M: 94335558 E: automotive@asia.com

not Ahel
Lee
2/s $4000
5 days
6/2/20
Limited repair

Limited repair
Estimation

Date: 04 February 2020
Vehicle: SJX3965B
Make / Model: HONDA/JAZZ

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	REAR BUMPER 466.30 Deepcut	1	$ 540.80	$ ~~540.80~~	
2	REAR BUMPER SIDE RETAINER o/s Bel 1pc	2	$ 29.80	$ 59.60	1pc
3	REAR RH FENDER	1	$ 827.50	$ 827.50	X
4	FRONT RH DOOR PANEL 751.30 oo/Bel	1	$ 881.90	$ ~~881.90~~	
5	FRONT RH DOOR FRAME STICKER	1	$ 55.00	$ 55.00	
6	FRONT RH DOOR GLASS REGULATOR MOTOR	1	$ 505.20	$ 505.20	X
7	FRONT RH DOOR LOCK ASSY	1	$ 355.00	$ 355.00	X
8	FRONT RH DOOR LOCK STRIKER	1	$ 42.00	$ 42.00	X
9	FRONT RH DOOR WETHERSTRIP	1	$ 104.30	$ 104.30	
10	FRONT RH DOOR INNER TRIM	1	$ 551.00	$ 551.00	X
11	REAR RH DOOR PANEL 702.50 oo/Bel	1	$ 846.10	$ ~~846.10~~	
12	REAR RH DOOR FRAME STICKER	1	$ 55.00	$ 55.00	
13	REAR RH DOOR CHECKER	1	$ 65.00	$ 65.00	X
14	REAR RH DOOR HINGE UPPER	1	$ 55.00	$ 55.00	X
15	REAR RH DOOR HINGE LOWER	1	$ 55.00	$ 55.00	X
16	REAR RH DOOR WEATHERSTRIP	1	$ 102.20	$ 102.20	
17	REAR RH DOOR INNER TRIM	1	$ 551.00	$ 551.00	X
18	REAR AXLE BEAM	1	$ 1,389.30	$ 1,389.30	X
19	REAR LH WHEEL HUB AND BEARING	1	$ 150.30	$ 150.30	X
				$ 7,191.20	
	P-2162-1		**Less 20%**	**$ 1,438.24**	
			Total	**$ 5,752.96**	
	S/Nett items:				
					S.N
20	REAR BUMPER CLIP	1 SET	$ 30.00	$ 30.00	
21	FRONT DOOR INNER TRIM CLIP	1 SET	$ 30.00	$ 30.00	X
22	REAR DOOR INNER TRIM CLIP	1 SET	$ 30.00	$ 20.00	X
23	RIM oo/Bel 300	1	$ 400.00	$ 400.00	300
24	BRAKE FULD	1 BOT	$ 60.00	$ 50.00	X
25	JOINT SEALANT	1	$ 120.00	$ 120.00	X
26	WINDSCREEN SEALANT	1	$ 120.00	$ 120.00	X
27	REAR BUMPER LOWER GARNISH Tom 600	1	$ 800.00	$ 800.00	600
28	~~LH~~ SILL GANRISH o/s Deepcut 600	1	$ 900.00	$ 900.00	600
				$ 2,470.00	

	Labour to:				
29	CHECK WIRING AND LIGHTNING SYSTEM		$ 60.00	$ 60.00	20
30	REMOVE.REFIT REAR LINING, TRIM AND GARNISH		$ 150.00	$ 150.00	60
31	REMOVE AND REFIT REAR REVERSE SENSOR		$ 100.00	$ 100.00	40
32	REMOVE AND REFIT REAR RH QUARTER GLASS		$ 120.00	$ 120.00	n/x
33	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT		$ 120.00	$ 120.00	60
34	REMOVE AND REPLACE REAR UNDERCARRAIAGE PARTS		$ 150.00	$ 150.00	n/x
35	PANEL BEATING ON AFFECTED AREAS		$ 1,200.00	$ 1,200.00	600
36	SPRAY PAINTING ON AFFECTED AREAS		$ 1,500.00	$ 1,500.00	1100
37	APPLY ANTI RUST ON AFFECTED AREAS		$ 120.00	$ 120.00	60
				$ 3,520.00	
					5799.68
					4155

Parts Replacement Amount	**$ 8,222.96**
Total Amount for Labour	**$ 3,520.00**
Total Amount	**$ 11,742.96**

	Labour to:				
29	CHECK WIRING AND LIGHTNING SYSTEM		$ 60.00	$ 60.00	20
30	REMOVE.REFIT REAR LINING, TRIM AND GARNISH		$ 150.00	$ 150.00	60
31	REMOVE AND REFIT REAR REVERSE SENSOR		$ 100.00	$ 100.00	40
32	REMOVE AND REFIT REAR RH QUARTER GLASS		$ 120.00	$ 120.00	max
33	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT		$ 120.00	$ 120.00	60
34	REMOVE AND REPLACE REAR UNDERCARRAIAGE PARTS		$ 150.00	$ 150.00	max
35	PANEL BEATING ON AFFECTED AREAS		$ 1,200.00	$ 1,200.00	600
36	SPRAY PAINTING ON AFFECTED AREAS		$ 1,500.00	$ 1,500.00	1100
37	APPLY ANTI RUST ON AFFECTED AREAS		$ 120.00	$ 120.00	60
				$ 3,520.00	
				5199.68	
				4155	

Parts Replacement Amount	**$ 8,222.96**
Total Amount for Labour	**$ 3,520.00**
Total Amount	**$ 11,742.96**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: