OPTIMA WERKZ SINGAPORE
OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg /OptimaWerkz /OptimaWerkz

Date: 03.02.2020
Vehicle No: SMR1623Y
Model: HONDA VEZEL
Chassis: RU31320642-2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLQ1073B
Date of Accident: 31.01.2020

Not without
Resurvey B4 paint
4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S$	AMOUNT S$	
1	REAR TAILGATE	1		Pa $972.40	✓
2	REAR TAILGATE 'VEZEL' EMBLEM	1		Ne $45.80	✓
3	REAR TAILGATE 'HYBRID' EMBLEM	1		Ne $75.30	✓
4	REAR WINDSCREEN SEALANT	1		Ne $80.00	400sn
5	REAR WINDSCREEN RUBBER	1		Sn $74.40	X
6	REAR TAILGATE INNER TRIM CLIPS	10	$5.80	$58.00	?
7	REAR BUMPER	1		Pa $787.90	✓
8	REAR BUMPER CLIPS	8	$5.50	Ne $44.00	✓
9	REAR END PANEL	1		REPAIR	
			SUB TOTAL	$2,137.80	
			LESS 20%	-$427.56	
			PARTS TOTAL	$1,710.24	

NO.	SPECIAL NETT	QTY	UNIT S$	AMOUNT S$	
1	REAR WINDSCREEN STOPPER	2	$15.00	Ne $30.00	✓
2	REAR BUMPER REVERSE SENSOR	1		Pd $350.00	200sn
			S/N TOTAL	$380.00	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- [illegible] is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,READJUST REAR ACCIDENT AREAS & ETC. $600.00 400l

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. $80.00 50l

LABOUR CHARGES TO REMOVE & REPLACE,REFIX REAR WINDSCREEN GLASS,REAR WINDSCREEN SEALANT,REAR WINDSCREEN RUBBER & ETC. TO EFFECT REPLACE AT REAR TAILGATE. $150.00 120l

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC TO EFFECT REPLACE OF REAR TAILGATE. $120.00 60l

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE,REAR END PANEL & REAR BUMPER & ETC. $700.00 450l

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg /OptimaWerkz /OptimaWerkz

Date:	03.02.2020	Third Party Insurer:	AIG
Vehicle No:	SMR1623Y	Third Party Veh No:	SLQ1073B
Model:	HONDA VEZEL	Date of Accident:	31.01.2020
Chassis:	RU31320642-2018		
Reg.Year:	2019		

15/.

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM.	$60.00
LABOUR TOTAL	$1,710.00
ONG — **TOTAL**	**$3,800.24**