GOLD AUTOWORKS PTE LTD
48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586
Email : claims@goldautoworks.com.sg Company Reg no. 201716329M
CAR MODEL : HONDA FIT 1.3GF CVT VEH NO: SMR5016Z
CHASSIS NO : GK3-3419866 HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount	
1	side mirror base RH	1	$ 527.50	$ 527.50	out
2	frt fender RH	1	$ 435.00	$ 435.00	bt
3	frt fender shield RH	1	$ 171.50	$ 171.50	old
4	frt fender shield clip	12	$ 3.20	$ 38.40	new
5	frt wheel knuckle RH bt	1	$ 345.00	$ 345.00	?
6	frt wheel bearing RH bt	1	$ 268.00	$ 268.00	?
7	frt lower arm RH	1	$ 328.00	$ 328.00	x nn
8	frt shock absorber RH	1	$ 482.00	$ 482.00	x nn
9	frt door RH	1	$ 757.50	$ 757.50	bt
10	frt door outer handle RH X	1	$ 322.70	$ 322.70	X nn.
11	frt door inner lock RH bt	1	$ 375.00	$ 375.00	?
12	frt door outer moulding	1	$ 155.00	$ 155.00	X nn
13	frt door trim board RH cm	1	$ 782.00	$ 782.00	?
14	door trim board clip new	15	$ 3.50	$ 52.50	?
15	frt door hinge RH upper & lower bt	2	$ 125.00	$ 250.00	?
16	frt window regulator assy RH bt	1	$ 482.90	$ 482.90	?
17	rr door RH	1	$ 799.50	$ 799.50	bt
18	rr door trim board RH	1	$ 823.00	$ 823.00	x nn
19	rr door trim board clip	15	$ 3.50	$ 52.50	X nn
20	rr door hinge RH lower & upper	2	$ 125.00	$ 250.00	RY
21	rr window regulator assy RH	1	$ 495.00	$ 495.00	X nn
22	rocker panel RH	1	$ 415.30	$ 415.30	RY
23	frt quarter glass with moulding assy	1	$ 498.00	$ 498.00	x nn.
	Total List Amount			$ 9,106.30	5284.80.
	List 20% Dsicount			$ 1,821.26	
	After Discount			$ 7,285.04	4227.84
	Special Nett Item				
24	frt tyre RH	1	$ 300.00	$ 300.00	x nn.
25	frt sport rim RH	1	$ 650.00	$ 650.00	out — 350
26	ceramic coating package	1	$ 980.00	$ 980.00	350.
27	panel sealant	1	$ 100.00	$ 100.00	40.
27	perform wheel alignment with report (before & aftrer)	1	$ 120.00	$ 120.00	80. 820.
	Labour				
A	to remove & reinstall interior trims, garnishes, seats				
	etc. for necessary repair	-	$ 250.00	$ 250.00	60.
B	to check electrical wiring system RH	-	$ 120.00	$ 120.00	30
C	to transfer frt RH door component parts to new door				
	(include window glass & window bracket)	-	$ 150.00	$ 150.00	60
D	to transfer Rr RH door component parts to new door				
	(include window glass & window bracket)	-	$ 150.00	$ 150.00	60
E	to remove & reinstall frt rh undercarriage parts for repair	-	$ 200.00	$ 200.00	100? ✓
F	to straighten, repair, realign on affected area	-	$ 1,800.00	$ 1,800.00	800
H	to spray painting on affected area & new parts	-	$ 2,000.00	$ 2,000.00	900
I	to apply anti-rust coating on affected panel	-	$ 180.00	$ 180.00	50.
J	to remove & reinstall quarter glass	-	$ 100.00	$ 100.00	x nn.
					2060.
	Total Labour & S/N			$ 7,100.00	
	Lump-sum 20%			$ 11,508.03	7107.84

Tanjim 97415749
'WP'
4/2/20 @ 4.55pm 4/s $5700.
07 days.
Resuming after repair
tanjim @ lkhanfo.com -
07 days * confirm with Simon thru mail.
4/s $5700, 7days