Performance Motors Limited Vic

FACSIMILE MESSAGE

DATE 4 Mar 2020

INS India International

SUV Guo Qiang

ATTN LKK office

MCA Chua K S

TIME

FAX NO

NO OF PAGES

FAX NO

FAX NO 64743229

TEL NO

If the fax is not received in order, please do call CSA. Thank you

Dear Sirs,

Supplementary repair for BMW 218iA

Vehicle Registration No. SFV7771A

Vehicle Chassis No. V312498

Guo Qiang
LKK
1 more day.

Supplementary Parts to replace **YES** [X] Refer to attachment

NO [ ]

Parts / Labour Description *	QTY	Prices
Reference to part quotation #547692	1	$2,457.10
To replace front right undercarriage parts Supp	1	$1,327.50
To check steering geometry and conduct wheel alignment according to BMW specification. 2nd round Supp	1	$531.00
Request for additional 1 work days		
	Total =>	$4,315.60

*** All of the above which are highlighted will be considered as agreeable if there i objection and/OR subsequence amendment within 3 work days.**