MY CAR CONSULTANT PTE LTD

MYCAR CONSULTANT

Reg no.: 201605878Z
Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Sun Pm (LHC)
28/02/2020
TP without prejudice.

Estimation

Date: 28-Feb-20
Vehicle: SML7937J
Make / Model: TOYOTA/PRIUS
Chassis:

Our Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To discuss damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	REAR FENDER RH pb	1	$ 810.50	$ 810.50	
2	REAR DOOR RH pb	1	$ 898.40	$ 898.40	
3	REAR DOOR TRIM BOARD RH CRA ?/	1	$ 746.50	$ 746.50	
4	REAR DOOR LOCK / Jamed	1	$ 530.70	$ 530.70	401.9
5	REAR DOOR GLASS X svc	1	$ 510.60	$ 510.60	X
6	REAR DOOR GLAS REGULATOR ?/BT	1	$ 230.80	$ 230.80	
7	REAR POWER WINDOW MOTOR RH ?X svc	1	$ 510.90	$ 510.90	X
8	REAR POWER WINDOW SWITCH RH ?/short	1	$ 140.60	$ 140.60	
9	REAR DOOR OUTER HANDLE RH LONG X R	1	$ 108.30	$ 108.30	X
10	REAR DOOR OUTER HANDLE RH SMALL X svc	1	$ 60.70	$ 60.70	X
11	CENTRE PILLAR RH X svc	1	$ 550.60	$ 550.60	X
12	REAR WINDOW GUIDE RH ?X svc	1	$ 209.40	$ 209.40	X
13	REAR WINDOW GUIDE GARNISH ?/BT	1	$ 170.50	$ 170.50	
14	REAR DOOR STICKER / Mis	1	$ 67.10	$ 67.10	40
15	REAR DOOR RUBBER RH ?/ cut.	1	$ 240.30	$ 240.30	
	Sill panel ?XR			$ 5,785.90	3,679.5
			Less 25%	$ 1,446.48	-25%
			Total	$ 4,339.43	2,759.63
	S/Nett items:				
16	RIMS cover / sch.	1 SET	$ 300.00	$ 300.00	110
17	TYRE X	1 SET	$ 80.00	$ 80.00	X
				$ 380.00	110.
	Labour to:				
18	TO CHECK REAR ELECTRICAL WIRING	1	$ 50.00	$ 50.00	30
19	TO REMOVE AND REFIT REVERSE SENSOR	1	$ 80.00	$ 80.00	X
20	TO REMOVE AND REFIT WINDSCREEN MOULDING	1	$ 120.00	$ 120.00	60.
21	TO RESPRAY UNDERCOATING	1	$ 100.00	$ 100.00	50
22	APPLY ANTI RUST ON AFFECTED AREAS	1	$ 120.00	$ 120.00	
23	SPRAY PAINTING ON AFFECTED AREAS	1	$ 1,500.00	$ 1,500.00	600 800
24	PANEL BEATING ON AFFECTED AREAS	1	$ 1,500.00	$ 1,500.00	600
				$ 3,470.00	1,540
					4,409.63
					-20%
			Parts Replacement Amount	$ 4,719.43	3,527.04
			Total Amount for Labour	$ 3,470.00	L/S
			Total Amount	$ 8,189.43	3,500

Repair dy - 5 days
Lum Sum
After paint photo.

11/3/2020