MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Estimation

Date: 1/4/2020
Vehicle: SMG6023D
Make / Model: TOYOTA PRIUS
Chassis: JTDZS3EUX0J034858

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER		$ 610.40	$ ~~610.40~~
2	REAR BUMPER SIDE RETAINER LH		$ 113.60	$ ~~113.60~~
3	REAR BUMPER SIDE RETAINER RH		$ 113.60	$ ~~113.60~~
4	REAR BUMPER REINFORCEMENT		$ 310.50	$ 310.50
5	REAR BUMPER BRACKET LH		$ 115.30	$ ~~115.30~~
6	REAR BUMPER BRACKET RH		$ 115.30	$ ~~115.30~~
7	REAR BUMPER LIP		$ 718.50	$ ~~718.50~~
8	REAR BUMPER REFLECTOR LH		$ 80.60	$ ~~80.60~~
9	REAR BUMPER REFLECTOR RH		$ 80.60	$ ~~80.60~~
				$ 2,258.40
			Less 25%	$ 564.60
			Total	$ 1,693.80
	S/Nett items:			
1	REAR REVERSE SENSOR	1 SET	$ 250.00	$ ~~250.00~~
2	REAR BUMPER CLIP	1 SET	$ 80.00	$ ~~80.00~~
3	REAR END PANEL GARNISH CLIP	1 SET	$ 30.00	$ ~~30.00~~
4	FLOOR PANEL SEALANT	1	$ 50.00	$ ~~50.00~~
5	END PANEL SEALANT	1	$ 50.00	$ ~~50.00~~
				$ ~~460.00~~
	Labour to:			
40	TO CHECK ELECTRICAL WIRING	1	$ 50.00	$ ~~50.00~~
41	TO REMOVE AND REFIT REVERSE SENSOR	1	$ 150.00	$ ~~150.00~~
43	TO RESPRAY UNDERCOATING	1	$ 100.00	$ ~~100.00~~
44	APPLY ANTI RUST ON AFFECTED AREAS	1	$ 120.00	$ ~~120.00~~
45	SPRAY PAINTING ON AFFECTED AREAS	1	$ 600.00	$ ~~600.00~~
46	PANEL BEATING ON AFFECTED AREAS	1	$ 600.00	$ ~~600.00~~
				$ ~~1,620.00~~

Parts Replacement Amount	$ 2,153.80
Total Amount for Labour	$ 1,620.00
Total Amount	$ 3,773.80

H/S 1,250/2

15/5/2020

Survey 2/4/2020 Resurvey 8/5/2020
Tgkm Wira Tgkm Wira
1730 kms 12.15 hrs

Lump sum repair request by workshop
Repair days 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: