MOVA
Automotive Pte Ltd

Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6478 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3, #01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0098864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services, Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.

INSURER: **Lonpac Insurance Bhd (HQ)** Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105187	Date of Loss:	27/03/2020
Vehicle Reg. No.:	XD7979A	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FONG SHENG LOGISTIC PTE LTD		
Driver:	RAMASAMY VIDUTHALAIPULI		
Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	23/10/2014
Vehicle Colour:	GREEN		
Engine No:	OM457LA457972C0284755	Chassis No:	FV51SJA10033
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	34,678.60
Miscellaneous Items	0.00
Labour	4,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S$)	**39,478.60**
+ GST 7.00% (S$)	2,763.50
Nett Amount (S$)	**42,242.10**

This claim is handled by: ALAN

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***

MOVA
Automotive Pte Ltd

Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6475 3333 Fax: 6271 5891

Service Centre : Block 1005, Bukit Merah Lane 3, #01-04/06/09/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg No: M2-0068864-2

Mova Spray Centre
2K Oven Spray Painting System
Power-M Automotive Pte Ltd
Specialise in Car Air-con Services, Car Audio & Hi-Fi System.
Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.

(SUPPLEMENTARY)

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105187	Date of Loss:	27/03/2020
Vehicle Reg. No.:	XD7979A	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FONG SHENG LOGISTIC PTE LTD		
Driver:	RAMASAMY VIDUTHALAIPULI		
Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	23/10/2014
Vehicle Colour:	GREEN		
Engine No:	OM457LA457972C0284755	Chassis No:	FV51SJA10033
Odometer:	0 KM		
Paint Type:			
Total Loss?	**NO**		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Remarks:	SUPPLEMENTARY ITEMS : 1. FRONT UNDERCARRIAGE LIFT SPRING SUSPENSION ASSY X 2 SETS : $1800 X 2 (S.N.) 2. LIFT SPRING U BOLT 11" X 4 PCS : $100 X 4 (S.N) 3. FRONT TIE ROD ASSY : $800 4. DPF MUFFLER ASSY : $11,500 5. FRONT TIE ROD END LH : $450 LABOUR : 1. TO REMOVE & RENEW FRONT BOTH UNDERCARRIAGE DAMAGED PARTS : $600 2. TO CHECK ALL WHEELS ALIGNMENT : $200		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	18,662.50
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S$)	**19,462.50**
+ GST 7.00% (S$)	1,362.38
Nett Amount (S$)	**20,824.88**
+ Previous Estimates (S$)	42,242.10
Claim Total (S$)	**63,066.98**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Labour Items		Lab.Type	Amount
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN	New	160.00
3	TO REMOVE & INSTALL DASHBOARD	New	300.00 200
4	TO REMOVE & INSTALL CARPET, GARNISH, SEAT & ETC IN ORDER TO CUT OFF LH FRONT DOOR PILLAR & STRAIGHTEN AFFECTED AREAS	New	400.00 200
5	TO CUT OFF WIPER PANEL, LH FRONT DOOR PILLAR, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1500 2,400.00 1200
6	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,500.00 900
		Gross Labour Cost (S$)	4,800.00 1100

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Supplementary labours
To remove & refeco front
both underarrange. damages
panels. = # 600

To check all wheels
alignment = # 200

Rasul
Hp 90010068

8 days
4/S

EXCESS: 2000

Revert
02/04/2020 @1635

Resurvey after repair

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Apr 2020)
Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for XD7979A)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS bro /	0.00	0.00	*1,500.00 F
2	1		*FRONT WINDSCREEN MOULDING rear /	0.00	0.00	*350.00 F
3	~~1~~ 2pcs		*WIPER ARM bl /	0.00	0.00	*750.00 F
4	1		*WIPER LINKAGE ASSY X	0.00	0.00	*850.00 F
5	1		*WIPER PANEL ~~bl~~ repair	0.00	0.00	*480.00 F
6	1		*FRONT PANEL bl /	0.00	0.00	*2,800.00 F
7	2		*FRONT PANEL HINGE X	0.00	0.00	*140.00 F
8	1		*FRONT PANEL (FUSO) EMBLEM rear /	0.00	0.00	*180.00 F
9	2		*FRONT PANEL GRILLE scr /	0.00	0.00	*1,200.00 F
10	1		*FRONT BUMPER TOP bro /	0.00	0.00	*250.00 F
11	1		*FRONT BUMPER LOWER bl /	0.00	0.00	*1,300.00 F
12	~~1~~ 1pc		*FRONT BUMPER LH & RH LH-bro / RH-X	0.00	0.00	~~*300.00 F~~ 150
13	~~1~~ 1pc		*FRONT BUMPER COVER LH LH-bro / RH-X	0.00	0.00	~~*300.00 F~~ 150
14	1		*FRONT BUMPER CENTER BRACKET ? X	0.00	0.00	*1,050.00 F
15	~~1~~ 1pc		*FRONT BUMPER LH & RH BRACKET LH-bl / RH-X	0.00	0.00	*600.00 F
16	1		*HEADLAMP LH bro /	0.00	0.00	*800.00 F
17	1		*SMALL LAMP LH bro /	0.00	0.00	*300.00 F
18	1		*SIGNAL LAMP LH bro /	0.00	0.00	*160.00 F
19	1		*FRONT CORNER PANEL LH cm /	0.00	0.00	*550.00 F
20	1		*FRONT CORNER PANEL BRACKET LH ?	0.00	0.00	*140.00 F
21	1		*FRONT SIDE MIRROR BRACKET LH bl /	0.00	0.00	*1,100.00 F
22	~~1~~ 1pc		*FRONT SIDE MIRROR BRACKET SUPPORT bl /	0.00	0.00	*600.00 F
23	2		*FRONT SIDE MIRROR cm /	0.00	0.00	*360.00 F
24	1		*FRONT SIDE ROUND MIRROR LH cm /	0.00	0.00	*110.00 F
25	1		*FRONT WHEEL ARCH LH de /	0.00	0.00	*210.00 F
26	1		*FRONT WHEEL ARCH BLADE GARNISH LH bro /	0.00	0.00	*950.00 F
27	1		*FRONT STEP PANEL LH bro /	0.00	0.00	*750.00 F
28	1		*FRONT STEP PANEL BOTTOM LH bro /	0.00	0.00	*600.00 F
29	3		*FRONT STEP PLATE bro /	0.00	0.00	*714.00 F
30	1		*FRONT STEP SUPPORT BAR LH bl /	0.00	0.00	*780.00 F
31	1		*CONDENSER bl /	0.00	0.00	*1,340.00 F
32	1		*CONDENSER BRACKET bl /	0.00	0.00	*580.00 F
33	2		*CONDENSER AIR CON PIPE bl /	0.00	0.00	*400.00 F
34	1		*CONDENSER FAN MOTOR ? front /	0.00	0.00	*900.00 F
35	1		*CONDENSER FAN BLADE ? bro /	0.00	0.00	*220.00 F
36	1		*CONDENSER FAN COWLING ? bro /	0.00	0.00	*190.00 F
37	1		*LH FRONT DOOR PILLAR repair	0.00	0.00	*2,800.00 F
38	1		*FRONT BUMPER CENTER STEP GARNISH bro /	0.00	0.00	*160.00 F
39	1		*DASHBOARD TOP ? (wt /	0.00	0.00	*2,500.00 F
40	1		*TOWING TO FAN YOONG /	0	0.00	*350.00 FS receipt:
41	1		*LH FRONT TYRE punctured /	0	0.00 70%	*600.00 FS ?420
42	1		*FRONT NUMBER PLATE bl /	0	0.00 35	~~*50.00 FS~~
43	1		*FRONT IU BRACKET RH /	0	0.00	*25.00 FS

F=Franchise part, S=Specific

Sub Total (S$)	30,289.00
+ Margin on L,N Items 15.00% (S$)	4,389.60
Total Parts (S$)	34,678.60

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

1) DPF Muffler qty #11,500
4) Front tie rod end LH #450

Supplementary parts.

1) Front undercarriage lift spring suspension qty x 2sets #800x2 #360x SIM
2) Lift Spring U Bolt 11" x 4pcs #100x4 SIM
3) Front tie rod qty #800 -#400