Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 25 Jun 2020

Preliminary Advice

Insured Vehicle No	: GBC2416G		
TP Vehicle No	: GBB2912X	Accident Date	: 22/06/2020
Make	: NISSAN URVAN	Assignment Date	: 23/06/2020
Date of Inspection	: 24/06/2020	Est. Duration of Repair	: 3.00
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion, rear windscreen shartted and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	6,498.70
Revised Amount	:S$	3,780.11
Check Items (Estimated)	:S$	0.00
Total	:S$	3,780.11
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :