Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

re Parts

Vehicle No	: FBL1477P	Case Owner	: 0
Make & Model	: YAMAHA MT-09 ABS	Year Manufacture	: 2016
Chassis No	: JYARN29S000004022	Engine No	: N701E062426
Sales Order	:	Supplier	:
Order By	:	Type of Claim	: Third Party

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	SIREN ASSY DIS	1				$1,680.00	780
2	FRONT CRASH BAR – LEFT SCA	1				$425.00	425
3	FRONT CRASH BAR – RIGHT X AN	1				$425.00	X
4	TOWING FROM ACCIDENT SCENE	1				$50.00	50
5	0	0					1255
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : **FBL1477P**
Make & Model : **YAMAHA MT-09 ABS**
Case Owner : **0**
Year of Manufacture : **2016**

S/No	Labour Description	Esimated Price	Adjusted Price
1	WORKMANSHIP	~~$150.00~~	100
			100
	1255		
	100		
	1355		
	1 day		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.