LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SJG 8660 L
MAKE : HONDA
MODEL : VEZEL 1.5X CVT
YEAR : 2017
CHASSIS NO : RU11231772

DATE : 17-Jul-20
DATE OF ACCIDENT : 17-Jul-20
THIRD PARTY REF SGB 46 A
THIRD PARTY REF AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				$ 518.60
					$ 518.60
	Less 20%				$ 103.72
					$ 414.88
1 pc	rear bumper sensor	S.NETT			$ 200.00
	Labour charges.				$ 200.00
TG/VL	TOTAL				$ 814.88
TG/VL	TOTAL				$ -

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64569127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd