

LKK → NG.C.P.P)

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 17.08.2020  
Time: 12:18:46  
Page: 1

JM

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305416978  
REGN NO : SHA3399E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 01.08.2019  
DATE/TIME IN : 17.08.2020 08:40  
ACCIDENT DATE : 16.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|      |                   |                           |      |               |       |               |                                                           |
|------|-------------------|---------------------------|------|---------------|-------|---------------|-----------------------------------------------------------|
| 0001 | 04-01-0104-2282-G | IONIQVC COVER-RR BUMPER#  | 1    | 459.40        | 20.00 | 367.52        | de ✓                                                      |
| 0002 | 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00         | 20.00 | 17.60         | ne ✓                                                      |
| 0003 | 04-01-0104-2533-G | MOULDING ASSY-RR BUMPER C | 1    | 451.25        | 20.00 | 361.00        | de ✓                                                      |
| 0004 | 04-01-0104-2270-G | EMBLEM-HYBRID             | 1    | 24.30         | 20.00 | 19.44         | ne ✓                                                      |
| 0005 | 04-01-0104-2271-G | EMBLEM-IONIQ              | 1    | 31.30         | 20.00 | 25.04         | ne ✓                                                      |
| 0006 | 28-01-0103-0005-A | REAR BOOT LOGO CTPL       | 1 N  | 30.00         | 2.00- | 30.00         | ne ✓                                                      |
| 0007 | 28-01-0103-0006-A | REAR BOOT TEL NUMBER CTPL | 1 N  | 30.00         | 0.20  | 30.00         | ne ✓                                                      |
| 0008 | 04-01-0104-2544-G | IONIQVC CAP-RR HOOK       | 1    | 98.80<br>9.10 | 20.00 | 79.04<br>7.28 | ? de ✓                                                    |
| 0009 | 28-01-9999-2025-A | APP LOGO REAR BONNET CTPL | 1 N  | 40.00         | 2.00- | 40.00         | ne ✓                                                      |
| 0010 | FNPS              | NO PLATE(S)               | 1 N  | 25.00         | 0.20  | 25.00         | ana ✓                                                     |
| 0011 | 09-01-9999-0068-A | HYUNDAI REVERSE SENSOR AS | 1 N  | 135.70        | 0.02- | 135.70        | na ✓                                                      |
| 0012 | 04-01-0104-2256-G | IONIQVC PANEL ASSY-TAIL G | 1    | 2,480.40      | 20.00 | 1,984.32      | bt ✓                                                      |
|      |                   |                           |      |               |       |               | SUB-TOTAL : 3,042.90                                      |
|      |                   |                           |      |               |       |               | 235.84                                                    |
|      |                   |                           |      |               |       |               | loniq beam rear bumper ana ✓ 294.80 20% 138.10 20% 110.48 |
|      |                   |                           |      |               |       |               | loniqvc stay-rr bumper LH 138.10 20% 110.48               |
|      |                   |                           |      |               |       |               | loniqvc lamp assy-rear fog 201.50 20% 161.20              |
|      |                   |                           |      |               |       |               | 3622.18                                                   |

JOB NATURE

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 17.08.2020

Time: 12:18:46

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305416978  
REGN NO : SHA3399E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 01.08.2019  
DATE/TIME IN : 17.08.2020 08:4  
ACCIDENT DATE : 16.08.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

|            |                              |                      |      |       |
|------------|------------------------------|----------------------|------|-------|
| 0000 PB    | PANEL BEATING                | 980.00               | 640. |       |
| 0001 SP    | SPRAYPAINT CHARGE            | 600.00               | 400. |       |
| 0002 17-01 | CHECK ALL LIGHTING           | 50.00                | 30.  |       |
| 0003 20-00 | TUFF COAT ON AFFECTED PARTS. | 50.00                | 30.  |       |
| 0004 L     | REVERSE SENSOR ASSY          | 80.00                | 30   | 1130. |
|            |                              | SUB-TOTAL : 1,760.00 |      |       |

TOTAL : 4,802.90

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

MIC

Tanjin 97495749  
-wp 17/8/2020 4pm  
3 days

p/p Resurvey before paint  
tanjin@lkhant.com

3622.18  
1130  
44752.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: