ASS. REC. BY: Steve | REF: CS3/CT/20008979/Esf3

ASSIGNMENT

From: PRS Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBB 5365E Yr Regn: 1/6/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Dyna 150 c.c 2982

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 407698 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFAT35Y80K 200616

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / S/D / Rim or

Tyre Size: F: 7.00-16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	4 mm	L/Bal.	4 mm
D.O.A.	20/8/20	D.O.I.	26/8/20

Survey held at Yap Lee Motor

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	M/V - 23K Repair range 6K - 7K
	14 days

Date/Time, File Pass to? 31/08/2020

1) TYPIST

Date/Time, File Return to?

2)

☐ : Prell. Report

☑ : Final Report

Days Of Repair: 14

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : PRS

Lump Sum / L.E.I. ( )

Survey Fee:

Transportation:

S + RS S

Photos

Others

TOTAL