ASS. REC. BY: Ram REF: CS3/ III 2000454/ ~~Eyd3~~ Ey A3-1

ASSIGNMENT

From: 1 Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBA 1854S

at Workshop m/s MotorSports 25 Kaki ~~[illegible]~~

of Bukit Road 4 #06-38.

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBA 1854S Yr Regn: 22/02/2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda CB400 c.c 399

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading 130516 T/Radio: Insured / Std / NI / NA

Eng/No: —

C/No: NC391102296

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60 R17 metzeler

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or metzeler

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	4 mm	L/Bal.	4 mm

D.O.A. 22/02/2020 D.O.I. 26/03/2020

Survey held at JD MotorSports

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range : $2000-$3000
	Repair days : 3 days
	MV : $10900
	PV : $3851
	WV : $7049

29/9/20 Submit L/S $2350/- (Red $750/-, 24%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) ~~8/5/20~~ 29/9/20 Typist

Report Format :

Lump Sum / LBR: ($)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS SI

Photos

Others

TOTAL