Ass. Rec. By: GQ | Ref: CS/AWA20009121/Gyf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s MCS AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBL 8977S Yr Regn: 28 Apr/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CBF190X c.c 184

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LALPJL704H3018128

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100/80-17

R: 130/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	22/3/20	D.O.I.	28-08-2020

Survey held at W/S 4:40pm

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/3/21	LS $2750 (Un-confirmed)

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Date/Time, File Return to?

3/3/21-Typist

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Survey Fee:

Transportation: $ + RS. SI

Photos

Other:

TOTAL

Estimate Repair For Vehicle FBL 8[illegible] (Honda CBF150X)

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NN NN NN

QTY	DESCRIPTION OF PARTS	PRICE	
1 pc	Handle bar / BT	$189.00	~~105~~ 172
1 set	Handle bar balancer L/R ×	$40.00	×
1 set	Hand guard L/R ×	$180.00	× NN
1 pc	Brake lever ×	$58.00	×
1 pc	Clutch lever / Cut	$58.00	✓
1 pc	Meter assy / NN	$680.00	480
1 pc	Front windshield / SCR	$385.00	200
1 pc	Headlamp cowling ×	$257.00	× NN
1 pc	Front shield / Cut	$108.00	✓
1 pc	Headlamp assy / CRA	$859.00	~~350~~ 617
1 pc	Front cowling stay / BT	$157.00	65
2 pcs	View mirror L/R $ $216.00 LH / Cut RH × NN	$432.00	45
1 pc	Fuel tank lid × NN	$280.00	×
2 pcs	Fuel tank side cover L/R @ $418.00 × NN	$836.00	×
1 set	Front side cowling emblem L/R ×	$58.00	×
2 pcs	Front inner shroud L/R @245.00 LH / Cut RH × NN	$490.00	55
2 pcs	Front side cowling L/R @ $315.00 LH / Cut RH × NN	$630.00	95
2 pcs	Front side cover L/R (silver) @ $157.00 ×	$314.00	×
2 pcs	Front signal lamp L/R @ $135.00 LH / Cut RH × NN	$270.00	35
2 pcs	Front fork tube assy L/R @ $890.00 / BT	$1,780.00	~~400~~ ~~260~~ 400
2 pcs	Front fork tube guard L/R @ $68.00 × NN	$136.00	×
1 pc	Front lower steering stem / BT	$385.00	80
1 pc	Front wheel rim / BT	$849.00	295
1 pc	Front brake disc × NN	$540.00	×
1 pc	Front fender / Cut	$216.00	160
1 pc	Rear brake pedal × NN	$95.00	×
1 pc	Front footrest LH / BR	$58.00	40
1 pc	Front footrest bracket LH ×	$285.00	×
1 pc	Rear footrest LH × NN	$45.00	×
1 pc	Rear footrest bracket LH ×	$185.00	×
		$10,855.00	2571 2821
	Less 10%	$1,085.50	
		$9,769.50	2313.9
	S/NETT ITEM		
1 set	Front rim bearing & oil seal / NEL	$55.00	30
1 set	Steering cone upper/lower bearing / NEL	$68.00	40
1 set	Engine crash bar L/R / Cut	$380.90	120
1 pc	Front number sticker / SCR	$20.00	10
2 pcs	Fork oil seal & duct cover L/R @ $38.00 / NEL	$76.00	40
2 bots	Fork oil @ $15.00 / NEL	$30.00	20
1 pc	Rear storage box / SCR	$450.00	150
		$10,849.40	410
	Labour charge		
1]	Towing service charge. (2 Trips)	$80.00	50
2]	Front body frame alignment.	$380.00	~~2~~ ~~photo~~ NN
3]	Replace, realign & adjust above damaged parts. check wiring, re-connection & lighting system.	$450.00	~~200~~ 400
	Sub Total :	**$910.00**	3398.9
			~~2973.9~~
	Total Parts and Labour	**$11,759.40**	-20%: ~~2350~~ 2700

ex Pays. lump sum repair / After repair photos.
Cancel Claim