LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SDU 1750 D
MAKE : MERCEDES BENZ
MODEL : C 180 KOMPRESSOR
YEAR : 2012
CHASSIS NO : WDD2040452A741423

DATE : 5-Sep-20
DATE OF ACCIDENT : 4-Sep-20
THIRD PARTY REF SKP 5287 S
THIRD PARTY REF AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			$ 1,370.00	
1 pc	rear bumper reinfrocement			$ 740.00	
2 pcs	rear bumper retainer		$ 42.00	$ 84.00	
1 pc	rear bumper chrome moulding - centre			$ 200.00	
2 pcs	rear bumper chrome moulding - side		$ 144.00	$ 288.00	
1 pc	rear end panel			$ 1,380.00	
1 pc	rear boot lid			$ 1,380.00	
1 pc	rear boot lock			$ 325.00	
1 pc	rear boot star			$ 50.00	
1 pc	rear boot C180 emblem			$ 90.00	
1 pc	rear boot kompressor emblem			$ 116.00	
1 pc	front bumper			$ 1,310.00	
1 pc	front bumper reinfrocement			$ 380.00	
1 pc	front bumper number plate griller			$ 145.00	
2 pcs	front bumper retainer		$ 90.00	$ 180.00	
1 pc	front grille			$ 750.00	
1 pc	front grille inner bracket			$ 28.00	
2 pcs	head lamps		$ 1,100.00	$ 2,200.00	
					$ 11,016.00
	Less 10%				$ 1,101.60
					$ 9,914.40
1 set	rear bumper sensor.	S.Nett			$ 400.00
1 set	number plate	S.Nett			$ 80.00
	To putty & spray paint				$ 1,200.00
	To check front wiring & focus head lights				$ 30.00
	To check rear wiring & water leakage				$ 30.00
	To anti-rust				$ 80.00
	Labour Charges				$ 800.00
TG/VL	TOTAL				$ 12,534.40

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd