REF: NA2 | REF: FWD

ASSIGNMENT

Date:

Veh No: SKM 4084H Yr Regn: 13 AUG 2009

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA ISIS 1.8LXA cc 1794

Colour: BLACK A/C: Insured / Std / Nil / N/A

Sp Reading: N/A T/Radio: Insured / Std / Nil / N/A

Eng No:

C/No: ZNM10OOS9741

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Wheel: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or VIKING

Front		Rear	
R/Bal	3 mm	R/Bal	5
L/Bal	3 mm	L/Bal	5
DOA	11/9/2020	DOA	15/9/2020

Survey held at AH LIM MOTOR

Dos. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S REAR, interior burnt, car burnt.

The U/C / Chassis frame / Body structure affected due to car L/S

Insured: Excess:

Claim No:

Sum Insured:

Claim Amount:

Policy No:

Class of Vehicle: S2K

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% Val.: Yes or No

EA REV / REP. / 24 HRS

Vehicle IN / OUT

Person Contacted:

DATE	Time	Action / Instruction
		COE Rebate $35620
		Repair Limit $15K
		vehicle uneconomical to repair. Recommend total loss.

Surveyor Report: ☐ : Prelim. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format:

Lump Sum: 1.8 L XA