(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/ CT/20010025/Usf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 1Q1813D

at Workshop m/s Ethan Tampines.

of

Insured: GR9734D

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $99k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.B/ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS L1A 1967

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 1Q1813D Yr Regn: 1019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or GM/

Make: Isuzu FRR90 c.c 5193

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 30502 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JALFRR907K7000038

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : NIL / S/Rim / STD A/Rim or

Tyre Size: F: 225/90R 17.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/6 mm
D.O.A.	14/9/20	D.O.I.	2/11/20

Survey held at —

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 11k. have video
6/11/20	P/P $2900.93 confirmed with Jimmy C$ 4,971.50 Red - 63%

Date/Time, File Pass to? 1) 16/11/20 Typ.

Date/Time, File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.: ($ 2,900.93 P/P)