Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Steve (LKK)
22/09/20

Vehicle No. SJC3132Z KIA CERATO K3 1.6

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
2	Rear reinforcement bracker beam RH/LH @2*$99 ✓ BT		198.00	
1	Rear boot lid weatherstripe ✓ TN		81.00	
1	Rear spare tyre top cover board ✓ TN		135.00	
1	Rear boot lid lock regulator (Smart Buzzle) ✓ BR		54.00	
1	Headlamp LH ✓ BR		1890.00	
			2358.00	
			-10% -235.80	
			2122.20	
	SPECIAL NETT ITEMS			
	LABOUR			
		Total Parts	2122.20	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: