Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Steve (LKK)
22/09/20

Vehicle No. SJC3132Z KIA CERATO K3 1.6

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S$)		SURVEYOR'S ADJUSTMENT	
	PARTS (LIST ITEMS)					
2	Rear reinforcement bracker beam RH/LH @2*$99 ✓ BT			198.00		
1	Rear boot lid weatherstripe ✓ TN			81.00		
1	Rear spare tyre top cover board ✓ TN			135.00		
1	Rear boot lid lock regulator (Smart Buzzle) ✓ BR			54.00		
1	Headlamp LH ✓ BR			1890.00		
				2358.00		
			-10%	-235.80		
				2122.20		
	SPECIAL NETT ITEMS					
	LABOUR					
		Total Parts		2122.20		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: