PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0646/2020/NS
DATE	:	9-Sep-20
WIP	:	48271

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKP 5546 U

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

Motor Claims Dept
Tel: 6223 9433 - Fax: 6223 4190

OWNER'S NAME	:	MR SIM SHAO QUAN(SHEN SHAOQUAN)
ADDRESS	:	96B HENDERSON ROAD #38-72 SINGAPORE 152096
TELEPHONE	:	HP +65 97885225
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	5118238328
VEHICLE NO	:	**SLR 4765 M**
MODEL CODE	:	AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR	:	16/8/2017
ENGINE NO	:	CHZ 397933
CHASSIS NO	:	WAUZZZGA9JA001351
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	15-Sep-20
PLACE OF ACCIDENT	:	CLUB STREET LAMP POST NUMBER 10

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 4765 M

S/N	NATURE OF JOBS			ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRNSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	$	280.00	✓ ✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		$	1,200.00	800 ✓
3	TO RESPRAY REAR BUMPER.		$	1,000.00	800 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	$	192.00	✓ ✓
	TOTAL LABOUR CHARGES	:		**$ 2,672.00**	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 4765 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	REAR BUMPER Repair		$ 1,164.00	X
2	REAR BUMPER FIXING PARTS Prem		$ 76.00	X
3	REAR BUMPER SPOILER Prem		$ 281.00	X
4	REAR BUMPER TOWING EYE COVER Prem		$ 43.00	X
5	REAR LIGHT REFLECTOR - RH Not Nec.		$ 30.00	X
6	TAIL LIGHT		$ 1,306.00	✓
7	TAIL LIGHT TRIM Prem		$ 30.00	✓
8	REAR BUMPER CARRIER		$ 544.00	✓
9	REAR BUMPER HOLDING STRAP - LH / RH	2	$ 26.00	✓
10	REAR PARKING AID SENSOR - OUTER Incl		TBC	✓
11	REAR PARKING AID SEAL RING	4	$ 14.00	✓
12	REAR WHEEL COVER - LH / RH Prem	2	$ 336.00	✓ 336.00
13	SUNDRIES Not Nec.		$ 200.00	X
	TOTAL SPARE PARTS	:	**$ 4,050.00**	
	TOTAL LABOUR CHARGES	:	**$ 2,672.00**	
	GRAND TOTAL	:	**$ 6,722.00**	

ALL CHARGES ARE INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Adrian Ng
SURVEYED DATE	:	18/09/20
AUTHORISED DATE	:	
EXCESS COST	:	
LIABILITY	:	
REMARKS	:	Not Authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT