ASS. Filed By: GQ | REF: CS/CTI20010677/Gd3

ASSIGNMENT

From: Date:

Estimated Cost:

[OD] / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s GOLDBELL ENGINEERING

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess: $500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: $61K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / [REV] / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SBB 9955B Yr Regn: 30 Jan/2013

Type: [M.Car] / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA LEXUS GS250 c.c 2500

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 112516 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHBF1BL905005977 *

Gen. Cond: [Good] / Fair / Poor / Burnt

Steering: [Inorder] / Jammed / Leaked / Burnt or

Brake: [Inorder] / Jammed / Leaked / Burnt or

Modi : Nil / [S/Rim] / STD A/Rim or

Tyre Size: F: 275/30ZR19

R: 275/30ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.		D.O.I.	06-10-2020

Survey held at W/S 3:30pm

Des. of Damages: [Frt] / Rear / [O/S] / [N/S] / [U/C] / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE Rebate: $52816
	NET: $8184

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

[ ] : Preli. Report

[ ] : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Invs ($)

[ ] : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / LPO: