National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8585J

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	459.40	459.40
1	REAR BUMPER CENTER - BLACK	CRUSHED	451.25	451.25
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	RR BUMPER LWR CTR MOULDING	BROKEN	155.00	155.00
1	RR BUMPER SIDE UNDER CVR LH	BROKEN	108.00	108.00
1	REAR BUMPER SIDE BRKT LH	BROKEN	33.10	33.10
1	REAR BUMPER TOW COVER	NOT NECESSARY	5.40	-
1	TAILLAMP LH	CRACKED	870.40	870.40
1	REAR BLIND SPOT DEVICE LH	NOT NECESSARY	1,625.00	-
1	REAR FENDER SHIELD LH	NOT NECESSARY	73.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT DOOR LWR MOULDING LH	CUT	116.20	116.20
1	REAR DOOR LWR MOULDING LH	CUT	116.20	116.20
1	FRT FENDER BLUE - DRIVE LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-852.73	-471.63
			3,410.92	1,886.52
	NETT ITEMS			
1	REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
1	FRT DOOR COMFORTDELGRO LH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS STICKER LH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-33.50	-15.50
			301.50	139.50
	LABOUR			
	PANEL BEATING.		700.00	320.00
	SPRAY PAINT - FRT FENDER LH ETC.		1,250.00	1,000.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	100.00	-
	R/I REVERSE SENSOR.		120.00	30.00

Report Ref No. NS/INC20011040/Esd3s2

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	DIA/RESET BSD TO SPECS.	NOT NECESSARY	180.00	-
			2,390.00	1,380.00
	GRAND TOTAL		**6,102.42**	**3,406.02**
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			**3,406.02**

Report Ref No. NS/INC20011040/Esd3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser