LIM TAN MOTOR

ESTIMATE TO REPAIR

VEHICLE NO.	: SKA 3127 M
MAKE	: BMW
MODEL	: X6 3.0 A
YEAR	: 2010
CHASSIS NO	: WBAFG22070LL80464

SURVEYOR NAME	: LKK
DATE OF SURVEY	: 4-NOV
TIME OF SURVEY	: 2pm

DATE	: 25-Oct-20
DATE OF ACCIDENT	: 21-Oct-20
THIRD PARTY REF	SML 425 R
THIRD PARTY REF	AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To Putty & Spray Paint				$ 800.00
	Labour charges.				$ 300.00
TG/SO	TOTAL				$ 1,100.00
TG/VL	TOTAL				$ -

660l
100l

Not Authorised
Resurvey After Repair
3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co Reg No 199307277D GST Reg No M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

Scanned with CamScanner