Kt

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: SUZUKI SWIFT SPORT 1.6
Engine/Chassis No.: JSAEZC31S00200938
Date of accident:
Damaged area: Front

Date: 04/11/2020
Claim Type: TP
VRN: SDQ5151C

Not authorised
Lilsp @ 2450/h
Reserve After Paint



3days

List items

S/N	Parts description		QTY	UNIT PRICE	AMOUNT	
1	FRONT BUMPER (~~SPORTS~~) 555.10 Bu/Rd		1	$ 1,602.00	$ 1,602.00	✓
2	FRONT BUMPER SIDE RETAINER	Sn	2	$ 65.00	$ 130.00	X
3	FRONT BUMPER LOWER GRILLE	Sn	1	$ 256.00	$ 256.00	X
4	SUPPORT PANEL	R	1	$ 542.00	$ 542.00	X
5	FRONT GRILLE TOP BRACKET	R	1	$ 39.00	$ 39.00	X
6	FRONT GRILLE TOP GARNISH	Sn	1	$ 87.00	$ 87.00	X
7	FRONT GRILLE LOGO	Wa	1	$ 69.00	$ 69.00	✓
8	FRONT GRILLE	CM	1	$ 461.00	$ 461.00	✓ 250SN
				Subtotal	$ 3,186.00	
				List discount	15.00%	
				Total	$ 2,708.10	

Special nett items

No.	Parts description		QTY	UNIT PRICE	AMOUNT	
1	FRONT BUMPER CLIP	Nn	10	$ 5.50	$ 55.00	✓
2	FRONT NUMBER PLATE WITH FRAME	Sn	1	$ 55.00	$ 55.00	X
3	GRILLE LOGO CLIP	Nn	2	$ 5.50	$ 11.00	X
4	BONNET INSULATOR CLIPS	Nn	8	$ 5.50	$ 44.00	X
5	CARBON FIBRE BONNET	CM	1	$ 2,500.00	$ 2,500.00	✓ 1500SN
6	SUNDRIES		1	$ 50.00	$ 50.00	
				Total	$ 2,715.00	

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	4	$ 800.00	350/
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	$ 50.00	10/
3	Supply spray paint material and necessary items to respray affected area / panel.	3	$ 600.00	400/
4	To rust proof all affected portions after repair.	0.5	$ Nn 100.00	X
		Total labour	$ 1,550.00	
		Estimate Grand Total	$ 6,973.10	

- To resurvey
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: