COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE NTUC - CP/P LKK

Date: 01.12.2020
Time: 12:57:30
Page: 1/2 B

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305436447
REGN NO	:	SHD4811J
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G3)
DATE OF REGN	:	16.01.2020
DATE/TIME IN	:	28.11.2020 08:40
ACCIDENT DATE	:	27.11.2020

	JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
PART REQUISITION							
0001 04-01-0104-2282-G	REAR BUMPER	1		459.40	20.00	367.52	Rp
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1		451.25	20.00	361.00	x un.
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10	L	22.00	20.00	17.60	rel
0004 09-01-9999-0068-A	REVERSE SENSOR	1		180.00	10.00	162.00	x nn
0005 04-01-0104-1150-A	REAR BUMPER MAT	1		50.00		50.00	x un 17.60
					SUB-TOTAL	: 958.12	
JOB NATURE							
0000 PB	PANEL BEATING					350.00	320
0001 SP	SPRAYPAINT CHARGE					250.00	200
0002 L	R/I REVERSE SENSOR					120.00	30 550
					SUB-TOTAL	: 720.00	

Taufik 9741 5449
- WP 01/12/20 c 4pm
P/P Resume after repair
2 days
taufik@lkkauto.com

$567.60
2 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: