C33/ABM 20014647/ G9d3 . 9

(~2022)

Rec. By: Gel. PRS

ASSIGNMENT

Date:

Estimated Cost:

O / TP / WS / TP RES / OD RES / EVA / INV / MV (OD circled)

Inspect Vehicle No:

Workshop m/s: Toh Motor

Insured:

Policy No.

Claims No.: 50M02XPT

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S (O/S circled)

Val. or Market Value: $3000

OAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FU8075A Regn: 17 Apr 2002

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (M.Cycle circled)

Make: Yamaha RXZ c.c 133

Colour: red

A/C: Insured / Std / NI / NA

Sp Reading: 9912.6

T/Radio: Insured / Std / NI / NA

Eng/No

C/No: 8MC 264234

Gen. Cond: Good / Fair / Poor / Burnt (Good circled)

Steering: Inorder / Jammed / Leaked / Burnt or (Inorder circled)

Brake: Inorder / Jammed / Leaked / Burnt or (Inorder circled)

Modi: Nil / S/Rim / STD A/Rim or (Nil circled)

Tyre Size: F: 80/80 -18

R: 80/80 -18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or (DUN circled)

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	29-12-20 @3:30pm

Survey held at: W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or (Frt, O/S circled)

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	006 : 349
	$2000 - $3000
30/12/20 @ 11:34am	verised to Yvonne Ang via Smart Claims.
	submit PRS.

Date/Time. File Pass to: ☐ : Preli. Report

1) 30/12 finish ☐ : Final Report

Date/Time. File Return to:

2)

Smart Claim

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (S$
☐ Interview (S$
☐
☐

Survey Fee:

Transportation:

Photos

Other