CS3/CTI21001278/Gqf3

6d
PPS

CTI

ASSIGNMENT

Date

timated Cost:

) / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s Garage B

sured:

licy No. DMCVSNW00038522001

aims No SNM21D200451C02

im Insured: Excess:

(Client's Record)

ake of Veh:

(Policy Condition)

emark: The veh had commenced its repair at the time of inspection.

N/S	O/S

al. or Market Value: $73K

DAC Accident Rport Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

st. Repairs 5 days Res.: Yes or No

um Sum: % 3 Val : Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date Person Contacted

Vehicle No. SKX6866Y 1st Regd 23 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make Toyota Harrier 2.0 cc 1986

Colour Silver A/C Insured / Std / NI / NA

Sp Reading 83665 T/Radio Insured / Std / NI / NA

Eng/No.

C/No: ZSU6000-625195

Gen Cond: Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Modi Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal	6 mm	R/Bal.	6 mm
L/Bal	6 mm	L/Bal	6 mm
D.O.A		D.O.I.	27-01-21

Survey held at W/S 12pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$4000 – $5000
	Submit PRS.

Date/Time. File Pass to: ☐ : Preli. Report

) 28/01 Typist ☐ : Final Report

Date/Time. File Return to:

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ Site Insp. ($

☐ Interview ($

MER-PRS