COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHC8302R** **01/02/21**

MAKE :

MODEL **IONIQ G3** **CHIANG/ AIG**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT RH ROCKER GRANISH17 / Cut			$290.00
1	FRT RH DOOR ~~Repair~~ / BT			$1,797.20
1	FRT DOOR KEY LOCK SET / D.3			$353.50
1	FRT DOOR INNER LOCK X NN			$385.60
1	FRT DOOR OUTER HANDLE / Dis			$234.80
1	FRT DOOR PROTECTOR / Set			$186.20
1	RR DOOR PROTECTOR /			$166.20
1	FRT RH DOOR X Repeat.			$1,797.20
	20.00%			**$5,210.70**
	DISCOUNTED TOTAL			$1,042.14
				$4,168.56
1	FRT DOOR COMFORTDEGRO STICKER / Spec			**$75.00**
1	REAR DOOR COMFORT APP /			**$80.00**
				$155.00
	Labour Charge			
	Panel Beating			$700.00 350
	Spray Painting			$800.00 750
	Tranfer door part to new door.			$60.00 /
	TOTAL LABOUR			$1,560.00
	ESTIMATE TOTAL			$5,883.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3Days.
P/P
before print photos.
Gene Qi
01/2/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: