Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 29 Mar 2021

Preliminary Advice

Insured Vehicle No	: SMJ7538M		
TP Vehicle No	: SLX5071T	Accident Date	: 05/02/2021
Make	: MERCEDES-BENZ GLA180 URBAN (R18 LED)	Assignment Date	: 08/02/2021
Date of Inspection	: 17/02/2021	Est. Duration of Repair	: 5
Inspection At	: SMARTONE AUTO PTE LTD (HQ) 8 KAKI BUKIT AVENUE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	21,877.10
Revised Amount	:S$	9,744.70
Check Items (Estimated)	:S$	0.00
Total	:S$	9,744.70
Lump Sum Repair	:S$	7,800.00

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :